

N64-17603

255p.

70

SECOND QUARTERLY

CODE-1

CR-53221

REPORT

[Oct. 1963 - 26 Jan. 1964]

JANUARY 31, 1964

N64-17603

FACILITY FORM 802

(ACCESSION NUMBER)

(THRU)

255

1

(PAGE)

(CODE)

CR-53221

D6

(NASA CR OR TMX OR AD NUMBER)

(CATEGORY)

BRUSHLESS ROTATING ELECTRICAL GENERATORS
FOR SPACE AUXILIARY POWER SYSTEMS

(NASA CONTRACT NO. NAS 3-2783)

(NASA CR-53221)

prepared for

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION

by

J. N. Ellis and F. A. Collins

31 Jan. 1964

255p on file

TECHNICAL MANAGEMENT

HOWARD A. SHUMAKER

NASA-LEWIS RESEARCH CENTER
SPACE POWER SYSTEM DIVISION
SOLAR AND CHEMICAL POWER BRANCH

OTS:PRICE

XEROX

MICROFILM

\$ 16.50
\$ 2.85

1382043

LEAR SIEGLER, INC.



POWER EQUIPMENT DIVISION

CLEVELAND 1, OHIO

ABSTRACT

This report contains a design calculation procedure and a Fortran II computer program for synchronous, wound-pole, salient-pole generators.

In addition, it contains the design calculation procedure for Lundell generators.

Losses in solid pole faces and the design limits imposed by them are discussed.

Lundell generators have limits of stator length to rotor diameter that cannot be profitably exceeded. These are discussed.

A brief discussion of the motor starting characteristics of salient pole generators is included.

TABLE OF CONTENTS

TABLE OF CONTENTS

| | <u>Page</u> |
|--|-------------|
| Introduction and Summary | 1 |
| Design of Salient-Pole, Wound Pole Synchronous Generator | 2 |
| Design of Two-Coil Lundell Generator | 129 |
| Pole Face Losses in Solid Pole Generators | 190 |
| Using Synchronous Generators As Motors | 218 |
| The Physical Dimensions of Lundell Type Generators | 229 |

INTRODUCTION AND SUMMARY

Introduction

This report is submitted by The Power Equipment Division of Lear Siegler Corporation as the second part of a study of brushless rotating electrical generators. The work was accomplished during the period October 26 to January 26.

Summary

Purpose and Objectives

The objective of this study is a report that will help to select the proper brushless generator for a specific application and provide a computer program to calculate the performance of the selected generator design.

To provide a basis for properly evaluating the different generator types, design calculation procedures and computer programs are being provided for those that appear most suitable. From these programs parametric curves of output vs. size, weight and speed as well as efficiency can be readily obtained.

The final reports will be two topical reports:

1. General Selection Criteria and Mechanical Analysis of all Generator Types Studied.
2. Electrical Calculations and Evaluation of all generator types studied.

In the first quarterly report, a statement was made to the effect that each succeeding report would contain all material contained in preceding reports. This has been changed and now only the final reports will contain all of the previously published reports. When Bell programs are rewritten in Fortran, only the Fortran programs will be included in the final report.

WOUND-POLE, SALIENT-POLE GENERATOR

THE WOUND-POLE, SALIENT-POLE, A. C. GENERATOR

The salient-pole, synchronous generator with wound poles is the standard generator of the electrical industry. It has the highest electrical power output per pound per rpm of any practical electrical generator presently known. Because of its wide spread use and its superiority, all other types of electrical generators are compared to the wound-pole, salient-pole synchronous generator.

It is used on both aircraft and utility systems almost to the exclusion of any other types except non-salient pole, wound rotor, generators (or turbine generators) which are used with 1800 rpm and 3600 rpm steam turbines in central station generating plants.

In addition to its use as an electrical generator, the salient-pole, wound-pole, machine makes the best synchronous motor known. The pole heads can be designed with cage windings so that the machine can start a substantial load as an induction motor. The cage windings can be made double to give good starting characteristics and good pull-in characteristics.

Within its usable range, the wound-pole synchronous generator has no equal, but its range of usefulness is limited. Its maximum rotor peripheral speed is low because of the field windings supported by the poles and the high stresses resulting from the centrifugal loads. Its output frequency is low because the possible number of poles is restricted by electrical and mechanical limits due to the field windings, pole construction and the need for having at least one slot/phase/pole in the stator. Its maximum operating temperature is about 600° F for the copper and insulation on the rotor and 350° F for the rotating (silicon) rectifiers.

These thermal limits, plus the silicon rectifiers' susceptibility to radiation damage, have forced the need for other more rugged types of generators all of which are heavier, on a KVA/revolution basis, than the old standby wound-pole, salient-pole machine.

It is well to remember that within its application range, no other type of a-c generator can compare with the wound-pole, salient-pole machine and it should be used whenever feasible.




Photo 6

ROTATING RECTIFIER GEN.

The Wound Pole, Salient Pole A.C. Generator section of the First Quarterly Report has been reassembled and rewritten for this Second Quarterly Report. The design manual and equations are now presented as one document. The computer program has been rewritten in the Fortran computer language using the fixed decimal system on the input and output sheets. The complete package is called "The Salient Pole Computer Design Manual".

This Computer Design Manual in its entirety contains the following:

1. A numbered series of definitions and equations forming the body of the design calculations.
2. A list of numbered symbols.
3. A collection of tables, graphs and figures that are necessary in preparing an input sheet.
4. Standard magnetization curves.
5. An input and output computer design sheet.
6. A complete list of Fortran symbols.
7. A complete list of Fortran equations.

Design Procedure

This computer program is an analysis procedure. In an analysis procedure, all of the machine dimensions and winding specifications are given in addition to the rating. With all of this information given, the computer calculates the performance of the machine.

A generator design starts with the input sheet. All of the information that has been gathered on the generator in question is recorded on the input sheet. The inputs listed on the input sheet follow the sequence of the design manual calculations sequentially except for a few isolated cases. Each input is identified in three ways: (1) by a symbol, (2) by an explanation of each symbol, and (3)

by an identification number which is bracketed in parenthesis. This identification number or item number shows the location of the particular input in the design manual. At each location in the design manual, a complete explanation is given for each symbol in question along with equation^s where they apply.

For example, given on the input sheet is (4) E_{PH} phase volts. If there is any question by the designers as to just what is meant by phase volts or how is it calculated, he need only to look up item (4) in the design manual. Item (4) gives the following explanation:

For three phase delta connected generators

$$E_{PH} = \frac{(\text{Line Volts})}{\sqrt{3}} = \frac{(3)}{\sqrt{3}}$$

For three phase wye connected generators

$$E_{PH} = (\text{Line Volts}) = (3)$$

Each item, as shown in Item 4 above, has 3 parts:

1. A word definition explaining the item,
2. An equation using symbols,
3. An equation using the location for each symbol
 - a. When a number in an equation is bracketed by parenthesis such as (3) in Item 4, it has no numerical value. It represents the location of the symbol that is used in the equivalent equation
 - b. When a number such as $\sqrt{3}$ in Item 4 is not bracketed by parenthesis, then it is a real number and must be used accordingly.

A few of the items on the input sheet can be either an input or an output. This is useful where the designer wants better control of the design. By inserting an adjusted number as an input, it may be possible for the designer to simulate an actual known condition rather than accept the standard calculated answer.

When the designer is satisfied that the existing or standard calculation satisfies his condition, then he need only to insert a zero (0), and the computer will do the calculating.

A minimum number of rules must be followed in order to make a computer design -

1. Fill out input sheet completely.
2. All whole numbers and zeros must be followed by a decimal point. For example, if the number that is to be used on the input is either 1, 2, or 0, they must be inserted as 1., 2., or 0. . All decimal numbers are accepted as is. That is, 1.4 should be entered as 1.4.
3. When a question arises about a particular input, refer back to the location per the item number for a detailed explanation.
4. When a particular magnetization curve is to be used, the proper code number should be used as an input if the curve is available on "card decks". The code number can be any number that is mutually agreed on by the designers and the computer operators. The code simply tells the operator which curve to use.


When the curve does not exist on a "card deck", then the designer must submit on a separate sheet of paper, 29 points from the curve that is to be used. These points are the ampere turns per inch for each 5 units on the density scale, where the density scale is in Kilolines per in². Start the first reading at 0 density.

Output Sheet


The output sheet is set up for the computer to type out the answers directly in the spaces provided. The space is set up to accept 5 places to the left and right of the decimal point. Single spacing is used on the vertical and regular type spacing on the horizontal

Each item on the output sheet can be checked out by referring back to the item number in the design manual in the same manner as outlined above for the input data.


(a) Open Slots



(b) Constant Slot Width



(c) Constant Tooth Width



(d) Round Slots




FIG 1

TABLE-1

CHORD FACTORS K₂ FOR HARMONICS

DIFFERENT PITCHES

| No. | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50 | 51 | 52 | 53 | 54 | 55 | 56 | 57 | 58 | 59 | 60 | 61 | 62 | 63 | 64 | 65 | 66 | 67 | 68 | 69 | 70 | 71 | 72 | 73 | 74 | 75 | 76 | 77 | 78 | 79 | 80 | 81 | 82 | 83 | 84 | 85 | 86 | 87 | 88 | 89 | 90 | 91 | 92 | 93 | 94 | 95 | 96 | 97 | 98 | 99 | 100 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-----|-----|---|---|---|---|---|---|---|---|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|-----|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|
| 1 | 3/3 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

TABLE-2
 -VALUES OF K_{dn} FOR INTEGRAL SLOT 3 ϕ WINDINGS₁₀


| n | K_{dn} - HARMONIC DISTRIBUTION FACTORS | | | | | | | | | |
|------|--|-------|-------|-------|-------|-------|-------|-------|-------|----------|
| $q=$ | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | ∞ |
| 1 | .966 | .960 | .958 | .957 | .957 | .957 | .956 | .955 | .955 | .955 |
| 3 | .707 | .667 | .654 | .646 | .644 | .642 | .641 | .640 | .639 | .636 |
| 5 | .259 | .217 | .205 | .200 | .197 | .195 | .194 | .194 | .193 | .191 |
| 7 | -.259 | -.177 | -.158 | -.149 | -.145 | -.143 | -.141 | -.140 | -.140 | -.136 |
| 9 | -.707 | -.333 | -.270 | -.247 | -.236 | -.229 | -.225 | -.222 | -.220 | -.212 |
| 11 | -.966 | -.177 | -.126 | -.110 | -.102 | -.097 | -.095 | -.093 | -.092 | -.087 |
| 13 | -.966 | .217 | .126 | .102 | .092 | .086 | .083 | .081 | .079 | .073 |
| 15 | -.707 | .667 | .270 | .200 | .172 | .158 | .150 | .145 | .141 | .127 |
| 17 | -.259 | .960 | .158 | .102 | .087 | .075 | .070 | .066 | .064 | .056 |
| 19 | .259 | .960 | -.205 | -.110 | -.084 | -.072 | -.066 | -.062 | -.060 | -.059 |
| 21 | .707 | .667 | -.654 | -.247 | -.172 | -.143 | -.127 | -.118 | -.112 | -.091 |
| 23 | .966 | .217 | -.958 | -.149 | -.092 | -.072 | -.063 | -.057 | -.054 | -.041 |
| 25 | .966 | -.177 | -.958 | .200 | .102 | .075 | .063 | .056 | .052 | .038 |
| 27 | .707 | -.333 | -.654 | .646 | .236 | .158 | .127 | .111 | .101 | .071 |
| 29 | .259 | -.177 | -.205 | .957 | .145 | .086 | .066 | .056 | .050 | .033 |
| 31 | -.259 | .217 | .158 | .957 | -.197 | -.097 | -.070 | -.057 | -.050 | -.031 |

| | | | | | | | | | | |
|----|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| 33 | -.709 | .667 | .270 | .646 | -.644 | -.229 | -.150 | -.118 | -.101 | -.058 |
| 35 | -.966 | .960 | .126 | .200 | -.957 | -.143 | -.083 | -.062 | -.052 | -.027 |
| 37 | -.966 | .960 | -.126 | -.149 | -.957 | .195 | .095 | .066 | .054 | .026 |
| 39 | -.707 | .667 | -.270 | -.247 | -.644 | .642 | .225 | .145 | .112 | .049 |
| 41 | -.259 | .217 | -.158 | -.110 | -.197 | .957 | .141 | .081 | -.060 | .023 |
| 43 | .259 | -.177 | .205 | .102 | .145 | .957 | -.194 | -.093 | -.064 | -.022 |
| 45 | .707 | -.333 | .654 | .200 | .236 | .642 | -.641 | -.222 | -.141 | -.042 |
| 47 | .966 | -.177 | .958 | .102 | .102 | .195 | -.956 | -.140 | -.079 | -.020 |
| 49 | .966 | .217 | .958 | -.110 | -.092 | -.143 | -.956 | .194 | .092 | .019 |
| 51 | .707 | .667 | .654 | -.247 | -.172 | -.229 | -.641 | .640 | .220 | .038 |
| 53 | .259 | .960 | .205 | -.149 | -.084 | -.097 | -.194 | .955 | .140 | .018 |
| 55 | -.259 | .960 | -.158 | .200 | .084 | .086 | .141 | .955 | -.193 | -.017 |
| 57 | -.707 | .667 | -.270 | .646 | .172 | .158 | .225 | .640 | -.639 | -.033 |
| 59 | -.966 | .217 | -.126 | .957 | .092 | .075 | .095 | .194 | -.955 | -.016 |
| 61 | -.966 | -.177 | .126 | .957 | -.102 | -.072 | -.083 | -.140 | -.955 | .016 |
| 63 | -.707 | -.333 | .270 | .646 | -.236 | -.143 | -.150 | -.222 | -.639 | .030 |
| 65 | -.259 | -.177 | .158 | .200 | -.145 | -.072 | -.070 | -.093 | -.193 | .015 |

TABLE-3
ROUND COPPER WIRE

| SIZE AWG | BARE DIAMETER | AREA □" | $\frac{R}{1000'}$ @ 25°C | SINGLE FORMVAR | HEAVY FORMVAR | SINGLE GLASS FORMVAR | BARE WT. #/1000' | SINGLE GLASS SILICONE | DOUBLE GLASS SILICONE |
|-------------|------------------|------------|-----------------------------|-------------------|------------------|-------------------------|---------------------|--------------------------|--------------------------|
| 36 | .0050 | .0000196 | 424 | .0056 | .0060 | | .0757 | | |
| 35 | .0056 | .0000246 | 338 | .0062 | .0066 | | .0949 | | |
| 34 | .0063 | .0000312 | 266 | .0070 | .0074 | | .1201 | | |
| 33 | .0071 | .0000396 | 210 | .0079 | .0084 | | .1526 | | |
| 32 | .0080 | .0000503 | 165 | .0088 | .0094 | .0121 | .1937 | | |
| 31 | .0089 | .0000622 | 134 | .0097 | .0104 | .0130 | .2398 | | |
| 30 | .0100 | .0000785 | 106 | .0108 | .0116 | .0142 | .3025 | .0132 | .0152 |
| 29 | .0113 | .000100 | 83.1 | .0122 | .0130 | .0156 | .3866 | .0145 | .0165 |
| 28 | .0126 | .000125 | 66.4 | .0135 | .0144 | .0169 | .4806 | .0158 | .0178 |
| 27 | .0142 | .000158 | 52.6 | .0152 | .0161 | .0186 | .6101 | .0174 | .0194 |
| 26 | .0159 | .000199 | 41.7 | .0169 | .0179 | .0203 | .7650 | .0191 | .0211 |
| 25 | .0179 | .000252 | 33.0 | .0190 | .0200 | .0224 | .970 | .0211 | .0231 |
| 24 | .0201 | .000317 | 26.2 | .0213 | .0223 | .0263 | 1.223 | .0251 | .0276 |
| 23 | .0226 | .000401 | 20.7 | .0238 | .0249 | .0289 | 1.546 | .0276 | .0301 |
| 22 | .0254 | .000507 | 16.4 | .0266 | .0277 | .0317 | 1.937 | .0303 | .0328 |
| 21 | .0285 | .000638 | 13.0 | .0299 | .0310 | .0349 | 2.459 | .0335 | .0360 |
| 20 | .0320 | .000804 | 10.3 | .0334 | .0346 | .0384 | 3.099 | .0370 | .0395 |
| 19 | .0360 | .00102 | 8.14 | .0374 | .0386 | .0424 | 3.900 | .0409 | .0434 |
| 18 | .0403 | .00126 | 6.59 | .0418 | .0431 | .0468 | 4.914 | .0453 | .0478 |
| 17 | .0453 | .00159 | 5.22 | .0469 | .0482 | .0519 | 6.213 | .0503 | .0528 |
| 16 | .0508 | .00204 | 4.07 | .0524 | .0538 | .0575 | 7.812 | .0558 | .0583 |
| 15 | .0571 | .00255 | 3.26 | .0588 | .0602 | .0639 | 9.87 | .0621 | .0646 |
| 14 | .0641 | .00322 | 2.58 | .0659 | .0673 | .0710 | 12.44 | .0691 | .0716 |
| 13 | .072 | .00407 | 2.04 | .0738 | .0753 | .0789 | 15.69 | .0770 | .0795 |
| 12 | .0808 | .00515 | 1.61 | .0827 | .0842 | .0877 | 19.76 | .0858 | .0883 |
| 11 | .0907 | .00650 | 1.28 | .0927 | .0942 | .0977 | 24.90 | .0957 | .0982 |
| 10 | .102 | .00817 | 1.02 | .1039 | .1055 | .1089 | 31.43 | .1069 | .1094 |
| 9 | .114 | .0102 | .814 | .1165 | .1181 | .1225 | 39.62 | .1204 | .1254 |
| 8 | .129 | .0131 | .634 | .1306 | .1323 | .1366 | 49.98 | .1345 | .1395 |
| 7 | .144 | .0163 | .510 | .1465 | .1482 | .1525 | 63.03 | .1503 | .1553 |
| 6 | .162 | .0206 | .403 | .1643 | .1661 | .1703 | 79.44 | .1680 | .1730 |
| 5 | .182 | .0260 | .319 | .1842 | .1861 | .1902 | 100.2 | .1879 | .1929 |
| 4 | .204 | .0327 | .254 | | | | 126.3 | .2103 | .2153 |
| 3 | .229 | .0412 | .202 | | | | 159.3 | | |
| 2 | .258 | .0523 | .159 | | | | 200.9 | | |
| 0 | .325 | .0830 | .100 | | | | | | |
| 2/0 | .365 | .105 | .0791 | | | | | | |
| 4/0 | .460 | .166 | .0500 | | | | | | |

CURVE-1




CURVE-2

13

From Kennard and Spooner "Surface Iron Losses with Respect to Laminated Materials", Trans. AIEE, Vol. 43, 1924, pp 262-281.


DRAWN BY J.A.T.

REFER TO ITEM (150) IN SALIENT POLE DESIGN MANUAL FOR SAMPLE USE OF THIS CURVE




CURVE-3

FROM E. J. DOLLARDS "LOAD LOSSES IN SALIENT POLE
SYNCHRONOUS MACHINES" A IEE TRANS. VOL. 54
1935 PP 1392-1396



CURVE-4



CURVE-7 NO LOAD DAMPER LOSS

17

$$D.L. = \frac{1.266 P \tau_b l_b \rho}{10^5 a_b} \left[\tau_s B_g K_p K_g \right]^2 \left[\frac{K_{f1} / (K_{W1} \lambda_s)}{(2\lambda_s + \frac{\lambda_g}{K_{\phi 1}})} + \frac{K_{f2} / (K_{W2} \lambda_s)}{(2\lambda_s + \frac{\lambda_g}{K_{\phi 2}})} \right]^2$$

= LOSS IN KW

$$\lambda_s = \frac{\tau_s}{b_r} + \lambda_e + \lambda_c$$

a_b = BAR AREA IN SQ IN.

τ_b = BARS/POLE

P = NO. POLES

l_b = LENGTH BAR IN

$$\lambda_g = \frac{\tau_b}{K_g g} = \frac{\tau_b}{g'}$$

K_g = CARTER'S COEFFICIENT (TOTAL)

$K_p = f_n(b_s/g)$, CURVE (a) ($b_s = b_o$ for partially closed slots)

K_{f1} AND $K_{f2} = f_n(\tau_s/\rho)$ CURVE (b)

ρ = DAMPER BAR RESISTIVITY (MICROHMS PER CU. IN.)

K_{W1} AND $K_{W2} = f_n(b_s/\tau_s)$, CURVE (c1) AND (c2)

$K_{\phi 1}$ AND $K_{\phi 2} = f_n(\tau_b/\tau_s)$, CURVE (d1) AND (d2)


$\lambda_e = f_n(b_r/g K_g)$ CURVE (e)

B_g IS IN KILOLINES PER SQ INCH

$\lambda_c = \frac{\tau_s}{K_{f1}}$ (FOR ROUND OR SQ BARS)

$\lambda_c = \frac{h_b}{3 b_b K_{f1}}$ (FOR RECT. BARS)


b_s/g (open slots) & b_o/g (partially closed slots)



NOTE:


ALSCIESA IS b_1/g_1 TO SELECT λ_{c1}
 IS b_2/g_2 TO SELECT K_{W1} AND K_{W2} ($b_2 = b_0$ FOR partially closed slots)
 AND IS b_3/g_3 TO SELECT K_{P1} AND K_{P2}
 FOR VALUES b_0/g_0 GREATER
 THAN 1.0, USE 2 b_0/g_0 's

CURVE-8




b_1/g_1 AND b_2/g_2
 b_3/g_3 AND b_0/g_0


19




CURVE 10




CURVE 11




CURVE 12



USS DYNAMO — 26 GAGE
Hot Rolled Sheets
DC MAGNETIZATION



Test Conditions: Half lengthwise and half crosswise sample tested in Fahy Permeameter.



Test Conditions: Half lengthwise and half crosswise sample tested in Fahy Permeameter.

SALIENT-POLE WOUND-POLE SYMBOLS

| <u>Calculation Location</u> | <u>Symbol</u> | <u>Explanation</u> |
|---------------------------------|---------------|--|
| (78) | A | Ampere conductors per inch of stator periphery |
| (46) | a_c | Strand area (stator) |
| (89) | a_{cf} | Field conductor area |
| (85) | a_p | Pole area |
| (20) | B | Density |
| (128) | B_c | Core density |
| (125) | B_g | Gap density |
| (140) | B_p | Pole density no load |
| (163) | B_{p1} | Pole density full load |
| (127) | B_T | Tooth density |
| (89) | b_{bo} | Width of slot opening (damper) |
| (89) | b_{b1} | Width of rectangular slot (damper) |
| (76) | b_h | Pole head width |
| (22) | b_o | Width of slot opening (stator) |
| (76) | b_p | Pole body width |
| (22) | b_s | Stator slot dimension per Fig. 1 |
| (15) | b_v | Width of duct |
| (22) | b_1 | Stator slot dimensions per Fig. 1 |
| (22) | b_2 | |
| (22) | b_3 | |

| Calculation Location | Symbol | Explanation |
|-------------------------|---------------|--------------------------------|
| (74) | C_m | Demagnetizing factor |
| (73) | C_p | Average/maximum field form |
| (75) | C_q | Cross magnetization factor |
| (72) | C_w | Winding constant |
| (71) | C_1 | Ratio max. to fund. |
| (32) | c | Parallel circuits |
| (12) | D | Stator outside diameter |
| (11) | d | Stator inside diameter |
| (35) | d_b | Diameter of bender pin |
| (11a) | d_r | Rotor outside diameter |
| (3) | E | Line volts |
| (145) | E_F | Field volts no load |
| (168) | E_{FFL} | Field volts full load |
| (4) | E_{PH} | Phase volts |
| (55) | $E_{F_{top}}$ | Eddy factor top |
| (56) | $E_{F_{bot}}$ | Eddy factor bottom |
| (130) | F_c | Stator core ampere turns |
| (131) | F_g | Air gap ampere turns |
| (165) | F_{FL} | Total ampere turns full load |
| (142) | F_{NL} | Total ampere turns no load |
| (141) | F_p | Pole ampere turns at no load |
| (164) | F_{PL} | Pole ampere turns at full load |
| (136) | F_{sc} | Short circuit ampere turns |

| Calculation Location | Symbol | Explanation |
|----------------------|-----------|--|
| (129) | F_t | Stator tooth ampere turns |
| (147) | F&W | Friction and windage |
| (5a) | f | Frequency |
| (69) | g_e | Effective air gap |
| (59a) | g_{max} | Maximum air gap |
| (22) | h_o | Stator slot dimension |
| (22) | h_1 | |
| (22) | h_2 | |
| (22) | h_3 | |
| (22) | h_s | |
| (22) | h_t | |
| (22) | h_w | |
| (89) | h_{bo} | Height of slot opening |
| (89) | h_{b1} | Rectangular bar thickness |
| (24) | h_c | Depth below slot |
| (76) | h_f | Pole head body |
| (76) | h_h | Pole head height |
| (37) | h_{st} | Uninsulated strand height |
| (38) | h'_{st} | Distance between center line of strand |
| (8) | I_{PH} | Phase current |
| (166) | I_{FFL} | Field amperes at full load |

| Calculation Location | Symbol | Explanation |
|-------------------------|-------------|---------------------------------|
| (143) | I_{FNL} | Field amperes at no load |
| (146) | $I^2 R_R$ | Rotor loss |
| (158) | $I^2 R_S$ | Stator copper loss |
| (9a) | K_c | Adjustment factor |
| (43) | K_d | Distribution factor |
| (18) | K_i | Stacking factor |
| (44) | K_p | Pitch factor |
| (67) | K_s | Carter coefficient |
| (42) | K_{SK} | Skew factor |
| (2) | KVA | Machine rating |
| (151) | K_1 | Pole face loss factor |
| (19) | k | Watts per lb. |
| (48) | L_E | End extension one turn |
| (113) | L_F | Field self inductance |
| (13) | ℓ | Gross core length |
| (93) | ℓ_b | Damper bar length |
| (136) | ℓ_{e2} | Coil extension straight portion |
| (76) | ℓ_n | Pole head length |
| (76) | ℓ_p | Pole body length |
| (17) | ℓ_s | Solid core length |
| (49) | ℓ_t | 1/2 mean turn |
| (100) | ℓ_{tr} | Mean length of field turns |
| (5) | m | Number of phases |

| Calculation Location | Symbol | Explanation |
|-------------------------|-------------------------|----------------------------|
| (34) | N_{st} | Strands per conductor |
| (92) | n_b | Number of damper bars |
| (45) | n_e | Effective conductors |
| (99) | n_p | Number of field turns |
| (30) | n_s | Conductor per slot |
| (14) | n_v | Number of ducts |
| (9) | P. F. | Power factor |
| (6) | p | Number of poles |
| (23) | Q | Number of slots |
| (53) | $R_{ph} \text{ (cold)}$ | Stator resistance at 20°C |
| (54) | $R_{ph} \text{ (hot)}$ | Stator resistance at X°C |
| (107) | $R_F \text{ (cold)}$ | Field resistance at 20°C |
| (108) | $R_f \text{ (hot)}$ | Field resistance at X°C |
| (137) | SCR | Short circuit ratio |
| (47) | s_s | Stator current density |
| (144) | s_f | Field current density |
| (133) | T_a | Armature time constant |
| (134) | T_d' | Transient time constant |
| (135) | T_d'' | Subtransient time constant |
| (132) | T_{do} | Open circuit time constant |
| (149) | W_c | Stator core loss |
| (172) | W_{DFL} | Damper loss at full load |

| <u>Calculation Location</u> | <u>Symbol</u> | <u>Explanation</u> |
|---------------------------------|-----------------|--|
| (157) | W_{DNL} | Damper loss at no load |
| (171) | W_{PFL} | Pole face losses at full load |
| (150) | W_{PNL} | Pole face loss at no load |
| (170) | W_{TFL} | Stator tooth loss at full load |
| (148) | W_{TNL} | Stator tooth loss at no load |
| (98a) | V_r | Peripheral speed of rotor |
| (79) | X | Reactance factor |
| (81) | X_{ad} | Reactance direct axis |
| (82) | X_{aq} | Reactance quadrature axis |
| (83) | X_d | Synchronous reactance direct axis |
| (119) | X_d' | Stator transient reactance |
| (120) | X_d'' | Subtransient reactance direct axis |
| (115) | X_{Dd} | Leakage reactance direct axis |
| (117) | X_{Dq} | Leakage reactance quadrature axis |
| (118) | X_{du}' | Unsaturated transient reactance |
| (112) | X_f | Field leakage reactance |
| (80) | X_ℓ | Leakage |
| (84) | X_q | Synchronous reactance quadrature axis |
| (121) | X_q'' | Subtransient reactance quadrature axis |
| (123) | X_0 | Zero sequence reactance |
| (122) | X_2 | Negative sequence reactance |
| (96) | $X_D^{\circ C}$ | Expected damper bar $^{\circ C}$ |

| Calculation Location | Symbol | Explanation |
|-------------------------|-----------------------|--|
| (103) | $X_F^{\circ C}$ | Expected field temp. in $^{\circ}C$ |
| (50) | $X_S^{\circ C}$ | Expected temp. stator in $^{\circ}C$ |
| (95) | ρ_D | Resistivity of damper bar at $20^{\circ}C$ |
| (51) | ρ_S | Resistivity of stator cond at $20^{\circ}C$ |
| (104) | ρ_F | Resistivity of field conductor |
| (138) | ϕ_l | Leakage flux at no load |
| (160) | ϕ_{ll} | Leakage flux at full load |
| (126) | ϕ_P | Flux per pole |
| (139) | ϕ_{PT} | Total flux per pole at no load |
| (162) | ϕ_{PTL} | Total flux per pole at full load |
| (124) | ϕ_T | Total flux |
| (94) | τ_b | Damper bar pitch |
| (41) | τ_p | Pole pitch |
| (26) | τ_s | Slot pitch |
| (27) | $\tau_s \text{ } 1/3$ | Slot pitch $1/3$ distance from narrowest point |
| (40) | τ_{sk} | Stator slot skew |
| (70) | λ_a | Air gap permeance |
| (63) | λ_E | End permeance |
| (86) | λ_{el} | Pole end leakage permeance |
| (62) | λ_i | Stator conductor permeance |
| (88) | λ_{sl} | Pole side leakage permeance |
| (87) | λ_{tl} | Pole tip leakage permeance |

SALIENT POLE COMPUTER DESIGN (INPUT)

32

MODEL _____ EWO _____ DESIGN NO(1) 1000.0

| PARAMETERS | | CONSTANTS | | ROTOR STACK | | DAMPER BAR | | FIELD | | STATOR WINDING | |
|------------|------------------|------------------------------------|--------|--------------|--------------------------------|------------|-------------------|-------|--|----------------|--|
| (2) | KVA | GENERATOR KVA | 30.0 | 1.018 | RATIO MAX TO MIN OF FUND | (71) | C _l | | | | |
| (3) | E | LINE VOLTS | 208.0 | 0.0 | WINDING CONSTANT | (72) | C _w | | | | |
| (4) | E _{ph} | PHASE VOLTS | 120.0 | .650 | POLE CONST. | (73) | C _p | | | | |
| (5) | m | PHASES | 3.0 | 0.0 | END EXTENSION ONE TURN | (48) | L _E | | | | |
| (5a) | f | FREQUENCY | 320.0 | .84 | DEMAGNETIZATION FACTOR | (74) | C _m | | | | |
| (6) | p | POLES | 8.0 | .52 | CROSS MAGNETIZING FACTOR | (75) | C _q | | | | |
| (7) | RPM | RPM | 4800.0 | 1.975 | POLE HEAD WIDTH | (76) | b _h | | | | |
| (8) | I _{ph} | PHASE CURRENT | 83.4 | 1.100 | POLE BODY WIDTH | (76) | b _p | | | | |
| (9) | PF | POWER FACTOR | .75 | .406 | POLE HEAD HEIGHT | (76) | h _h | | | | |
| (9a) | K _c | ADJ. FACTOR | 1.0 | .979 | POLE BODY HEIGHT | (76) | h _f | | | | |
| (10) | | OPTIONAL LOAD POINT | .5 | 3.0 | POLE BODY LENGTH | (76) | l _p | | | | |
| (11) | d | STATOR I.D. | 7.25 | 3.0 | POLE HEAD LENGTH | (76) | l _n | | | | |
| (12) | D | STATOR O.D. | 9.25 | .71 | POLE EMBRACE | (77) | α | | | | |
| (13) | l | GROSS CORE LENGTH | 3.0 | 7.18 | ROTOR DIAMETER | (11a) | d _r | | | | |
| (14) | n _y | NO. OF DUCTS | 0.0 | .97 | STACKING FACTOR (ROTOR) | (16) | K _i | | | | |
| (15) | b _y | WIDTH OF DUCT | 0.0 | (CURVE) 14.0 | ROTOR LAM. MTR'L. | (18) | | | | | |
| (16) | K _i | STACKING FACTOR (STATOR) | .92 | 0 | WEIGHT OF ROTOR IRON | (108b) | (-) | | | | |
| (18) | | STATOR LAM. MTR'L. (CURVE) | 13.0 | 1.17 | POLE FACE LOSS FACTOR | (151) | (K _l) | | | | |
| (19) | k | WATTS/LB. | 15.0 | .040 | WIDTH OF SLOT OPENING | (89) | b _{bo} | | | | |
| (20) | B | DENSITY | 77.4 | .038 | HEIGHT OF SLOT OPENING | (89) | h _{bo} | | | | |
| (21) | | TYPE OF SLOT | 2.0 | .156 | DAMPER BAR DIA. OR WIDTH | (90) | () | | | | |
| (22) | b _o | SLOT OPENING | .06 | 0.0 | RECTANGULAR BAR THICKNESS | (89) | h _{bl} | | | | |
| (22) | b _l | SLOT WIDTH TOP | 0.0 | 0.0 | RECTANGULAR SLOT WIDTH | (89) | b _{bl} | | | | |
| (22) | b ₂ | | 0.0 | 5.0 | NO. OF DAMPER BARS | (92) | n _b | | | | |
| (22) | b ₃ | | 0.0 | 3.0 | DAMPER BAR LENGTH | (93) | l _b | | | | |
| (22) | b _s | SLOT WIDTH | .122 | .403 | DAMPER BAR PITCH | (94) | τ _b | | | | |
| (22) | h _o | | .020 | .694 | RESISTIVITY OF DAMP. BAR @20° | (95) | ρ _D | | | | |
| (22) | h ₁ | | .344 | 150.0 | DAMPER BAR TEMP °C | (96) | X °C | | | | |
| (22) | h ₂ | | 0.0 | 68 | NO. OF FIELD TURNS | (99) | N _p | | | | |
| (22) | h ₃ | | 0.0 | 10.13 | MEAN LENGTH OF FLD. TURN | (100) | l _{tr} | | | | |
| (22) | h _s | SLOT DEPTH | .434 | .0641 | FLD. COND. DIA. OR WIDTH | (101) | | | | | |
| (22) | h _t | | 0.0 | 0.0 | FLD. COND. THICKNESS | (102) | | | | | |
| (22) | h _w | | .030 | 150.0 | FLD. TEMP IN °C | (103) | X _f °C | | | | |
| (23) | Q | NO. OF SLOTS | 96.0 | .694 | RESISTIVITY OF FIELD COND @20° | (104) | ρ _f | | | | |
| (28) | | TYPE OF WDG. | 1.0 | 1.0 | NO LOAD SAT. | (179) | | | | | |
| (29) | | TYPE OF COIL | 1.0 | 0 | FRICTION & WINDAGE | (147) | (F&W) | | | | |
| (30) | n _s | CONDUCTORS/SLOT | 2.0 | | | | | | | | |
| (31) | y | SLOTS SPANNED | 10.0 | | | | | | | | |
| (32) | c | PARALLEL CIRCUITS | 1.0 | | | | | | | | |
| (33) | | STRAND DIA. OR WIDTH | .075 | | | | | | | | |
| (34) | N _{st} | STRANDS/CONDUCTOR | 1.0 | | | | | | | | |
| (35) | d _b | DIA. OF PIN | .25 | | | | | | | | |
| (36) | l _{e2} | COIL EXT. STR. PORT | .25 | | | | | | | | |
| (37) | h _{st} | UNINS. STRD. HT. | .162 | | | | | | | | |
| (38) | h _{'st} | DIST. BTWN. C _L OF STD. | .192 | | | | | | | | |
| (39) | | STATOR STRAND T'KNS. | .162 | | | | | | | | |
| (40) | T _{sk} | STATOR SLOT SKEW | .0001 | | | | | | | | |
| (50) | X °C | STATOR TEMP °C | 150.0 | | | | | | | | |
| (51) | ρ _s | RES'TVY STA. COND. @20° C | .694 | | | | | | | | |
| (59) | g _{min} | MINIMUM AIR GAP | .035 | | | | | | | | |
| (59a) | g _{max} | MAXIMUM AIR GAP | .047 | | | | | | | | |
| | | | | | | | | | | | |

DESIGNER _____ DATE _____

MODEL NO. _____ EWO _____ DESIGN NO. 1000.00000

| | | | | | | | | |
|----------------------|----------------------------|-------------------------|-------------------------------|------------------------------------|-----------------------------|----------------------|---------------------|----------|
| STATOR | (17) (ℓ_s) | SOLID CORE LENGTH | 2.76000 | 1.08190 | CARTER COEFFICIENT | (67) (K_s) | GAP | |
| | (24) (h_c) | DEPTH BELOW SLOT X 2 | .56600 | 68.33850 | AIR GAP AREA | (68) (-) | | |
| | (26) (τ_s) | SLOT PITCH | .23728 | 152.69103 | AIR GAP PERM | (70) (λ_a) | | |
| | (27) ($\tau_{s1/3}$) | SLOT PITCH 1/3 DIST. UP | .24676 | .03786 | EFFECTIVE AIR GAP | (69) (g_e) | CONSTANTS | |
| | (42) (K_{sk}) | SKEW FACTOR | 1.00000 | 1.01800 | RATIO MAX TO FUND. | (71) (C_1) | | |
| | (43) (K_d) | DIST. FACTOR | .95765 | .39823 | WINDING CONST. | (72) (C_w) | | |
| | (44) (K_p) | PITCH FACTOR | .96596 | .65000 | POLE CONST. | (73) (C_p) | | |
| | (45) (n_e) | EFF. CONDUCTORS | 185.46619 | 4.59241 | END. EXT. ONE TURN | (48) (L_E) | | |
| | (46) (a_c) | STRAND AREA | .01135 | .84000 | DEMAGNETIZING FACTOR | (74) (C_M) | | |
| | (47) (S_s) | CURRENT DENSITY (STA.) | 7343.32690 | .52000 | CROSS MAGNETIZING FCTR | (75) (C_g) | | |
| | (49) (ℓ_t) | 1/2 MEAN TURN | 7.59241 | 679.03797 | AMP COND/IN | (78) (A) | | |
| | (53) (R_{ph}) | COLD STA. RES. @20°C | .02971 | .87672 | REACTANCE FACTOR | (79) (X) | | |
| | (54) (R_{ph}) | HOT STA. RES. @X°C | .04501 | 7.76606 | LEAKAGE REACTANCE | (80) (X_L) | | |
| (55) (EF_{top}) | EDDY FACTOR TOP | 1.16467 | 114.47347 | REACTANCE DIRECT AXIS | (81) (X_{ad}) | REACTANCE | | |
| (56) (EF_{bot}) | EDDY FACTOR BOT | 1.02326 | 69.61152 | REACTANCE QUAD AXIS | (82) (X_{aq}) | | | |
| (62) (λ_i) | STATOR COND. PERM. | 3.43609 | 122.23953 | SYN REACT DIRECT AXIS | (83) (X_d) | | | |
| (63) (ρ_e) | END PERM. | 5.42192 | 77.37758 | SYN REACT QUAD AXIS | (84) (X_q) | | | |
| (65) () | WT. OF STA COPPER | 5.31106 | 14.33483 | FIELD LEAKAGE REACT | (112) (X_f) | | | |
| (66) () | WT. OF STA IRON | 16.27519 | .18440 | FIELD SELF INDUCTANCE | (113) (L_f) | | | |
| ROTOR | (41) (τ_p) | POLE PITCH | 2.84743 | 4.33170 | LEAKAGE REACT DIRECT AX. | | (115) (X_{Dd}) | |
| | (85) (σ_p) | POLE AREA | 3.20100 | 5.35257 | LEAKAGE REACT QUAD AX. | | (117) (X_{Dq}) | |
| | (86) ($\rho_e \ell$) | POLE END LEAK PERM. | .41800 | 22.10089 | UNSAT. TRANS. REACT | | (118) (X'_{du}) | |
| | (87) ($\lambda_{t\ell}$) | POLE TIP LEAK PERM. | .64832 | 19.44878 | SAT. TRANS. REACT | | (119) (X'_d) | |
| | (88) ($\lambda_{s\ell}$) | POLE SIDE LEAK PERM. | .80990 | 12.09776 | SUB. TRANS REACT DIRECT AX. | (120) (X''_d) | | |
| | (89) (σ_{CF}) | FLD COND. AREA | .00322 | 13.11863 | SUB. TRANS REACT QUAD AX. | (121) (X''_q) | | |
| | (90) (R_F) | COLD FLD RES @ 20°C | 1.18771 | 12.60819 | NEG SEQUENCE REACT | (122) (X_2) | | |
| | (91) (R_F) | HOT FLD RES @ X°C | 1.79930 | 3.30450 | ZERO SEQUENCE REACT | (123) (X_0) | | |
| | (108a) () | WT OF FLD COPPER | 5.69599 | 3520.25190 | TOTAL FLUX | (124) (ϕ_T) | | |
| | (108b) () | WT OF ROTOR IRON | .00000 | 286.02046 | FLUX PER POLE | (126) (ϕ_p) | | |
| TIME CONSTANTS | (98a) (V_r) | PERIPHERAL SPEED | 9029.56800 | 51.51198 | GAP DENSITY | (125) (B_g) | MAGNETIZATION | |
| | (132) (T_{do}) | OPEN CIR. TIME CONST. | .10248 | 106.49226 | TOOTH DENSITY | (127) (B_r) | | |
| | (133) (T_a) | ARM TIME CONST. | .00200 | 91.54646 | CORE DENSITY | (128) (B_c) | | |
| | (134) (T'_d) | TRANS TIME CONST. | .01630 | 67.69566 | TOOTH AMPERE TURNS | (129) (F_t) | | |
| | (135) (T''_d) | SUB TRAN TIME CONST. | .00500 | 25.81124 | CORE AMPERE TURNS | (130) (F_c) | | |
| | (136) (F_{sc}) | SHORT CIR NI | 747.32558 | 611.36163 | GAP AMPERE TURNS | (131) (F_g) | | |
| | (137) (SCR) | SHORT AIR RATIO | 1.03001 | | | | | |
| | PERCENT LOAD | | 0 | 100 | 150 | 200 | | OPTIONAL |
| | (ϕ_ℓ) (138) | LEAK FLUX | 27.131 | ($\phi_{\ell\ell}$) (160) 49.621 | 62.294 | 75.252 | | 37.569 |
| | (ϕ_{pt}) (139) | POLE FLUX | 313.151 | ($\phi_{pt\ell}$) (162) 353.503 | 377.720 | 404.910 | | 332.960 |
| (B_p) (140) | POLE DENSITY | 97.829 | ($B_{p\ell}$) (163) 110.435 | 118.000 | 126.494 | 104.017 | | |
| (F_p) (141) | POLE NI | 68.669 | ($F_{p\ell}$) (164) 241.300 | 442.669 | 835.502 | 130.953 | | |
| (F_{nl}) (142) | TOTAL NI | 823.071 | (F_{nl}) (165) 1621.979 | 2176.268 | 2929.955 | 1176.017 | | |
| (I_{fnl}) (143) | FIELD AMPS | 12.103 | (I_{fnl}) (166) 23.852 | 32.003 | 43.087 | 17.294 | | |
| (S_F) (144) | CUR. DENS. (FLD) | 3759.001 | (—) (167) 7407.650 | 9939.114 | 13381.236 | 5370.925 | | |
| (E_F) (145) | FIELD VOLTS | 14.376 | (E_{ffl}) (168) 42.918 | 57.584 | 77.527 | 31.117 | | |
| (I^2R_r) (146) | ROTOR LOSS | 174.007 | (I^2R_r) (169) 1023.708 | 1842.938 | 3340.471 | 538.162 | | |
| ($F & W$) (147) | F & W LOSS | 347.291 | ($F & W$) (147) 347.291 | 347.291 | 347.291 | 347.291 | | |
| (W_{fnl}) (148) | STA TOOTH LOSS | 184.539 | (W_{fnl}) (170) 234.722 | 288.655 | 359.285 | 198.950 | | |
| (W_c) (149) | STA CORE LOSS | 404.227 | (W_c) (149) 404.227 | 404.227 | 404.227 | 404.227 | | |
| (W_{pnl}) (150) | POLE FACE LOSS | 105.017 | (W_{pnl}) (171) 114.675 | 126.748 | 143.650 | 107.432 | | |
| (W_{dnl}) (157) | DAMPER LOSS | .256 | (W_{dnl}) (172) .345 | .382 | .433 | .324 | | |
| (I^2R_s) (158) | STATOR CU LOSS | .000 | (I^2R_s) (173) 939.209 | 2113.220 | 3756.837 | 234.802 | | |
| (—) (158) | EDDY LOSS | .000 | (—) (173a) 88.248 | 198.558 | 352.992 | 22.062 | | |
| (—) (159) | TOTAL LOSSES | 1215.340 | (—) (174) 3152.428 | 5322.023 | 8705.189 | 1853.253 | | |
| (—) (—) | RATING (KW) | .000 | (—) (175) 22534.013 | 33801.020 | 45068.026 | 11267.007 | | |
| (—) (—) | RATING & LOSSES | 1215.340 | (—) (176) 25686.441 | 39123.043 | 53773.215 | 13120.260 | | |
| (—) (—) | PERCENT LOSSES | 100.000 | (—) (177) 12.272 | 13.603 | 16.188 | 14.125 | | |
| (—) (—) | PERCENT EFF. | .000 | (—) (178) 87.727 | 86.396 | 83.811 | 85.874 | | |

DESIGNER
DATE

NO LOAD SATURATION OUTPUT SHEET

| ITEMS VOLTS | (179) (—) VOLTS | (180) (F'_g) AIR GAP A.T. | (181) (B'_t) TOOTH DENSITY | (182) (F'_t) TOOTH A.T. | (183) (B'_c) CORE DENSITY | (184) (F'_c) CORE A.T. |
|----------------|---------------------------------|-------------------------------------|---|-----------------------------------|----------------------------------|--|
| | (185) (F'_s) STATOR A.T. | (186) (ϕ'_l) LEAKAGE FLUX | (187) (ϕ'_{pt}) TOTAL FLUX/POLE | (188) (B'_p) TOOTH DENSITY | (189) (F'_p) POLE A.T. | (190) (F'_{nl}) TOTAL A.T. (N.L.) |
| 80% | 166.27200 14.59590 | 489.08930 18.08733 | 85.19380 246.90370 | 7.29726 77.13330 | 73.23716 14.31810 | 7.298 28.914 |
| 90% | 187.05600 33.12066 | 550.22547 20.94796 | 95.84303 278.36637 | 21.14996 86.96231 | 82.39181 25.71249 | 11.970 58.833 |
| 100% | 207.84000 93.50690 | 611.36163 25.31182 | 106.49226 311.33228 | 67.69566 97.26094 | 91.54646 64.89074 | 25.811 158.397 |
| 110% | 228.62400 231.00817 | 672.49779 32.44489 | 117.14149 347.06740 | 158.70457 108.42467 | 100.70111 203.36754 | 72.303 434.375 |
| 120% | 249.40800 479.03354 | 733.63396 43.54689 | 127.79071 386.77144 | 301.98336 120.82831 | 109.85575 544.53846 | 177.050 1023.572 |
| 130% | 270.19200 747.42263 | 794.77012 55.38014 | 138.43994 427.20674 | 394.41868 133.46039 | 119.01040 1193.19100 | 353.003 1940.613 |
| 140% | TOOTH DENSITY SATURATED | | | | | |
| 150% | | | | | | |
| 160% | | | | | | |

SALIENT POLE COMPUTER DESIGN MANUAL

| | | |
|------|----------|---|
| (1) | -- | <u>DESIGN NUMBER</u> - To be used for filing purposes |
| (2) | KVA | <u>GENERATOR KVA</u> |
| (3) | E | <u>LINE VOLTS</u> |
| (4) | E_{PH} | <u>PHASE VOLTS</u> - For 3 phase, delta connected generator $E_{PH} = \frac{(\text{Line Volts})}{\sqrt{3}} = \frac{(3)}{\sqrt{3}}$ <p>For 3 phase, wye connected generator</p> $E_{PH} = (\text{Line Volts}) = (3)$ |
| (5) | m | <u>PHASES</u> - Number of |
| (5a) | f | <u>FREQUENCY</u> - In cycles per second |
| (6) | P | <u>POLES</u> - Number of |
| (7) | RPM | <u>SPEED</u> - In revolutions per minute |
| (8) | I_{PH} | <u>PHASE CURRENT</u> - In amperes at rated load |
| (9) | P.F. | <u>POWER FACTOR</u> - Given in per unit |
| (9a) | K_c | <u>ADJUSTMENT FACTOR</u> - When P.F. = 0. to .95 set $K_c = 1.$; when P.F. = .95 to 1. set $K_c = 1.05$ |
| (10) | -- | <u>LOAD POINTS</u> - The computer program is set up to have the 0.%, 100%, 150%, 200% load points as standard out- puts. There is an additional space available on the output sheet for one optional load point. This optional |

load point will be the designer's choice and can be selected anywhere in the range of 0 to 200% load. When an optional load calculation is required insert the per unit load value on the input sheet. The optional load point will be calculated in addition to the standard points listed above. If only the standard points are required, insert 0. on input sheet. For example, insert .33 on input sheet when the optional load calculation for 33% load is required in addition to the standard points.

- | | | |
|-------|--------|--|
| (11) | d | <u>STATOR PUNCHING I.D.</u> - The inside diameter of the stator punching in inches |
| (11a) | d_r | <u>ROTOR PUNCHING O.D.</u> - The outside diameter of the rotor punching in inches |
| (12) | D | <u>PUNCHING O.D.</u> - The outside diameter of the stator punching in inches |
| (13) | ℓ | <u>GROSS CORE LENGTH</u> - In inches |
| (14) | n_v | <u>RADIAL DUCTS</u> - Number of |
| (15) | b_v | <u>RADIAL DUCT WIDTH</u> - In inches |
| (16) | K_i | <u>STACKING FACTOR</u> - This factor allows for the coating (core plating) on the punchings, the burrs due to slotting, and the deviations in flatness. Approximate values of K_i are given in Table IV. |

THICKNESS OF
LAMINATIONS
(INCHES)

GAGE

K_i

| | | |
|------|----|------|
| .014 | 29 | 0.92 |
| .018 | 26 | 0.93 |
| .025 | 24 | 0.95 |
| .028 | 23 | 0.97 |
| .063 | -- | 0.98 |
| .125 | -- | 0.99 |

TABLE IV

(17) ℓ_s

SOLID CORE LENGTH - The solid length is the gross length times the stacking factor. If ventilating ducts are used, their length must be subtracted from the gross length also.

$$\ell_s = (K_i) \left[(\ell) - (n_v) (b_v) \right] = (16) \left[(13) - (14) (15) \right]$$

(18) --

LAMINATION MATERIAL - This input is used in selecting the proper magnetization curve. Where curves are available on card decks, use the proper identifying code. Where card decks are not available, submit as an auxiliary input, 29 points of the curve to be used (start first reading at 0). These points are the ampere turns per inch for each five units on the density scale, where 1 unit is 1 kiloline/in². Refer to curves 10, 11, 12 for standard magnetization curves. Submit separate magnetization curves for stator and rotor when different materials are used. Separate spaces are provided on input sheet for stator material and rotor material.

When the magnetization curve is not available on card decks insert 0. on input sheet and provide 29 point of

the curve to be used as outlined previously in this paragraph. When the magnetization curve is available on existing card decks, and a coding system is available to identify each curve, then insert the proper code number on the input sheet. Since curves

are available on card decks, they have been coded as follows: 1.0 = curve 10; 2.0 = curve 11-high; 2.1 = curve 11-average; 2.2 = curve 11-low; 3.0 = curve 12-high; 3.1 = curve 12-average; 3.2 = curve 12-low. Once a curve has been submitted, the card deck should be coded and stored for future use. An index of coded magnetization curves should be published from time to time to bring records up to date.

- | | | |
|------|-----------------------|--|
| (19) | k | <u>WATTS/LB</u> - Core loss per lb of lamination material. Must be given at the density specified in (20). |
| (20) | B | <u>DENSITY</u> - This value must correspond to the density used in item (19) to pick the watts/lb. The density that is usually used is 77.4 kilolines/in ² . |
| (21) | 1 2 3 4 5 | <u>TYPE OF STATOR SLOT</u> - Refer to Figure 1, Page 8 for type of slot For (a) slot use 1. as an input For (b) slot use 2. as an input For (c) slot use 3. as an input For (d) slot use 4. as an input Type 5. is not a slot but instead a particular situation for an open slot where the winding has only one conductor per slot. |

(22)

 b_0 b_1 b_2 b_3 b_s h_0 h_1 h_2 h_3 h_s h_t h_w

ALL SLOT DIMENSIONS - Given in inches per Figure 1, page 8

Where the dimension does not apply to the slot being used, insert 0. on input sheet.

(23)

 Q

STATOR SLOTS - Number of

(24)

 h_c

DEPTH BELOW SLOTS - The depth of the stator core below the slots.

Due to mechanical strength reasons, h_c should never be less than 70% of h_s .

$$h_c = \frac{(D) - [\overline{(d)} + 2(\overline{h_s})]}{2} = \frac{(12) - [\overline{(11)} + 2(\overline{22})]}{2}$$

(25)

 q

SLOTS PER POLE PER PHASE

$$q = \frac{(Q)}{(P)(m)} = \frac{(23)}{(6)(5)}$$

(26)

 τ_s

STATOR SLOT PITCH

$$\tau_s = \frac{\pi(d)}{Q} = \frac{\pi(11)}{(23)}$$


- (27) $\tau_{s1/3}$ STATOR SLOT PITCH - 1/3 distance up from narrowest section
 For slot (a), (b), (c), and (e)

$$\tau_{s1/3} = \frac{\pi [(d) + .66(h_s)]}{(Q)} = \frac{\pi [(11) + .66(22)]}{(23)}$$

 For slot (d)

$$\frac{\pi [(d) + 2(h_o) + 1.32(b_s)]}{(Q)} =$$

$$\frac{\pi [(11) + 2(22) + 1.32(22)]}{(23)}$$
- (28) -- TYPE OF WINDING - Record whether the connection is "wye" or "delta". For "wye" conn use 1. for input. For "delta" use 0. for input
- (29) -- TYPE OF COIL - Record whether random wound or formed coils are used. For random wound coils use 0. for input. For formed coils use 1. for input.
- (30) n_s CONDUCTORS PER SLOT - The actual number of conductors per slot. For random wound coils use a space factor of 75% to 80%. Where space factor is the percent of the total slot area that is available for insulated conductors after all other insulation areas have been subtracted out.
- (31) γ THROW - Number of slots spanned. For example, with a coil side in slot 1 and the other coil side in slot 10, the throw is 9.

- (31a) PERCENT OF POLE PITCH SPANNED - Ratio of the number of slots spanned to the number of slots in a pole pitch
- $$= \frac{(Y)}{(m)(q)} = \frac{(31)}{(5)(25)}$$
- (32) C PARALLEL PATHS, No. of - Number of parallel circuits per phase
- (33) -- STRAND DIA OR WIDTH - In inches. For round wire, use strand diameter. For rectangular wire, use strand width.
- (34) N_{ST} NUMBER OF STRANDS PER CONDUCTOR IN DEPTH -
Applies to rectangular wire. In order to have a more flexible conductor and reduce eddy current loss a stranded conductor is often used. For example, when the space available for one conductor is .250 width x .250 depth, the actual conductor can be made up of 2 or 3 strands in depth as shown
- 
- For a more detailed explanation refer to section titled "Effective Resistance and Eddy Factor" in the Derivations in Appendix.
- (35) d_b DIAMETER OF BENDER PIN in inches - This pin is used in forming coils
- (36) l_{e2} COIL EXTENSION BEYOND CORE in inches - Straight portion of coil that extends beyond stator core
- (37) h_{ST} HEIGHT OF UNINSULATED STRAND in inches

(38) h_{ST} DISTANCE BETWEEN CENTERLINES OF STRANDS IN DEPTH
in inches

(39) -- STATOR COIL STRAND THICKNESS in inches - For rectangular conductors only. For round wire insert 0. on input sheet.

(40) τ_{SK} SKEW - Stator slot skew in inches at stator I.D.

(41) τ_P POLE PITCH in inches

$$\frac{\pi(d)}{(P)} = \frac{\pi(11)}{(6)}$$

(42) K_{SK} SKEW FACTOR - The skew factor is the ratio of the voltage induced in the coils to the voltage that would be induced if there were no skew

$$K_{SK} = \frac{\sin \left[\frac{\pi(\tau_{SK})}{2(\tau_P)} \right]}{\frac{\pi(\tau_{SK})}{2(\tau_P)}} = \frac{\sin \left[\frac{\pi(40)}{2(41)} \right]}{\frac{\pi(40)}{2(41)}}$$

(43) K_d DISTRIBUTION FACTOR - The distribution factor is the ratio of the voltage induced in the coils to the voltage that would be induced in the coils if the winding were concentrated in a single slot. See Table 2 for compilation of distribution factors for the various harmonies.

$$K_d = \frac{\sin \left[\frac{(q)(\alpha_s)}{2} \right]}{(q) \sin \frac{(\alpha_s)}{2}} \quad \text{where } \alpha_s = \frac{180^\circ}{(m/q)}$$

$$\therefore K_d = \frac{\sin \left[90^\circ / (m) \right]}{(q) \sin \left[90^\circ / (m)(q) \right]} = \frac{\sin \left[90^\circ / (5) \right]}{(25) \sin \left[90^\circ / (5) \times (25) \right]} \text{ For } (25) = \text{Integer}$$

or

$$K_d = \frac{\sin \left[N\alpha(m)/2 \right]}{N \sin \left[\alpha(m)/2 \right]} \text{ where } N = \text{Integer} = \frac{(Q)}{(m)(P)} \times \text{Integer} \text{ \& } \alpha m = \frac{180^\circ}{N \times (m)}$$

$$\therefore K_d = \frac{\sin \left[90^\circ / (m) \right]}{N \sin \left[90^\circ / N(m) \right]} = \frac{\sin \left[90^\circ / (5) \right]}{N \sin \left[90^\circ / N \times (5) \right]} \text{ For } (25) = \text{Integer}$$

(44) K_p PITCH FACTOR - The ratio of the voltage induced in the coil to the voltage that would be induced in a full pitched coil. See Table 1 for compilation of the pitch factors for the various harmonics.

$$K_p = \sin \left[\frac{(Y)}{(m)(q)} \times 90^\circ \right] = \sin \left[\frac{(31)}{(5)(25)} \times 90^\circ \right]$$

(45) n_e TOTAL EFFECTIVE CONDUCTORS - The actual number of effective series conductors in the stator winding taking into account the pitch and skew factors but not allowing for the distribution factor.

$$n_e = \frac{(Q)(n_s)(K_p)(K_{SK})}{(C)} = \frac{(23)(30)(44)(42)}{(32)}$$

(46) a_c CONDUCTOR AREA OF STATOR WINDING in (inches)² -

The actual area of the conductor taking into account the corner radius on square and rectangular wire. See the following table for typical values of corner radii

$$\text{If } (39) = 0 \text{ then } a_c = .25\pi(\text{Dia})^2 = .25\pi(33)^2$$

$$\text{If (39) } \neq 0 \text{ then } a_c = (N_{ST}) \left[(\text{strand width}) (\text{strand depth}) - (.858 r_c^2) \right]$$

$$= (34) \left[(33) (39) - \{.858 r_c^2\} \right]$$

where $.858 r_c^2$ is obtained from Table V below.

| (39) | (33) .188 | .189 (33) .75 | (33) .751 |
|------|-----------|---------------|-----------|
| .050 | .000124 | .000124 | .000124 |
| .072 | .000210 | .000124 | .000124 |
| .125 | .000210 | .00084 | .000124 |
| .165 | .000840 | .00084 | .003350 |
| .225 | .001890 | .00189 | .003350 |
| .438 | -- | .00335 | .007540 |
| .688 | -- | .00754 | .01340 |
| -- | -- | .03020 | .03020 |

TABLE V

(47) S_S CURRENT DENSITY - Amperes per square inch of stator conductor

$$S_S = \frac{(I_{PH})}{(C)(a_c)} = \frac{(8)}{(32)(46)}$$

(48) L_E END EXTENSION LENGTH in inches - Can be an input or output.

For L_E to be output, insert 0. on input sheet.

For L_E to be input, calculate per following:

When (29) = 0 then:

$$L_E = \frac{.5 + K_T \pi y \left[d + h_s \right]}{Q} = .5 + \frac{\left[\begin{array}{l} 1.3 \text{ If } (6) = 2 \\ 1.5 \text{ If } (6) = 4 \\ 1.7 \text{ If } (6) > 4 \end{array} \right] \pi (31) \left[(11) + (22) \right]}{(23)}$$

When (29) = 1. then:

$$L_E = 2\ell_{e2} + \pi \left[\frac{h_1}{2} + \text{dia} \right] + y \left[\frac{t_s^2}{\sqrt{t_s^2 - b_s^2}} \right]$$

$$= 2 \times (36) + \pi \left[\frac{(22)}{2} + (35) \right] + (31) \left[\frac{(26)^2}{\sqrt{(26)^2 - (22)^2}} \right]$$

(49) ℓ_t 1/2 MEAN TURN - The average length of one conductor in inches

$$\ell_t = (\ell) + (L_E) = (13) + (44)$$

(50) $X_s^{\circ}\text{C}$ STATOR TEMP $^{\circ}\text{C}$ - Input temp at which F.L. losses will be calculated. No load losses and cold resistance will be calculated at 20°C .

(51) ρ_s RESISTIVITY OF STATOR WINDING - In micro ohm-inches @ 20°C . If tables are available using units other than that given above, use Table VI for conversion to ohm-inches.

| ρ | ohm-cm | ohm-in | ohm-cir mil/ft |
|--------------------|------------------------|------------------------|---------------------|
| 1 ohm-cm = | 1.000 | 0.3937 | 6.015×10^6 |
| 1 ohm-in = | 2.540 | 1.000 | 1.528×10^7 |
| 1 ohm-cir mil/ft = | 1.662×10^{-7} | 6.545×10^{-8} | 1.000 |

TABLE VI
Conversion Factors for Electrical Resistivity

(52) $\rho_{s(\text{hot})}$ RESISTIVITY OF STATOR WINDING - Hot at $X_s^{\circ}\text{C}$ in micro ohm-inches

$$\rho_{s(\text{hot})} = (\rho_s) \left[\frac{(X_s^{\circ}\text{C}) + 234.5}{254.5} \right] = (51) \left[\frac{(50) + 234.5}{254.5} \right]$$

(53) R_{SPH}
(cold)

STATOR RESISTANCE/PHASE - Cold @ 20°C in ohms

$$R_{SPH(cold)} = \frac{(\rho_s)(n_s)(Q)(\ell_t)}{(m)(a_c)(C)^2} = \frac{(51)(30)(23)(49)}{(5)(46)(32)^2}$$

(54) R_{SPH}
(hot)

STATOR RESISTANCE/PHASE - Calculated @ X°C in ohms

$$R_{SPH(hot)} = \frac{(\rho_{s \text{ hot}})(n_s)(Q)(\ell_t)}{(m)(a_c)(C)^2} = \frac{(52)(30)(23)(49)}{(5)(46)(32)^2}$$

(55) EF
(top)

EDDY FACTOR TOP - The eddy factor of the top coil.

Calculate this value at the expected operating temperature of the machine.

$$EF_{top} = 1 + \left\{ .584 + \left[\frac{N_{st}^2 - 1}{16} \right] \left[\frac{h'_{st} \ell}{h_{st} \ell_t} \right]^2 \right\} 3.35 \times 10^{-3}$$

$$\left[\frac{(h_{st})(n_s)(f)(a_c)}{(b_s)(\rho_{s \text{ hot}}) \times 10^6} \right]^2$$

$$= 1 + \left\{ .584 + \left[\frac{(34)^2 - 1}{16} \right] \left[\frac{(38)(13)}{(37)(49)} \right]^2 \right\} 3.35 \times 10^{-3}$$

$$\left[\frac{(37)(30)(5a)(46)}{(22)(52) 10^6} \right]^2$$

(56) EF
(bot)

EDDY FACTOR BOTTOM - The eddy factor of the bottom coil at the expected operating temperature of the machine

$$EF_{(bot)} = (EF_{(top)}) - 1.677 \left[\frac{(h_{st})(n_s)(f)(a_c)}{(b_s)(\rho_{s \text{ hot}}) 10^6} \right]^2 \times 10^{-3}$$

$$= (55) - 1.677 \left[\frac{(37)(30)(5a)(46)}{(22)(52) 10^6} \right] 10^{-3}$$

(57) b_{tm} STATOR TOOTH WIDTH 1/2 way down tooth in inches -

For slots type (a), (b), (d) and (e), Figure I

$$b_{tm} = \frac{\pi[(d) + (h_s)]}{(Q)} - (b_s) = \frac{\pi[(11) + (22)]}{(23)} - (22)$$

For slot type (c), Figure I

$$b_{tm} = \frac{\pi[(d) + 2(h_s)]}{(Q)} - (b_s) = \frac{\pi[(11) + 2(22)]}{(23)} - (22)$$

(57a) $b_{t \ 1/3}$ STATOR TOOTH WIDTH 1/3 distance up from narrowest section

For slots type (a), (b) and (e)

$$b_{t \ 1/3} = (\tau_{s \ 1/3}) - (b_s) = (27) - (22)$$

For slot type (c)

$$b_{t \ 1/3} = b_{tm} = (57)$$

For slot type (d)

$$b_{t \ 1/3} = (\tau_{1/3}) - \frac{2\sqrt{2}}{3} (b_s) = (27) - .94 (22)$$

(58) b_t TOOTH WIDTH AT STATOR I.D. in inches -

For partially closed slot

$$b_t = \frac{\pi(d)}{(Q)} - b_0 = \frac{\pi(11)}{(23)} - (22)$$

For open slot

$$b_t = \frac{\pi(d)}{(Q)} - b_s = \frac{\pi(11)}{(23)} - (22)$$

| | | |
|-------|-------------|---|
| (59) | g_{\min} | <p><u>MINIMUM AIR GAP</u> in inches - For concentric pole face</p> <p>$g_{\min} = g_{\max}$. For non concentric pole face</p> <p>g_{\min} = gap at the center of the pole.</p> |
| (59a) | g_{\max} | <u>MAXIMUM AIR GAP</u> in inches |
| (60) | C_X | <p><u>REDUCTION FACTOR</u> - Used in calculating conductor permeance and is dependent on the pitch and distribution factor. This factor can be obtained from Graph 1 with an assumed K_d of .955 or calculated as shown</p> $C_X = \frac{(K_X)}{(K_P)^2 (K_d)^2} = \frac{(61)}{(44)^2 (43)^2}$ <p>NOTE: See special case for (e) slot referred to calculation (62)</p> |
| (61) | K_X | <p><u>FACTOR TO ACCOUNT FOR DIFFERENCE</u> in phase current in coil sides in same slot</p> $K_X = \frac{1}{4} \left[\frac{3(Y)}{(m)(q)} + 1 \right] \text{ For 3 phase}$ $= \frac{1}{4} \left[\frac{3(31)}{(5)(25)} + 1 \right]$ $K_X = \frac{(Y)}{(m)(q)} \text{ For 2 phase}$ $= \frac{(31)}{(5)(25)}$ <p>NOTE: See special case for (e) slot. Refer to calculation (62)</p> |
| (62) | λ_i | <p><u>CONDUCTOR PERMEANCE</u> - The specific permeance for the portion of the stator current that is embedded in the iron. This permeance depends upon the configuration of the slot.</p> |

(a) For open slots

$$\lambda_i = (C_X) \frac{20}{(m)(q)} \left[\frac{(h_2)}{(b_s)} + \frac{(h_1)}{3(b_s)} + \frac{(b_t)^2}{16(\tau_s)(g)} + \frac{.35(b_t)}{(\tau_s)} \right]$$

$$\lambda_i = (60) \frac{20}{(5)(25)} \left[\frac{(22)}{(22)} + \frac{(22)}{3(22)} + \frac{(58)^2}{16(26)(59)} + \frac{.35(58)}{(26)} \right]$$

(b) For partially closed slots with constant slot width

$$\lambda_i = (C_X) \frac{20}{(m)(q)} \left[\frac{(h_o)}{(b_o)} + \frac{2(h_t)}{(b_o) + (b_s)} + \frac{(h_w)}{(b_s)} + \frac{(h_1)}{3(b_s)} + \frac{(b_t)^2}{16(\tau_s)(g)} + \frac{.35(b_t)}{(\tau_s)} \right]$$

$$\lambda_i = (60) \frac{20}{(5)(25)} \left[\frac{(22)}{(22)} + \frac{2(22)}{(22) + (22)} + \frac{(22)}{(22)} + \frac{(22)}{3(22)} + \frac{(58)^2}{16(26)(59)} + \frac{.35(58)}{(26)} \right]$$

(d) For round slots

$$\lambda_i = (C_X) \frac{20}{(m)(q)} \left[.62 + \frac{(h_o)}{(b_o)} \right]$$

$$\lambda_i = (60) \frac{20}{(5)(25)} \left[.62 + \frac{(22)}{(22)} \right]$$

(e) For open slots with a winding of one conductor per slot

$$\lambda_i = (C_X) \frac{20}{(m)(q)} \left[\frac{(h_2)}{(b_s)} + \frac{(h_1)}{3(b_s)} + .6 + \frac{(g)}{2(\tau_s)} + \frac{(\tau_s)}{4(g)} \right]$$

$$\lambda_i = (60) \frac{20}{(5)(25)} \left[\frac{(22)}{(22)} + \frac{(22)}{3(22)} + .6 + \frac{(59)}{2(26)} + \frac{(26)}{4(59)} \right]$$

$$\left((C_X) = \frac{1}{(K_p^2)(K_d^2)} \right)$$

$$(K_X) = 1$$

(63) K_E LEAKAGE REACTIVE FACTOR for end turn

$$K_E = \frac{\text{Calculated value } (L_E)}{\text{Value } (L_E) \text{ from Graph 1}} \quad (\text{For machines where } (11) > 8'')$$

where $L_E = (48)$ and abscissa of Graph 1 = $(\gamma)(\tau_s) = (31)(26)$

$$K_E = \sqrt{\frac{\text{Calculated value of } (L_E)}{\text{Value } (L_E) \text{ from Graph 1}}} \quad (\text{For machines where } (11) < 8'')$$

(64) λ_E END WINDING PERMEANCE - The specific permeance for the end extension portion of the stator winding

$$\lambda_E = \frac{6.28(k_s)}{(l)(K_d)^2} \left[\frac{\phi_E L_E}{2n} \right] = \frac{6.28(63)}{(13)(43)^2} \left[\frac{Q_E L_E}{2n} \right]$$

The term $\left[\frac{\phi_E L_E}{2n} \right]$ is obtained from Graph 1.

The symbols used in this (term) do not apply to those of this design manual. Reference information for the symbol origin is included on Graph 1.

(65) --

WEIGHT OF COPPER - The weight of stator copper in lbs.

$$\# \text{'s copper} = .321(n_s)(Q)(a_c)(l_t) = .321(30)(23)(46)(49)$$

(66) --

WEIGHT OF STATOR IRON - in lbs.

$$\begin{aligned} \# \text{'s iron} = & .283 \left\{ (b_{tm})(Q)(l_s)(h_s) + \pi \left[(D) - (h_c) \right] (h_c)(l_s) \right\} \\ & .283 \left\{ (57)(23)(17)(22) + \pi \left[(12) - (24) \right] (24)(17) \right\} \end{aligned}$$

(67) K_s CARTER COEFFICIENT

$$K_s = \frac{(\tau_s) \left[5(g) + (b_s) \right]}{(\tau_s) \left[5(g) + (b_s) \right] - (b_s)^2} \quad (\text{For open slots})$$

$$K_s = \frac{(26) [5(59) + (22)]}{(26) [5(59) + (22)] - (22)^2}$$

$$K_s = \frac{\tau_s [4.44(g) + .75(b_o)]}{\tau_s [4.44(g) + .75(b_o)] - (b_o)^2} \quad (\text{For partially closed slots})$$

$$K_s = \frac{(26) [4.44(59) + .75(22)]}{(26) [4.44(59) + .75(22)] - (22)^2}$$

(68) -- AIR GAP AREA - The area of the gap surface at the stator bore

$$\text{Gap Area} = \pi(d)(\mathcal{L}) = \pi(11)(13)$$

(69) g_e EFFECTIVE AIR GAP

$$g_e = (K_s)(g) = (67)(59)$$

(70) λ_a AIR GAP PERMEANCE - The specific permeance of the air gap

$$\lambda_a = \frac{6.38(d)}{(P)(g_e)} = \frac{6.38(11)}{(6)(69)}$$

(71) C_1 THE RATIO OF MAXIMUM FUNDAMENTAL of the field form to the actual maximum of the field form - This term can be an input or output. For C_1 to be output insert 0. on input sheet. For C_1 to be input, determine C_1 as follows:

For pole heads with only one radius, C_1 is obtained from curve #4. The abscissa is "pole embrace" (α) = (77). The graphical flux plotting method of determining C_1 is explained in the section titled "Derivations" in the Appendix.

(72) C_W

WINDING CONSTANT - The ratio of the RMS line voltage for a full pitched winding to that which would be introduced in all the conductors in series if the density were uniform and equal to the maximum value. This value can be an input or output. For C_W to be an output, insert 0. on input sheet. For C_W to be an input, calculate as follows:

$$C_W = \frac{(E)(C_1)(K_d)}{\sqrt{2} (E_{PH})(m)} = \frac{(3)(71)(43)}{\sqrt{2} (4)(5)}$$

Assuming $K_d = .955$, then $C_W = .225 C_1$ for three phase delta machines and $C_W = .390 C_1$ for three phase star machines.

(73) C_P

POLE CONSTANT - The ratio of the average to the maximum value of the field form. This ratio can be an input or output. For C_P to be an output, insert 0. on input sheet. For C_P to be an input, determine as follows:

For pole heads with more than one radius C_P is calculated from the same field form that was used to determine C_1 , and this method is described in the section titled "Derivations" in the Appendix. For pole heads with only one radius C_P is obtained from curve #4. Note the correction factor at the top of the curve.

(74) C_M

DEMAGNETIZING FACTOR - direct axis - This factor can be an input or output. For C_M to be an output, insert 0. on input sheet. For C_M to be an input, determine as follows:

$$C_M = \frac{(\alpha)\pi + \sin[(\alpha)\pi]}{4 \sin[(\alpha)\pi/2]} = \frac{(77)\pi + \sin[(77)\pi]}{4 \sin[(77)\pi/2]}$$

C_M can also be obtained from curve 9.

(75) C_q

CROSS MAGNETIZING FACTOR - quadrature axis - This factor can be an input or output. For C_q to be an output, insert 0. on input sheet. For C_q to be an input, determine as follows:

$$C_q = \frac{1/2 \cos[(\alpha)\pi/2] + (\alpha)\pi - \sin[(\alpha)\pi]}{4 \sin[(\alpha)\pi/2]} \quad \left. \begin{array}{l} \text{VALID FOR} \\ \text{CONCENTRIC} \\ \text{POLES.} \end{array} \right\}$$

$$= \frac{1/2 \cos[(77)\pi/2] + (77)\pi - \sin[(77)\pi]}{4 \sin[(77)\pi/2]}$$

C_q can also be obtained from curve 9.

(76) --

POLE DIMENSIONS LOCATIONS per Figure 2

Where:

b_h = width of pole head

b_p = width of pole body

h_h = height of pole head at center

h_f = height of pole body

ℓ_p = length of pole body

ℓ_n = length of pole head




Fig. 2

all dimensions in inches

(77) α

POLE EMBRACE

$$\alpha = \frac{b_h}{\tau_p} = \frac{(76)}{(41)}$$

(78) A

AMPERE CONDUCTORS per inch - The effective ampere conductors per inch of stator periphery. This factor indicates the "specific loading" of the machine. Its value will increase with the rating and size of the machine and also will increase with the number of poles. It will decrease with increases in voltage or frequency. A is generally higher in single phase machines than in polyphase ones.

$$A = \frac{(I_{PH})(n_s)(K_P)}{(C)(\tau_s)} = \frac{(8)(30)(44)}{(32)(26)}$$

(79) X

REACTANCE FACTOR - The reactance factor is the quantity by which the specific permeance must be multiplied to give percent reactance. It is the percent reactance for unit specific permeance, or the percent of normal voltage induced by a fundamental flux per pole per inch numerically equal to the fundamental armature ampere turns at rated current. Specific permeance is defined as the average flux per pole per inch of core length produced by unit ampere turns per pole.

$$X = \frac{100(A)(K_d)}{\sqrt{2}(C_1)(B_g) \times 10^3} = \frac{100(78)(43)}{\sqrt{2}(71)(125) \times 10^3}$$

(80) X_ℓ

LEAKAGE REACTANCE - The leakage reactance of the stator for steady state conditions. When (5) = 3, calculate as follows:

$$X_\ell = X[(\lambda_i) + (\lambda_E)] = (79)[(62) + (64)]$$

In the case of two phase machines a component due to belt leakage must be included in the stator leakage reactance. This component is due to the harmonics

caused by the concentration of the MMF into a small number of phase belts per pole and is negligible for three phase machines. When (5) = 2, calculate as follows:

$$\lambda_B = \frac{0.1(d)}{(P)(g_e)} \left[\frac{\sin \left[\frac{3(y)}{(m)(q)} \right] 90^\circ}{(K_p)} \right] = \frac{0.1(11)}{(6)(69)} \left[\frac{\sin \left[\frac{3(31)}{(5)(25)} \right] 90^\circ}{(44)} \right]$$

$$X_\ell = X \left[(\lambda_i) + (\lambda_E) + (\lambda_B) \right] \text{ where } \lambda_B = 0 \text{ for 3 phase machines.}$$

$$X_\ell = (79) \left[(62) + (64) + (80) \right]$$

(81) X_{ad} REACTANCE - direct axis - This is the fictitious reactance due to armature reaction in the direct axis.

$$X_{ad} = (X)(\lambda_a)(C_1)(C_M) = (79)(70)(71)(74)$$

(82) X_{aq} REACTANCE - quadrature axis - This is the fictitious reactance due to armature reaction in the direct axis.

$$X_{aq} = (X)(C_q)(\lambda_a) = (79)(75)(70)$$

(83) X_d SYNCHRONOUS REACTANCE - direct axis - The steady state short circuit reactance in the direct axis.

$$X_d = (X_\ell) + (X_{ad}) = (80) + (81)$$

(84) X_q SYNCHRONOUS REACTANCE - quadrature axis - The steady state short circuit reactance in the quadrature axis.

$$X_q = (X_\ell) + (X_{aq}) = (80) + (82)$$

(85) a_p POLE AREA - The effective cross sectional area of the pole.

$$a_p = (b_p)(\ell_p)(K_1) = (76)(76)(16)$$

(86)

 λ_{el} POLE END LEAKAGE PERMEANCE

$$\lambda_{el} = \left\{ \frac{2[(\ell_n) - (\ell)] + (h_f) = .25(b_p)}{\ell} \right\}$$

$$= \left\{ \frac{2[(76) - (13)] + (76) + .25(76)}{(13)} \right\}$$

(87)

 λ_{tl} POLE TIP LEAKAGE PERMEANCE

$$\lambda_{tl} = \left\{ \frac{2[(h_h) + (g) - (\tau_p)/18]}{(\tau_p) - (b_h)} \right\}$$

$$= \left\{ \frac{2[(76) + (59) - (41)/18]}{(41) - (76)} \right\}$$

(88)


 λ_{sl} POLE SIDE LEAKAGE PERMEANCE

$$s = \left\{ \frac{(h_f)}{\pi/(P)[(d_r) - 2(h_h) - .5(h_f)] - (b_p)} \right\}$$

$$= \left\{ \frac{(76)}{\pi/(6)[(11a) - 2(76) - .5(76)] - (76)} \right\}$$

(89)

--

DAMPER SLOT DIMENSIONS b_{bo} - width of slot opening h_{bo} - height of slot opening h_b - diameter of round slot h_{b1} - height of bar section of slot b_{b1} - width of rectangular slot

| | | |
|------|------------------------|---|
| (90) | -- | <u>DAMPER BAR DIA OR WIDTH</u> in inches |
| (91) | h_{b1} | <u>DAMPER BAR THICKNESS</u> in inches - Damper bar thickness considered equal to damper bar slot height (h_b) per item (89). Set this item = 0 for round bar. |
| (92) | n_b | <u>NUMBER OF DAMPER BARS PER POLE</u> |
| (93) | l_b | <u>DAMPER BAR LENGTH</u> in inches |
| (94) | τ_b | <u>DAMPER BAR PITCH</u> in inches |
| (95) | ρ_D | <u>RESISTIVITY</u> of damper bar @ 20°C in ohm-inches - Refer to table given in item (51) for conversion factors. |
| (96) | $X_D^{\circ}\text{C}$ | <u>DAMPER BAR TEMP</u> °C - Input temp at which damper losses are to be calculated. |
| (97) | $\rho_{D(\text{hot})}$ | RESISTIVITY of damper bar @ $X_D^{\circ}\text{C}$ $\rho_{D(\text{hot})} = (\rho_D) \left[\frac{(X_D^{\circ}\text{C}) + 234.5}{254.5} \right] = (95) \left[\frac{(96) + 234.5}{254.5} \right]$ |
| (98) | a_{cd} | <u>CONDUCTOR AREA OF DAMPER BAR</u> - Calculate same as stator conductor area At (46) except substitute $\begin{cases} (91) \text{ for } (39) \\ (90) \text{ for } (33) \end{cases}$ If (91) = 0 $a_{cd} = .25 \pi (\text{damper bar dia})^2 = .25 \pi (90)^2$ If (91) \neq 0 $a_{cd} = (h_{b1}) (\text{damper bar width}) = (91)(90)$ |

| | | |
|-------|-----------------------|--|
| (98a) | V_r | <p><u>PERIPHERAL SPEED</u> - The velocity of the rotor surface in feet per minute</p> $V_r = \frac{\pi(d_r)(\text{RPM})}{12} = \frac{\pi(11a)(7)}{12}$ |
| (99) | N_P | <u>NUMBER OF FIELD TURNS PER POLE</u> |
| (100) | ℓ_{tr} | <u>MEAN LENGTH OF FIELD TURN</u> |
| (101) | -- | <u>FIELD CONDUCTOR DIA OR WIDTH</u> in inches |
| (102) | -- | <u>FIELD CONDUCTOR THICKNESS</u> in inches - Set this item = 0. for round conductor |
| (103) | $X_f^{\circ}\text{C}$ | <u>FIELD TEMP IN $^{\circ}\text{C}$</u> - Input temp at which full load field loss is to be calculated. |
| (104) | ρ_f | <u>RESISTIVITY</u> of rotor field conductor @ 20°C in micro ohm-inches. Refer to table given in item (51) for conversion factors. |
| (105) | ρ_f (hot) | <p><u>RESISTIVITY</u> of rotor field conductor at $X_f^{\circ}\text{C}$</p> $\rho_f(\text{hot}) = \rho_f \left[\frac{(X_f^{\circ}\text{C}) + 234.5}{254.5} \right] = (104) \left[\frac{(103) + 234.5}{254.5} \right]$ |
| (106) | a_{cf} | <p><u>CONDUCTOR AREA OF ROTOR FIELD WDG</u> - Calculate same as stator conductor area (46) except substitute</p> $\begin{cases} (102) \text{ for } (39) \\ (101) \text{ for } (33) \end{cases}$ |
| (107) | R_f (cold) | <p><u>COLD FIELD RESISTANCE @ 20°C</u></p> $R_f(\text{cold}) = (\rho_f) \frac{(N_P)(P)(\ell_{tr})}{(a_{cf})} = (104) \frac{(99)(6)(100)}{(106)}$ |

(108) R_f (hot) HOT FIELD RESISTANCE - Calculated at $X_f^0 C$ (103)

$$R_f \text{ (hot)} = (\rho_{f \text{ hot}}) \frac{(N_p)(P)(\ell_{tr})}{(a_{cf})} = (105) \frac{(99)(6)(100)}{(106)}$$

(108a) -- WEIGHT OF ROTOR FIELD COPPER in lbs

$$\begin{aligned} \# \text{'s of copper} &= .321(N_p)(P)(\ell_{tr})(a_{cf}) \\ &= .321(99)(6)(100)(106) \end{aligned}$$

(108b) -- WEIGHT OF ROTOR IRON - Because of the large number of different pole shapes, one standard formula cannot be used for calculating rotor iron weight. Therefore the computer will not calculate rotor iron weight. The space is allowed on the input sheet for record purposes only. By inserting 0. in the space allowed for rotor iron weight, the computer will show "0." on the output sheet. If the rotor iron weight is available and inserted on input sheet, then the output sheet will show this same weight on the output sheet.

(109) λ_b PERMEANCE OF DAMPER BAR - The permeance of that portion of the damper bar that is embedded in pole iron.

For round slot

$$\lambda_b = 6.38 \left[\frac{(h_{bo})}{(b_{bo})} + .62 + .5 \right] = 6.38 \left[\frac{(89)}{(89)} + .62 + .5 \right]$$

For rectangular slot

$$\lambda_b = 6.38 \left[\frac{(h_{bo})}{(b_{bo})} + \frac{(h_{b1})}{3(b_{b1})} + .5 \right] = 6.38 \left[\frac{(89)}{(89)} + \frac{(89)}{3(89)} + .5 \right]$$

(110) λ_{pt} PERMEANCE OF END PORTION OF DAMPER BARS

$$\lambda_{pt} = 6.38 \left\{ \frac{(b_h) - (\tau_b) [(n_b) - 1]}{3(g_e)} \right\}$$

$$= 6.38 \left\{ \frac{(76) - (94) [(92) - 1]}{3(69)} \right\}$$

(111) λ_F ROTOR LEAKAGE PERMEANCE

$$\lambda_F = 4.25 [(\lambda_s) + 1.5(\lambda_{t\ell})] + 6.38(\lambda_{e\ell})$$

$$= 4.25 [(88) + 1.5(87)] + 6.38(86)$$

(112) X_F FIELD LEAKAGE REACTANCE

$$X_F = (X_{ad}) \left[1 - \frac{[(C_1)/(C_m)]}{2(C_p) + \frac{4(\lambda_F)}{\pi(\lambda_a)}} \right]$$

$$= (81) \left[1 - \frac{[(71)/(74)]}{2(73) + \frac{4(111)}{\pi(70)}} \right]$$

(113) L_f FIELD SELF INDUCTANCE

$$L_f = (N_P)^2 (P)(\ell_P) \left[(C_P)(\lambda_a) \frac{\pi}{2} + (\lambda_f) \right] \times 10^{-8}$$

$$= (99)^2 (6)(76) \left[(73)(70) \frac{\pi}{2} + (111) \right] \times 10^{-8}$$

(114) λ_{Dd} PERMEANCE OF DAMPER BAR - in direct axis

$$\lambda_{Dd} = \left\{ \cos \left[\frac{\{(n_b) - 1\} (\tau_b) \pi}{2(\tau_p)} \right] \right\} \left\{ \frac{\{(\lambda_b) + (\lambda_{Pt})\} (\lambda_F)}{\lambda_b + \lambda_{Pt} + \lambda_F} \right\}$$

$$= \left\{ \cos \left[\frac{\{(92) - 1\} (94)}{2(94)} \right] \right\} \left\{ \frac{\{(109) + (110)\} (111)}{(109) + (110) (111)} \right\}$$

(115) X_{Dd} DAMPER LEAKAGE REACTANCE - in direct axis

$$X_{Dd} = X(\lambda_{Dd}) = (79)(114)$$

(116) λ_{Dq} PERMEANCE IN QUADRATURE AXIS

For round slot

$$\lambda_{Dq} = \frac{20(\tau_b)}{(\tau_p)} \left[\frac{(h_{bo})}{(b_{bo})} + .62 + .5 + \frac{(g)}{(\tau_b)} \right]$$

$$= \frac{20(94)}{(41)} \left[\frac{(89)}{(89)} + .62 + .5 + \frac{(59)}{(94)} \right]$$

For rectangular slot

$$\lambda_{(Dq)} = \frac{20(\tau_b)}{(\tau_p)} \left[\frac{(h_{bo})}{(b_{bo})} + \frac{(h_{b1})}{3(b_{b1})} + .5 + \frac{(g)}{(\tau_b)} \right]$$

$$= \frac{20(94)}{(41)} \left[\frac{(89)}{(89)} + \frac{(89)}{3(89)} + .5 + \frac{(59)}{(94)} \right]$$

(117) X_{Dq} DAMPER LEAKAGE REACTANCE - in quadrature axis

$$X_{Dq} = X(\lambda_{Dq}) = (79)(116)$$

(118) X'_{du} UNSATURATED TRANSIENT REACTANCE

$$X'_{du} = (X_l) + (X_f) = (80) + (112)$$

(119) X_d' SATURATED TRANSIENT REACTANCE

$$X_d' = .88(X_{du}') = .88(118)$$

(120) X_d'' SUBTRANSIENT REACTANCE in direct axis

When damper bars exist, i.e. when (92) $\neq 0$

$$X_d'' = (X_\ell) + (X_{Dd}) = (80) + (115)$$

When no damper bars exist, i.e. when (92) = 0

$$X_d'' = (X_d') = (119)$$

(121) X_q'' SUBTRANSIENT REACTANCE in quadrature axis

When damper bar exists, i.e. when (92) $\neq 0$

$$X_q'' = (X_\ell) + (X_{Dq}) = (80) + (116)$$

When no damper bars exist, i.e. when (92) = 0

$$X_q'' = X_q = (84)$$

(122) X_2

NEGATIVE SEQUENCE REACTANCE - The reactance due to the field which rotates at synchronous speed in a direction opposite to that of the rotor.

$$X_2 = .5 [X_d'' + X_q''] = .5 [(120) + (121)]$$

(123) X_0

ZERO SEQUENCE REACTANCE - The reactance drop across any one phase (star connected) for unit current in each of the phases. The machine must be star connected for otherwise no zero sequence current can flow and the term then has no significance.

If (28) = 0 Then $X_o = 0$

If (28) $\neq 0$ Then

$$X_o = X \left\{ \frac{(K_{xo})}{(K_{x1})} [(\lambda_i) + (\lambda_{Bo})] + \frac{1.667 [(h_1) + 3(h_3)]}{(m)(q)(K_p)^2 (K_d)^2 (b_s)} + .2(\lambda_E) \right\}$$

$$= (79) \left\{ \frac{(123a)}{(123b)} [(62) + (123c)] + \frac{1.667 [(22) + 3(22)]}{(5)(25)(44)^2 (43)^2 (22)} + .2(64) \right\}$$

(123a) K_{xo}

If (30) = 1 Then $K_{xo} = 1$

If (30) $\neq 1$ Then $K_{xo} = \frac{3(\gamma)}{(m)(q)} - 2$

$$= \frac{3(31)}{(5)(25)} - 2$$

(123b) K_{x1}

If (30) = 1 Then $K_{x1} = 1$

If (30) $\neq 1$ Then:

$$K_{x1} = \left[\frac{3(\gamma)}{4(m)(q)} + \frac{1}{4} \right] = \left[\frac{3(31)}{4(5)(25)} + \frac{1}{4} \right] \quad \text{If (31a)} \geq .667$$

$$K_{x1} = \left[\frac{3(\gamma)}{4(m)(q)} - \frac{1}{4} \right] = \left[\frac{3(31)}{4(5)(25)} - \frac{1}{4} \right] \quad \text{If (31a)} < .667$$

(123c) λ_{Bo}

If (92) = 0 Then:

$$\lambda_{Bo} = \frac{(K_{xo})}{(K_p)^2} [.07(\lambda_a)] = \frac{(123a)}{(44)^2} [.07(70)]$$

If (92) $\neq 0$ Then $\lambda_{Bo} = \frac{\frac{(K_{xo})}{(K_{x1})} (\lambda_{Dq}) + \frac{(K_{xo})}{(K_p)^2} [.07(\lambda_a)]}{\left\{ \frac{(K_{xo})}{(K_{x1})} (\lambda_{Dq}) \right\} \left\{ \frac{(K_{xo})}{(K_p)^2} [.07(\lambda_a)] \right\}}$

$$\frac{\frac{(123a)}{(123b)} (116) + \frac{(123a)}{(44)^2} [.07(70)]}{\left\{ \frac{(123a)}{(123b)} (116) \right\} \left\{ \frac{(123a)}{(44)^2} [.07(70)] \right\}}$$

(124) ϕ_T TOTAL FLUX IN KILO LINES

$$\phi_T = \frac{6(E)10^6}{(C_w)(n_e)(RPM)} = \frac{6(3)10^6}{(72)(45)(17)}$$

(125) B_g GAP DENSITY in Kilo Lines/in² - The maximum flux density in the air gap

$$B_g = \frac{(\phi_T)}{\pi(d)(\ell)} = \frac{(124)}{\pi(11)(13)}$$

(126) ϕ_P FLUX PER POLE in Kilo Lines

$$\phi_P = \frac{(\phi_T)(C_P)}{(P)} = \frac{(124)(73)}{(6)}$$

(127) B_t TOOTH DENSITY in Kilo Lines/in² - The flux density in the stator tooth at 1/3 of the distance from the minimum section.

$$B_t = \frac{\phi_T}{(Q)(\ell_s)(b_{t1/3})} = \frac{(124)}{(23)(17)(57a)}$$

(128) B_c CORE DENSITY in Kilo Lines/in² - The flux density in the stator core

$$B_c = \frac{(\phi_P)}{2(h_c)(\ell_s)} = \frac{(126)}{2(24)(17)}$$

(129) F_T STATOR TOOTH AMPERE TURNS

$$F_T = h_s \left[\text{NI/in at density } B_t \right]$$

$$= (22) \left[\text{Look-up on stator magnetization curve given in (18) @ density (127)} \right]$$

(130) F_c STATOR CORE AMPERE TURNS

$$F_c = \left[\frac{\pi[(D) - (h_c)]}{4(P)} \right] \left[\text{NI/in @ density of } B_c \right]$$

$$= \left[\frac{\pi[(12) - (24)]}{4(6)} \right] \left[\text{Look-up on stator magnetization curve given in (18) @ density (128)} \right]$$

(130a) F_s STATOR AMPERE TURNS, total

$$F_s = (F_T) + (F_c) = (129) + (130)$$

(131) F_g

AIR GAP AMPERE TURNS - The field ampere turns per pole required to force flux across the air gap when operating at no load with rated voltage.

$$F_g = \frac{(B_g)(g_e)}{3.19} = \frac{(125)(69)}{3.19}$$

(132) T'_{do}

OPEN CIRCUIT TIME CONSTANT - The time constant of the field winding with the stator open circuited and with negligible external resistance and inductance in the field circuit. Field resistance at room temperature (20°C) is used in this calculation.

$$T'_{do} = \frac{L_F}{R_F} = \frac{(113)}{(107)}$$

| | | |
|-------|----------|--|
| (133) | T_a | <p><u>ARMATURE TIME CONSTANT</u> - Time constant of the D.C. component. In this calculation stator resistance at room temperature (20°C) is used.</p> $T_a = \frac{X_2}{200\pi(f)(r_a)} = \frac{(122)}{200\pi(5a)(133)}$ <p>where $r_a = \frac{(m)(I_{PH})^2(R_{SPH \text{ cold}})}{\text{Rated KVA}} = \frac{(5)(8)^2(53)}{(2)}$</p> |
| (134) | T_d' | <p><u>TRANSIENT TIME CONSTANT</u> - The time constant of the transient reactance component of the alternating wave.</p> $T_d' = \frac{(X_d')}{(X_d)} (T_{do}') = \frac{(119)}{(83)} (132)$ |
| (135) | T_d'' | <p><u>SUBTRANSIENT TIME CONSTANT</u> - The time constant of the subtransient component of the alternating wave. This value has been determined empirically from tests on large machines. Use following values.</p> $T_d'' = .035 \text{ second at 60 cycle}$ $T_d'' = .005 \text{ second at 400 cycle}$ |
| (136) | F_{SC} | <p><u>SHORT CIRCUIT AMPERE TURNS</u> - The field ampere turns required to circulate rated stator current when the stator is short circuited.</p> $F_{SC} = (X_d)(F_g) = (83)(131)$ |
| (137) | SCR | <p><u>SHORT CIRCUIT RATIO</u> - The ratio of the field current to produce rated voltage on open circuit to the field current required to produce rated current on short circuit.</p> |

Since the voltage regulation depends on the leakage reactance and the armature reaction, it is closely related to the current which the machine produces under short circuit conditions, and therefore is directly related to the SCR.

$$\text{SCR} = \frac{F_{\text{NL}}}{F_{\text{SC}}} = \frac{(142)}{(136)}$$

The items to follow (138) to (158) are to be calculated for variable loads. The first set of calculations are at no load. These calculations will then be repeated for 100% load. From then on any variation in load would be a repeat of the 100% load calculations with the proper percent load inserted.

(138) ϕ_{ℓ}

LEAKAGE FLUX - at no load

$$\begin{aligned}\phi_{\ell} &= .00638 \left[(\lambda_{s\ell}) + (\lambda_{e\ell}) + (\lambda_{t\ell}) \right] \left[(F_g) + (F_S) \right] (\ell_P) \\ &= .00638 \left[(88) + (86) + (87) \right] \left[(131) + (130a) \right] (76)\end{aligned}$$

(139) ϕ_{PT}

TOTAL FLUX PER POLE - at no load

$$\phi_{\text{PT}} = \phi_P + \phi_{\ell} = (126) + (138)$$

(140) B_P

POLE DENSITY - The apparent flux density at the base of the pole. Note that no provision is made in this manual for calculating the density in the spider section. It is therefore important to remember not to restrict the flux area through this section.

$$B_P = \frac{(\phi_{PT})}{(a_P)} = \frac{(139)}{(85)}$$

(141) F_P

POLE AMPERE TURNS - at no load. The ampere turns per pole required to force the flux through the pole and spider at no load rated voltage. In general the spider density is kept fairly low and its ampere turns can be neglected. The no load pole ampere turns per pole are calculated as the product of $(h_f) + (h_h)$ times the NI per inch at the density (B_P) . Use magnetization curve submitted per item (18) for rotor.

$$\begin{aligned} F_P &= [(h_f) + (h_h)] [NI/in @ \text{density } (B_P)] \\ &= [(76) + (76)] [\text{Look-up on rotor magnetization} \\ &\quad \text{curve given in (18) @ density (140)}] \end{aligned}$$

(142) F_{NL}

TOTAL AMPERE TURNS - at no load. The total ampere turns per pole required to produce rated voltage at no load.

$$F_{NL} = [(F_g) + (F_S) + (F_P)] = [(131) + (130a) + (141)]$$

(143) I_{FNL}

FIELD CURRENT - at no load

$$I_{FNL} = (F_{NL}) / (N_P) = (142) / (99)$$

(144) S_F

CURRENT DENSITY - at no load. Amperes per square inch of field conductor.

$$S_F = (I_{FNL}) / (a_{cf}) = (143) / (106)$$

| | | |
|-------|-----------|--|
| (145) | E_F | <p><u>FIELD VOLTS</u> - at no load. This calculation is made with cold field resistance at 20°C for no load condition.</p> $E_F = (I_{FNL})(R_{f \text{ cold}}) = (143)(107)$ |
| (146) | $I^2 R_R$ | <p><u>ROTOR $I^2 R$</u> - at no load. The copper loss in the field winding is calculated with cold field resistance at 20°C for no load condition.</p> $\text{Rotor } I^2 R = (I_{FNL})^2 (R_{f \text{ cold}}) = (143)^2 (107)$ |
| (147) | F & W | <p><u>FRICTION & WINDAGE LOSS</u> - There is no known calculation method that will give accurate results for this loss. The best results are obtained by using existing data. For ratioing purposes, the loss can be assumed to vary approximately as the 5/2 power of the rotor diameter and as the 3/2 power of the RPM. When no existing data is available, the following calculation can be used for an approximate answer. Insert 0. when computer is to calculate F & W. Insert actual F & W when available. Use same value for all load conditions.</p> $F \& W = 2.52 \times 10^{-6} (d_r)^{2.5} (\ell_h) (\text{RPM})^{1.5}$ $= 2.52 \times 10^{-6} (11a)^{2.5} (76) (7)^{1.5}$ |
| (148) | W_{TNL} | <p><u>STATOR TEETH LOSS</u> - at no load. The no load loss (W_{TNL}) consists of eddy current and hysteresis losses in the iron. For a given frequency the no load tooth loss will vary as the square of the flux density.</p> |

$$W_{TNL} = .453(b_t 1/3)(Q)(l_s)(h_s)(K_Q)$$

$$= .453(57a)(23)(17)(22)(148)$$

$$\text{Where } K_Q = (k) \left[\frac{(B_t)}{(B)} \right]^2 = (19) \left[\frac{(127)}{(20)} \right]^2$$

(149) W_c

STATOR CORE LOSS - The stator core losses are due to eddy currents and hysteresis and do not change under load conditions. For a given frequency the core loss will vary as the square of the flux density (B_c).

$$W_c = 1.42 \left[(D) - (h_c) \right] (h_c)(l_s)(K_Q)$$

$$= 1.42 \left[(12) - (24) \right] (24)(17)(149)$$

$$\text{Where } K_Q = (k) \left[\frac{(B_c)}{(B)} \right]^2 = (19) \left[\frac{(128)}{(20)} \right]^2$$

(150) W_{NPL}

POLE FACE LOSS - at no load. The pole surface losses are due to slot ripple caused by the stator slots. They depend upon the width of the stator slot opening, the air gap, and the stator slot ripple frequency. The no load pole face loss (W_{PNL}) can be obtained from Graph 2. Graph 2 is plotted on the bases of open slots. In order to apply this curve to partially open slots, substitute b_o for b_s . For a better understanding of Graph 2, use the following sample.

K_1 as given on Graph 2 is derived empirically and depends on lamination material and thickness. Those values given on Graph 2 have been used with success. K_1 is an input and must be specified. See item (151) for values of K_1 .

(150) (Cont.)

K_2 is shown as being plotted as a function of $(B_G)^{2.5}$. Also note that upper scale is to be used. Another note in the lower right hand corner of graph indicates that for a solid line (—), the factor is read from the left scale, and for a broken or dashed line (— ~ — ~), the right scale should be read. For example, find K_2 when $B_G = 30$ kilo lines. First locate 30 on upper scale. Read down to the intersection of solid line plot of $K_2 = f(B_G)^{2.5}$. At this intersection read the left scale for K_2 . $K_2 = .28$. Also refer to item (152) for K_2 calculations.

K_3 is shown as a solid line plot as a function of $(F_{SLT})^{1.65}$. The note on this plot indicates that the upper scale X 10 should be used. Note F_{SLT} = slot frequency. For an example, find K_3 when $F_{SLT} = 1000$. Use upper scale X 10 to locate 1000. Read down to intersection of solid line plot of $K_3 = f(F_{SLT})^{1.65}$. At this intersection read the left scale for K_3 . $K_3 = 1.35$. Also refer to item (153) for K_3 calculations.

For K_4 use same procedure as outlined above except use lower scale. Do not confuse the dashed line in this plot with the note to use the right scale. The note does not apply in this case. Read left scale. Also refer to item (154) for K_4 calculations.

For K_5 use bottom scale and substitute b_o for b_s when using partially closed slot. Read left scale when using solid plot. Use right scale when using dashed plot. Also refer to item (155) for K_5 calculations.

(150) (Cont.)

For K_6 use the scale attached for C_1 and read K_6 from left scale. Also refer to item (156) for K_6 calculations.

The above factors (K_2), (K_3), (K_4), (K_5), (K_6) can also be calculated as shown in (152), (153), (154), (155), (156), respectively.

$$W_{PNL} = \pi(d)(\ell)(K_1)(K_2)(K_3)(K_4)(K_5)(K_6)$$

$$= \pi(11)(13)(151)(152)(153)(154)(155)(156)$$

(151) K_1

K_1 is derived empirically and depends on lamination material and thickness. The values used successfully for K_1 are shown on Graph 2. They are

$$\begin{aligned} K_1 &= 1.17 \text{ for } .028 \text{ lam thickness, low carbon steel} \\ &= 1.75 \text{ for } .063 \text{ lam thickness, low carbon steel} \\ &= 3.5 \text{ for } .125 \text{ lam thickness, low carbon steel} \\ &= 7.0 \text{ for solid core} \end{aligned}$$

K_1 is an input and must be specified on input sheet.

(152) K_2

K_2 can be obtained from Graph 2 (see item 150) for explanation of Graph 2) or it can be calculated as follows:

$$\begin{aligned} K_2 &= f(B_G) = 6.1 \times 10^{-5} (B_G)^{2.5} \\ &= 6.1 \times 10^{-5} (125)^{2.5} \end{aligned}$$

(153) K_3

K_3 can be obtained from Graph 2 (see item 150) for explanation of Graph 2) or it can be calculated as follows:

$$\begin{aligned} K_3 &= f(F_{SLT}) = 1.5147 \times 10^{-5} (F_{SLT})^{1.65} \\ &= 1.5147 \times 10^{-5} (153)^{1.65} \end{aligned}$$

$$\begin{aligned} \text{Where } F_{SLT} &= \frac{(RPM)}{60} (Q) \\ &= \frac{(7)}{60} (23) \end{aligned}$$

(154) K_4

K_4 can be obtained from Graph 2 (see item (150) for explanation of Graph 2) or it can be calculated as follows:

For $\tau_s \leq .9$

$$\begin{aligned} K_4 &= f(\tau_s) = .81(\tau_s)^{1.285} \\ &= .81(26)^{1.285} \end{aligned}$$

For $.9 \leq \tau_s \leq 2.0$

$$\begin{aligned} K_4 &= f(\tau_s) = .79(\tau_s)^{1.145} \\ &= .79(26)^{1.145} \end{aligned}$$

For $\tau_s > 2.0$

$$\begin{aligned} K_4 &= f(\tau_s) = .92(\tau_s)^{.79} \\ &= .92(26)^{.79} \end{aligned}$$

(155) K_5

K_5 can be obtained from Graph 2 (see item (150) for explanation of Graph 2) or it can be calculated as follows:

For $(b_s)/(g) \leq 1.7$

$$\begin{aligned} K_5 &= f(b_s/g) = .3 \left[(b_s)/(g) \right]^{2.31} \\ &= .3 \left[(22)/(59) \right]^{2.31} \end{aligned}$$

NOTE: For partially open slots substitute b_o for b_s in equations shown.

For $1.7 < (b_s)/(g) \leq 3$

$$\begin{aligned} K_5 &= f(b_s)/(g) = .35 \left[(b_s)/(g) \right]^2 \\ &= .35 \left[(22)/(59) \right]^2 \end{aligned}$$

For $3 < (b_s) / (g) \leq 5$

$$K_5 = f(b_s) / (g) = .625 \left[(b_s) / (g) \right]^{1.4}$$

$$= .625 \left[(22) / (59) \right]^{1.4}$$

For $(b_s) / (g) > 5$

$$K_5 = f \left[(b_s) / (g) \right] = 1.38 \left[(b_s) / (g) \right]^{.965}$$

$$= 1.38 \left[(22) / (59) \right]^{.965}$$

(156) K_6

K_6 can be obtained from Graph 2 (see item (150) for explanation of Graph 2) or it can be calculated as follows:

$$K_6 = f(C_1) = 10 \left[.9323(C_1) - 1.60596 \right]$$

$$= 10 \left[.9323(71) - 1.60596 \right]$$

(157) W_{DNL}

DAMPER LOSS - at no load at 20°C . This loss is produced by slot ripple in the damper winding. At no load this loss is calculated from curves 7 and 8.

$$W_{DNL} = \frac{1.246(P)(n_b)(\ell_b)(\rho_D)}{(a_{cr}) \times 10^3} \left[(\tau_s)(B_g)(K_{P1})(K_g) \right]^2$$

$$\left\{ (K_{f1}) \left[\frac{K_{W1}}{2(\lambda_s) + [(\lambda_g) / (K_{\phi 1})]} \right]^2 \right.$$

$$\left. + (K_{f2}) \left[\frac{(K_{W2})}{2(\lambda_s) + [(\lambda_g) / (K_{\phi 2})]} \right]^2 \right\}$$

$$W_{DNL} = \frac{1.246(6)(92)(93)(95)}{(98) \times 10^3} \left[(26)(125)(157)(157) \right]^2$$

$$\left\{ (157) \left[\frac{(157)}{2(157) + [(157) / (157)]} \right]^2 \right. + (157) \left[\frac{(157)}{2(157) + [(157) / (157)]} \right]^2 \left. \right\}$$

(157) (Cont.)

$$\begin{aligned} \text{Where } K_{P1} &= 1 - \frac{1}{\sqrt{1 + [(b_s)/2(g)]^2}} \\ &= 1 - \frac{1}{\sqrt{1 + [(22)/2(59)]^2}} \end{aligned}$$

NOTE: Substitute b_o for b_s when partially opened stator slot is used.

K_{P1} can also be obtained from curve 7 where abscissa is $(b_s)/(g)$ or $(b_o)/(g) = (22)/(59)$

$$\text{Where } K_g = (K_s) = (67)$$

$$\text{Where } g' = (K_g)(g) = (157)(59)$$

Where K_{f1} & K_{f2} are obtained from curve 7

Where the abscissa is S_1 or S_2

$$S_1 = 3.2 \sqrt{\frac{(f_{S1})}{(D)}} = 3.2 \sqrt{\frac{(157)}{(95)}}$$

$$S_2 = 3.2 \sqrt{\frac{(f_{S2})}{(D)}} = 3.2 \sqrt{\frac{(157)}{(95)}}$$

$$\text{Where } f_{S1} = 2qmf = 2(25)(5)(5a)$$

$$f_{S2} = 2(f_{S1})$$

Where K_{W1} and K_{W2} are obtained from curve 8.
where the abscissa is $(b_s)/(\tau_s)$ for open slots or
 $(b_o)/(\tau_s)$ for semi-enclosed slots $(b_s)/(\tau_s) =$
 $(22)/(26)$

(157) (Cont.)

Where λ_t is obtained from curve 8

Where the abscissa is $(b_{bo}) / (g') = \frac{(89)}{(157)}$

When 91 = 0 or when (90) = (91)

$$\lambda_C = \frac{.75}{(K_{f1})} = \frac{.75}{(157)} \text{ For round or square slots}$$

When 91 \neq 0 and when (90) \neq (91)

$$\lambda_C = \frac{(h_{b1})}{3(b_{b1})(K_{f1})} = \frac{(91)}{3(89)(157)}$$

$$\text{Where } \lambda_S = \frac{(h_{bo})}{(b_{bo})} + (\lambda_t) + (\lambda_C)$$

$$= \frac{(89)}{(89)} + (157) + (157)$$

$$\text{Where } \lambda_g = \frac{\tau_b}{g'} = \frac{(94)}{(157)}$$

Where $K_{\phi 1}$ and $K_{\phi 2}$ are obtained from curve 8

Where the abscissa is $(\tau_b) / (\tau_s) = (94) / (26)$

(158) I^2R

STATOR I^2R - at no load. This item = 0. Refer to item (173) for 100% load stator I^2R .

(158a) --

EDDY LOSS - at no load. This item = 0. Refer to item (173a) for 100% load eddy loss.

(159) --

TOTAL LOSSES - at no load. Sum of all losses

$$\begin{aligned} \text{Total losses} &= (\text{Rotor } I^2R) + (F \& W) + (\text{Stator Teeth Loss}) \\ &+ (\text{Stator Core Loss}) + (\text{Pole Face Loss}) \\ &+ (\text{Damper Loss}) \end{aligned}$$

$$= (146) + (147) + (148) + (149) + (150) + (157)$$

NOTE: The output sheet shows the next items to be:
 (Rating), (Rating + Losses), (% Losses), (% Efficiency).
 These items do not apply to the no load calculation
 since the rating is zero. Refer to items (175), (176),
 (177), (178) for these calculations under load.

Item (138) through (159) have been calculated for 0%
 load or no load. They should all be repeated now for
 100% load.

(160) ϕ_{ll}

LEAKAGE FLUX PER POLE at 100% load

$$\phi_{ll} = \phi_l \left\{ \frac{(e_d)(F_g) + [1 + \cos(\theta)](F_T) + (F_C)}{(F_g) + (F_T) + (F_C)} \right\}$$

$$= (138) \frac{(160a)(131) + [1 + \cos(160b)](129) + (130)}{(131) + (129) + (130)}$$

(160a) e_d

Where $e_d = \cos \epsilon + (X_d) \sin \psi$

$$= \cos (160b) + (83) \sin (160b)$$

(160b) θ

Where $\theta = \cos^{-1} [\text{Power Factor}]$

$$= \cos^{-1} [(9)]$$

Where $\psi = \tan^{-1} \left[\frac{\sin (\theta) + (X_q) / (100)}{\cos (\theta)} \right]$

$$= \tan^{-1} \left[\frac{\sin (160b) + (84) / (100)}{\cos (160b)} \right]$$

Where $\epsilon = \psi - \theta = (160b) - (160b)$

| | | |
|-------|--------------|---|
| (161) | ϕ_{PL} | <p><u>FLUX PER POLE at 100% load</u></p> <p>FOR P.F. 0 TO .95</p> $\phi_{PL} = (\phi_P) \left[(e_d) - \frac{.0093(X_{ad})}{100} \sin(\psi) \right]$ $= (126) \left[(160a) - \frac{.0093(81)}{100} \sin(160b) \right]$ <p>FOR P.F. .95 TO 1.0 $\phi_{PL} = (\phi_P)(K_c) = (126)(9a)$</p> |
| (162) | ϕ_{PTL} | <p><u>TOTAL FLUX PER POLE at 100% load</u></p> $\phi_{PTL} = \phi_{PL} + \phi_{ll} = (161) + (160)$ |
| (163) | B_{PL} | <p><u>FLUX DENSITY AT BASE OF POLE at 100% load</u></p> $B_{PL} = \frac{\phi_{PTL}}{a_P} = \frac{(162)}{(85)}$ |
| (164) | F_{PL} | <p><u>AMPERE TURNS PER POLE at 100% load</u></p> $F_{PL} = [(h_f) + (h_h)] [NI/in @ density (B_{PL})]$ $= [(76) + (76)] \text{ Look-up ampere turns/inch on rotor magnetization curve given in (18) at density (163)}$ |
| (165) | F_{FL} | <p><u>TOTAL AMPERE TURNS PER POLE at 100% load - The total ampere turns per pole required to produce rated load.</u></p> $F_{FL} = (e_d)(F_g) + [1 + \cos(\theta)] (F_T) + (F_C) + (F_{PL})$ $= (160a)(131) + [1 + \cos(160b)] (129) + (130) + (164)$ |
| (166) | I_{FFL} | <p><u>FIELD CURRENT at 100% load</u></p> $I_{FFL} = (F_{FL}) / (N_P) = (165) / (99)$ |

(167) --

CURRENT DENSITY at 100% load

$$\text{Current Density} = (I_{\text{FFL}}) / (a_{\text{cf}}) = (166) / (106)$$

(168) E_{FFL}

FIELD VOLTS at 100% load - This calculation is made with hot field resistance at expected temperature at 100% load.

$$\text{Field Volts} = (I_{\text{FFL}}) (R_{\text{f hot}}) = (166) (108)$$

(169) $I^2 R_{\text{R}}$

ROTOR $I^2 R$ at 100% load - The copper loss in the field winding is calculated with hot field resistance at expected temperature for 100% load condition.

$$\text{Rotor } I^2 R = (I_{\text{FFL}})^2 (R_{\text{F hot}}) = (166)^2 (108)$$

(170) W_{TFL}

STATOR TEETH LOSS at 100% load - The stator tooth loss under load increases over that of no load because of the parasitic fluxes caused by the ripple due to the rotor damper bar slot openings.

$$W_{\text{TFL}} = \left\{ \left[2.27 (X_{\text{d}}) \right]^{1.8} \frac{(\% \text{ Load})}{100} + 1 \right\} (W_{\text{TNL}})$$

NOTE (X_{d}) is in per unit

$$= \left\{ 2.27 (83) \right\}^{1.8} 1 + 1 \quad (148)$$

(171) W_{PFL}

POLE FACE LOSS at 100% load

$$W_{\text{PFL}} = \left\{ \left[\frac{(K_{\text{sc}}) (I_{\text{PH}}) \frac{(\% \text{ Load})}{100} (n_{\text{s}})}{(C) (F_{\text{g}})} \right]^2 + 1 \right\} (W_{\text{PNL}})$$

$$= \left\{ \left[\frac{(171)(8) 1 (30)}{(32)(131)} \right]^2 + 1 \right\} \quad (150)$$

(K_{sc}) is obtained from Graph 3

(172) W_{DFL} DAMPER LOSS at 100% load

$$W_{DFL} = \left\{ \left[\frac{(K_{sc})(I_{PH}) \frac{(\% \text{ Load})}{100} (n_s)}{(C)(F_g)} \right]^2 + 1 \right\} (W_{DNL}) \times \frac{(\ell_{D \text{ hot}})}{(\ell_{D \text{ cold}})}$$

$$= \left\{ \left[\frac{(172)(8) 1 (30)}{(32)(131)} \right]^2 + 1 \right\} (157) \frac{(97)}{(95)}$$

(K_{sc}) is obtained from Graph 3

(173) I^2R

STATOR I^2R at 100% load - The copper loss based on the D.C. resistance of the winding. Calculate at the maximum expected operating temperature.

$$I^2R = (m)(I_{PH})^2 (R_{SPH \text{ hot}}) \frac{(\% \text{ Load})}{100}$$

$$= (5)(8)^2 (54) 1.$$

(173a) --

EDDY LOSS - Stator I^2R loss due to skin effect

$$\text{Eddy Loss} = \left[\frac{(EF_{\text{top}}) + (EF_{\text{bot}})}{2} - 1 \right] (\text{Stator } I^2R)$$

$$= \left[\frac{(55) - (56)}{2} - 1 \right] (173)$$

(174) --

TOTAL LOSSES at 100% load - sum of all losses at 100% load

$$\begin{aligned} \text{Total Losses} &= (\text{Rotor } I^2R) + (F \& W) + (\text{Stator Teeth Loss}) \\ &+ (\text{Stator Core Loss}) + (\text{Pole Face Loss}) \\ &+ (\text{Damper Loss}) + (\text{Stator } I^2R) + (\text{Eddy Loss}) \\ &= (169) + (147) + (170) + (149) + (171) + (172) + (173) + (173a) \end{aligned}$$

(175) -- RATING IN WATTS at 100% load

$$\text{Rating} = 3(E_{PH})(I_{PH})\sqrt{3} (P.F.) \frac{(\% \text{ Load})}{100}$$

$$= 3(4)(8)\sqrt{3} (9)(1.)$$

(176) -- RATING & Σ LOSSES = (175) + (174)

$$\underline{\% \text{ LOSSES}} = \left[\Sigma \text{ Losses} / \text{Rating} + \Sigma \text{ Losses} \right] 100$$

$$= \left[(174) / (177) \right] 100$$

(178) -- % EFFICIENCY = 100% - % Losses

$$= 100\% - (177)$$

Item (160) through (178) are 100% load calculations.

These items can be recalculated for any load condition by simply inserting the values that correspond to the % load being calculated. The factor $\frac{(\% \text{ Load})}{100}$ takes care of (I_{PH}) as it changes with load.

Note that values for F & W (147) and W_C (Stator Core Loss) (149) do not change with load, therefore they can be calculated only once.

NO-LOAD-SATURATION - The next series of calculations are for the no load saturation where the items are calculated for various voltage conditions. For the purposes of this manual, a sample set of calculations for item (179) through (190) are presented for 150% of rated voltage. The calculations for any other voltage can be obtained by simply using the values that correspond to the % load being calculated.

The no load saturation is not a standard output for the computer. When 0 is inserted in item (179) "No Load Sat" on input sheet, the computer will not calculate the no load saturation. When 1 is inserted in item (179) on input sheet, the computer will calculate the no load saturation at 80, 90, 100, 110, 120, 130, 140, 150, 160% of rated volts. There is a standard output sheet available, therefore the items will be read out to match the sequence of calculations that follow:

(179) -- VOLTS - Line volts

$$\begin{aligned}\text{Volts} &= (\text{Per Unit Voltage})(\text{Rated Voltage}) \\ &= (1.5)(3)\end{aligned}$$

(180) F'_g AIR GAP AMPERE TURNS

$$\begin{aligned}F'_g &= (\text{Per Unit Voltage})(F_g) \\ &= (1.5)(131)\end{aligned}$$

(181) B'_t TOOTH DENSITY

$$\begin{aligned}B'_t &= (\text{Per Unit Voltage})(B_t) \\ &= (1.5)(127)\end{aligned}$$

(182) E' TOOTH AMPERE TURNS PER POLE

Repeat (129) using density (181)

(183) B'_C CORE DENSITY

$$\begin{aligned}B'_C &= (\text{Per Unit Voltage})(B_C) \\ &= (1.5)(128)\end{aligned}$$

(184) F'_C STATOR CORE AMPERE TURNS

Repeat (130) using density (183)

(185) F'_S STATOR AMPERE TURNS

$$F'_S = F'_T + F'_C = (182) + (184)$$

(186) ϕ'_ℓ LEAKAGE FLUX

$$\begin{aligned}\phi'_\ell &= .00638 \left[(\lambda_s) + (\lambda_e) + (\lambda_{t\ell}) \right] \left[(F'_S) + (F'_g) \right] (\ell_P) \\ &= .00638 \left[(88) + (86) + (87) \right] \left[(185) + (180) \right] (76)\end{aligned}$$

(187) ϕ'_{PT} TOTAL FLUX / POLE

$$\begin{aligned}\phi'_{PT} &= \left[(\text{Per Unit Voltage})(\phi_P) \right] + \left[(\phi'_\ell) \right] \\ &= \left[(1.5)(126) \right] \left[(186) \right]\end{aligned}$$

(188) B'_P POLE DENSITY

$$B'_P = (\phi'_{PT}) / (a_P) = (187) / (85)$$

(189) F'_P POLE AMPERE TURNS

Repeat (141) using density (188)

(190) F'_{NL} TOTAL AMPERE TURNS

$$\begin{aligned}F'_{NL} &= (F'_g) + (F'_S) + (F'_P) \\ &= (180) + (185) + (189)\end{aligned}$$

COMPUTER PROCEDURE

- (1) Insert the first output sheet to the typewriter and line up the carriage with the mark on the top of the sheet. Set single space.
- (2) Clear core for the 1st pass only.
- (3) Load the 1st pass object program.
- (4) Load the 1st pass data.
- (5) Punch outputs which are the input data for the 2nd pass.
- (6) Reset and load 2nd pass.
- (7) Repeat steps (3), (4), (5) and (6) for 2nd to 5th passes.
- (8) For the 6th pass, data of the two magnetization curves, the first for stator and the second for the rotor, following the other data to be read in.
- (9) If no load saturation data are required, outputs will be punched out from the 7th pass and be used in the 8th pass.
- (10) Insert the second output sheet to the typewriter as in step (1) before processing the 8th pass.
- (11) The two magnetization curves are included as input data in the 8th pass as in the 6th pass.

- (6) The magnetization curves are read in ampere turns per inch (magnetizing force) for every 5 Kilolines per square inch (induction) starting from 0 to 140, that is totally 29 points for each curve.
- (7) Data for two magnetization curves are required. The first curve for the stator and the second for the rotor. If both are of the same kind of material, two identical sets are used.
- (8) The first seven passes are to be used to complete the first output sheet and the 8th pass for the second output sheet.
- (9) Number of cards as input data to each pass:

| <u>No. of Pass</u> | <u>Data</u> | <u>Magnetization Curve</u> | <u>Total</u> |
|--------------------|-------------|--------------------------------|--------------|
| 1st | 15 | 0 | 15 |
| 2nd | 16 | 0 | 16 |
| 3rd | 17 | 0 | 17 |
| 4th | 16 | 0 | 16 |
| 5th | 17 | 0 | 17 |
| 6th | 11 | 10 | 21 |
| 7th | 9 | 0 | 9 |
| 8th | 2 | 10 | 12 |

- (10) Number of cards punched out from each pass:

| <u>No. of Pass</u> | <u>No. of Cards</u> |
|--------------------|---------------------|
| 1st | 16 |
| 2nd | 17 |
| 3rd | 16 |
| 4th | 17 |
| 5th | 11 |

(10) Cont'd

| <u>No. of Pass</u> | <u>No. of Cards</u> |
|--------------------|---------------------|
| 6th | 9 |
| 7th | 2* |
| 8th | 0 |

* It is zero when no load saturation data are not required.

INPUT SYMBOL LISTING

| <u>Calculation Number</u> | <u>Electrical Symbol</u> | <u>Fortran Symbol</u> | <u>Explanation</u> | <u>Remarks</u> |
|-------------------------------|------------------------------|---------------------------|-------------------------|----------------|
| (2) | Kva | VA | Generator KVA | |
| (3) | E | EE | Line volts | |
| (4) | E _{PH} | EP | Phase volts | |
| (5) | m | PN | Phases | |
| (5a) | f | F | Frequency | |
| (6) | p | PX | Poles | |
| (7) | Rpm | RPM | Speed | |
| (8) | I _{PH} | PI | Phase current | |
| (9) | P. F. | P. F. | Power factor | |
| (9a) | K _c | CK | Adjustment factor | |
| (10) | L. P. | POL | Load points | |
| (11) | d | DI | Stator inside diameter | |
| (12) | D | DU | Stator outside diameter | |
| (13) | ℓ | CL | Gross core length | |
| (14) | n _v | HV | Number of radial ducts | |
| (15) | b _v | BV | Width of radial ducts | |
| (16) | K _i | SF | Stacking factor | |
| (18) | -- | SML | Stator material | |
| (19) | k | WL | Watts/lb. | |
| (20) | B | BK | Density | |

| <u>Calculation Number</u> | <u>Electrical Symbol</u> | <u>Fortran Symbol</u> | <u>Explanation</u> | <u>Remarks</u> |
|-------------------------------|------------------------------|---------------------------|------------------------|---|
| (21) | -- | ZZ | Type of slot | 1.0 : a 2.0 : b 3.0 : c 4.0 : d 5.0 : e |
| (22) | b_o | BO | Stator slot dimensions | |
| (22) | b_1 | B1 | | |
| (22) | b_2 | B2 | | |
| (22) | b_3 | B3 | | |
| (22) | b_s | BS | | |
| (22) | h_o | HO | | |
| (22) | h_1 | HX | | |
| (22) | h_2 | HY | | |
| (22) | h_3 | HZ | | |
| (22) | h_s | HS | | |
| (22) | h_t | HT | | |
| (22) | h_w | HW | | |
| (23) | Q | QQ | | |
| (28) | -- | W | Type of winding | 0.0 delta 1.0 wye |
| (29) | -- | RF | Type of coil | 0.0 random 1.0 formed |
| (30) | n_s | SC | Conductors/slot | |
| (31) | y | YY | Throw | |
| (32) | c | C | Parallel paths | |

| <u>Calculation Number</u> | <u>Electrical Symbol</u> | <u>Fortran Symbol</u> | <u>Explanation</u> | <u>Remarks</u> |
|-------------------------------|------------------------------|---------------------------|--|----------------|
| (33) | -- | DW | Strand dia. or width | |
| (34) | N_{st} | SN | Strands/conductor | |
| (35) | d_b | DB | Diameter of pin | |
| (36) | ℓ_{e2} | CE | Coil extension straight portion | |
| (37) | h_{st} | SH | Uninsulated height of strand | |
| (38) | h'_{st} | SD | Distance between CL of strand | |
| (39) | -- | DT | Stator strand thickness | |
| (40) | T_{sk} | SK | Stator slot skew | |
| (50) | $X_s^{\circ}C$ | T1 | Expected operating temperature $^{\circ}C$ | |
| (51) | $\rho_s(20^{\circ}C)$ | RS | Resistivity of stator winding | |
| (59) | g_{min} | GC | Minimum air gap | |
| (59a) | g_{max} | GP | Maximum air gap | |
| (71) | C_1 | C1 | Ratio max. to min. of fundamental | |
| (72) | C_w | CW | Winding constant | |
| (73) | C_p | CP | Ratio of ave. to max. field form | |
| (48) | L_E | EL | End extension one turn | |
| (74) | C_m | CM | Demagnetizing factor | |
| (75) | C_q | CQ | Cross magnetizing factor | |
| (76) | b_h | BH | Pole head width | |

| <u>Calculation Number</u> | <u>Electrical Symbol</u> | <u>Fortran Symbol</u> | <u>Explanation</u> | <u>Remarks</u> |
|-------------------------------|------------------------------|---------------------------|---|----------------|
| (76) | b_p | BP | Pole body width | |
| (76) | h_h | HH | Pole head height | |
| (76) | h_f | HF | Pole body height | |
| (76) | ℓ_p | SQ | Pole body length | |
| (76) | ℓ_n | PL | Pole head length | |
| (77) | α | PE | Pole embrace | |
| (11a) | d_r | DR | Rotor diameter | |
| (16) | K_i | RK | Stacking factor rotor | |
| (18) | -- | RML | Rotor material | |
| (108b) | -- | WR | Weight of rotor iron | |
| (151) | K_1 | D1 | Pole face loss factor | |
| (89) | b_{bo} | WO | Width of slot opening (Damper slot) | |
| (89) | h_{bo} | HD | Height of slot opening (Damper slot) | |
| (90) | -- | DD | Damper bar dia. or width | |
| (89) | h_{b1} | H | Rectangular bar thickness | |
| (89) | b_{b1} | B | Rectangular slot width | |
| (92) | n_b | BN | Number of damper bars | |
| (93) | ℓ_b | SB | Damper bar length | |
| (94) | τ_b | TB | Damper bar pitch | |
| (95) | ρ_D | RE | Resistivity of damper bar at 20°C | |

| <u>Calculation Number</u> | <u>Electrical Symbol</u> | <u>Fortran Symbol</u> | <u>Explanation</u> | <u>Remarks</u> |
|-------------------------------|------------------------------|---------------------------|---|-------------------|
| (96) | $X_D^{\circ}C$ | T3 | Expected operating bar temp. in $^{\circ}C$ | |
| (99) | N_p | PT | Number of field turns | |
| (100) | ℓ_{tr} | FE | Mean length of field turns | |
| (101) | -- | RD | Field conductor diameter or width | |
| (102) | -- | RT | Field conductor thickness | |
| (103) | $X_f^{\circ}C$ | T2 | Expected operating temp. in $^{\circ}C$ | |
| (104) | $\rho_f(20^{\circ}C)$ | RR | Field conductor resistivity at $20^{\circ}C$ | |
| (179) | -- | SNL | No load saturation | 0.0 no 1.0 yes |
| (147) | F&W | WF | Friction & windage loss | |
| | | DNO | Design number | |
| (174) | -- | SP | Total loss (F. L.) | |
| (175) | -- | VA | Rating in KW (F. L.) | |
| (176) | -- | P | Rating + losses (F. L.) | |
| (177) | -- | PM | Percent losses (F. L.) | |
| (178) | -- | E | Percent efficiency (F. L.) | |

OUTPUT SYMBOL LISTING

| <u>Calculation Number</u> | <u>Electrical Symbol</u> | <u>Fortran Symbol</u> | <u>Explanation</u> |
|-------------------------------|------------------------------|---------------------------|--------------------------------|
| (17) | ℓ_s | SS | Solid core length |
| (24) | h_c | HC | Depth below slot X 2 |
| (26) | τ_s | TS | Slot pitch |
| (27) | $\tau_s \text{ } 1/3$ | TT | Slot pitch 1/3 dist. up |
| (42) | K_{sk} | FS | Skew factor |
| (43) | K_d | DF | Distribution factor |
| (44) | K_p | CF | Pitch factor |
| (45) | N_e | EC | Effective conductors |
| (46) | a_c | AC | Strand area |
| (47) | S_s | S | Current density (stator) |
| (49) | ℓ_t | HM | 1/2 mean turn |
| (53) | $R_{PH(cold)}$ | RG | Cold stator resistance at 20°C |
| (54) | $R_{PH(hot)}$ | RP | Hot stator resistance at X°C |
| (55) | $EF_{(top)}$ | ET | Eddy factor top |
| (56) | $EF_{(bot)}$ | EB | Eddy factor bottom |
| (62) | λ_i | PC | Stator conductor permeance |
| (63) | λ_E | EW | End permeance |
| (65) | -- | WC | Weight of stator copper |
| (66) | -- | WI | Weight of stator iron |
| (41) | τ_p | TP | Pole pitch |
| (85) | a_p | AP | Pole area |

| <u>Calculation Number</u> | <u>Electrical Symbol</u> | <u>Fortran Symbol</u> | <u>Explanation</u> |
|-------------------------------|------------------------------|---------------------------|-------------------------------|
| (86) | λ_{el} | ES | Pole end leakage permeance |
| (87) | λ_{tl} | TL | Pole tip leakage permeance |
| (88) | λ_{sl} | SL | Pole side leakage permeance |
| (89) | a_{cf} | AS | Field cond. area |
| (90) | $R_{f(cold)}$ | FK | Cold field resistance at 20°C |
| (91) | $R_{f(hot)}$ | FR | Hot field resistance at X°C |
| (108a) | -- | RC | Weight of field copper |
| (108b) | -- | WR | Weight of field iron |
| (98a) | V_r | VR | Peripheral speed |
| (132) | T'_{do} | TC | Open circuit time constant |
| (133) | T_a | TA | Armature time constant |
| (134) | T'_d | T5 | Transient time constant |
| (135) | T''_d | T4 | Subtransient time constant |
| (136) | F_{sc} | FSC | Short circuit ampere turns |
| (137) | SCR | SCR | Short circuit ratio |
| (67) | K_s | CC | Carter coefficient |
| (68) | -- | GA | Air gap area |
| (70) | λ_a | AG | Air gap permeance |
| (69) | g_e | GE | Effective air gap |
| (71) | C_1 | C1 | Ratio max to fundamental |
| (72) | C_w | CW | Winding constant |
| (73) | C_p | CP | AVE/maximum field form |
| (48) | L_E | EL | End extension one turn |

| Calculation Number | Electrical Symbol | Fortran Symbol | Explanation |
|-----------------------|----------------------|-------------------|---|
| (74) | C_M | CM | Demagnetization factor |
| (75) | C_q | CQ | Cross magnetizing factor |
| (78) | A | A | Ampere conductors/in. |
| (79) | X | XR | Reactance factor |
| (80) | X_ℓ | XL | Leakage reactance |
| (81) | X_{ad} | XL | Reactance direct axis |
| (82) | X_{aq} | XQ | Reactance quadrature axis |
| (83) | X_d | XA | Synchronous reactance direct axis |
| (84) | X_q | XB | Synchronous reactance quadrature axis |
| (112) | X_F | XF | Field leakage reactance |
| (113) | L_F | SI | Field self inductance |
| (115) | X_{Dd} | X1 | Leakage reactance in direct axis |
| (117) | X_{Dq} | X2 | Leakage reactance in quadrature axis |
| (118) | X'_{du} | XU | Unsaturated transient reactance |
| (119) | X'_d | XS | Saturated transient reactance |
| (120) | X''_d | XX | Subtransient reactance direct axis |
| (121) | X''_q | XY | Subtransient reactance quadrature axis |
| (122) | X_2 | XN | Negative sequence reactance |
| (123) | X_0 | XO | Zero sequence reactance |
| (124) | ϕ_T | TG | Total flux |
| (126) | ϕ_p | FQ | Flux per pole |

| Calculation Number | Electrical Symbol | Fortran Symbol | Explanation |
|-----------------------|----------------------|-------------------|---------------------------------|
| (125) | B_g | BG | Gap density |
| (127) | B_t | TE | Tooth density |
| (128) | B_c | BX | Core density |
| (129) | F_t | FX | Tooth ampere turns |
| (130) | F_c | AT | Core ampere turns |
| (130) | F_g | FH | Gap ampere turns |
| (138) | ϕ_l | UX | Leakage flux (No load) |
| (139) | ϕ_{PT} | TF | Pole flux (N. L.) |
| (140) | B_p | PD | Pole density (N. L.) |
| (141) | F_p | FA | Pole ampere turns (N. L.) |
| (142) | F_{NL} | FN | Total ampere turns (N. L.) |
| (143) | I_{FNL} | FI | Field amperes (N. L.) |
| (144) | S_F | CD | Current density (Field) (N. L.) |
| (145) | E_F | EF | Field volts (N. L.) |
| (146) | $I^2 R_R$ | PR | Rotor loss (N. L.) |
| (147) | F&W | WF | Friction & windage loss (N. L.) |
| (148) | W_{TNL} | ST | Stator tooth loss (N. L.) |
| (149) | W_c | WQ | Stator core loss (N. L.) |
| (150) | W_{PNL} | WN | Pole face loss (N. L.) |
| (157) | W_{PNL} | DL | Damper loss (N. L.) |
| (158) | $I^2 R_s$ | PS | Stator copper loss (N. L.) |
| (158a) | -- | EX | Eddy loss (N. L.) |
| (159) | -- | SP | Total loss (N. L.) |

| <u>Calculation Number</u> | <u>Electrical Symbol</u> | <u>Fortran Symbol</u> | <u>Explanation</u> |
|-------------------------------|------------------------------|---------------------------|----------------------------|
| (160) | ϕ_{ll} | GZ | Leakage flux (Full load) |
| (162) | ϕ_{PTL} | GL | Pole flux (F. L.) |
| (163) | B_{PL} | FD | Pole density (F. L.) |
| (164) | F_{PL} | FX | Pole ampere turns (F. L.) |
| (165) | F_{FL} | FB | Total ampere turns (F. L.) |
| (166) | I_{FFL} | FI | Field amperes (F. L.) |
| (167) | S_F | CD | Current density (F. L.) |
| (168) | E_{FFL} | EF | Field volts (F. L.) |
| (169) | $I^2 R_R$ | PR | Rotor loss (F. L.) |
| (147) | F&W | WF | Friction & windage (F. L.) |
| (170) | W_{TFL} | ST | Stator tooth loss (F. L.) |
| (149) | W_C | WQ | Stator core loss (F. L.) |
| (171) | W_{PFL} | PP | Pole face loss (F. L.) |
| (172) | W_{DFL} | DL | Damper loss (F. L.) |
| (173) | $I^2 R_s$ | PS | Stator copper loss (F. L.) |
| (173a) | -- | EX | Eddy loss (F. L.) |

```

    DIMENSION DA(8),DX(6),DY(8),DZ(8)
1  FORMAT(F12.5,F12.5,F12.5,F12.5,F12.5,F12.5)
2  FORMAT(40X F12.5)
3  FORMAT(9X F12.5,2X F12.5)
33 READ1, VA,EE,EP,PN,F,PX
    READ1, RPM,PI,PF,CK,POL,DI
    READ1, DU,CL,HV,BV,SF,SML
    READ1, WL,BK,ZZ,BO,B1,B2
    READ1, B3,BS,HO,HX,HY,HZ
    READ1, HS,HT,HW,QQ,W,RF
    READ1, SC,YY,C,DW,SN,DB
    READ1, CE,SH,SD,DT,SK,T1
    READ1, RS,GC,GP,C1,CW,CP
    READ1, EL,CM,CQ,BH,BP,HH
    READ1, HF,SQ,PL,PE,DR,RK
    READ1, RML,WR,D1,WO,HD,DD
    READ1, H,B,BN,SB,TB,RE
    READ1, T3,PT,FE,RD,RT,T2
    READ1, RR,SNL,WF,DNO
    PRINT2,DNO
    SS=SF*(CL-HV*BV)
    HC=(DU-D1-2.0*HS)*0.5
    ZY=0.7*HS
    IF(HC-ZY) 33,33,5
5  QN=QQ/(PX*PN)
    TS=3.142*D1/QQ
    IF(ZZ-4.0)29,30,29
29 TT=(0.667*HS+D1)*3.142/QQ
    GO TO 31

```

```

30 TT=((2.0*H0+BS)*0.66+DI)*3.1416/QQ
31 IF(ZZ-1.0)6,6,7
  6 CC=(5.0*GC+BS)*TS/((5.0*GC+BS)*TS-BS*BS)
    GO TO 8
  7 QC=(4.44*GC+0.75*B0)*TS
    CC=QC/(QC-B0*B0)
  8 CS=YY/(PN*QN)
    TP=3.142*DI/PX
    FS=SIN(1.571*SK/TP)*TP/(1.571*SK)
    ZY=PX*PN
    U=0.0
  9 U=U+1.0
    DM=U*ZY
    IF(QQ-DM)11,10,9
 10 DF=SIN(1.571/PN)/(QN*SIN(1.571/(PN*QN)))
    GO TO 12
 11 DF=SIN(1.571/PN)/(QQ*SIN(1.571/(QQ*PN)))
 12 CF=SIN(YY*1.571/(PN*QN))
    EC=QQ*SC*CF*FS/C
    IF(DT) 13,13,14
 13 AC=0.785*DW*DW
    GO TO 24
 14 ZY=0.0
    DA(1)=0.05
    DA(2)=0.072
    DA(3)=0.125
    DA(4)=0.165
    DA(5)=0.225

```

$$DA(6)=0.438$$

$$DA(7)=0.688$$

$$DA(8)=1.5$$

$$DX(1)=0.000124$$

$$DX(2)=0.00021$$

$$DX(3)=0.00021$$

$$DX(4)=0.00084$$

$$DX(5)=0.00189$$

$$DX(6)=0.00189$$

$$DY(1)=0.000124$$

$$DY(2)=0.000124$$

$$DY(3)=0.00084$$

$$DY(4)=0.00084$$

$$DY(5)=0.00189$$

$$DY(6)=0.00335$$

$$DY(7)=0.00754$$

$$DY(8)=0.03020$$

$$DZ(1)=0.000124$$

$$DZ(2)=0.000124$$

$$DZ(3)=0.000124$$

$$DZ(4)=0.00335$$

$$DZ(5)=0.00335$$

$$DZ(6)=0.00754$$

$$DZ(7)=0.0134$$

$$DZ(8)=0.0302$$

$$15 \quad JA=0$$

$$JB=0$$

$$JC=0$$

$$JD=0$$

16 JA=JA+1
JB=JB+1
JC=JC+1
JD=JD+1
IF(DT-DA(JA))17,17,16
17 IF(DW-0.188)18,18,19
18 CY=DX(JB-1)
CZ=DX(JB)
GO TO 22
19 IF(DW-0.75)20,20,21
20 CY=DY(JC-1)
CZ=DY(JC)
GO TO 22
21 CY=DZ(JD-1)
CZ=DZ(JD)
22 D=CY+(CZ-CY)*(DT-DA(JA-1))/(DA(JA)-DA(JA-1))
IF(ZY)23,23,27
23 AC=DT*DW-D
24 IF(RT)25,25,26
25 AS=0.785*RD*RD
GO TO 28
26 ZY=1.0
GO TO 15
27 AS=RT*RD-D
28 S=PI/(C*AC)
PUNCH1,VA,EE,EP,PN,F,PX
PUNCH1,RPM,PI,PF,CK,POL,DI

PUNCH1,DU,CL,SS,HC,SF,QN
PUNCH1,WL,BK,ZZ,BO,B1,B2
PUNCH1,B3,BS,HO,HX,HY,HZ
PUNCH1,HS,HT,HW,QQ,W,RF
PUNCH1,SC,YY,C,TS,SN,DB
PUNCH1,CE,SH,SD,TT,SK,T1
PUNCH1,RS,GC,GP,C1,CW,CP
PUNCH1,EL,CM,CQ,BH,BP,HH
PUNCH1,HF,SQ,PL,PE,DR,RK
PUNCH1,CC,WR,D1,WO,HD,DD
PUNCH1,H,B,BN,SB,TB,RE
PUNCH1,T3,PT,FE,RD,RT,T2
PUNCH1,RR,SNL,WF,CS,AS,FS
PUNCH1,TP,DF,CF,EC,AC,S
PAUSE
END

```

1  FORMAT(F12.5,F12.5,F12.5,F12.5,F12.5,F12.5)
3  FORMAT(9X F12.5,2X F12.5)

  READ1, VA,EE,EP,PN,F,PX
  READ1, RPM,PI,PF,CK,POL,DI
  READ1, DU,CL,SS,HC,SF,QN
  READ1, WL,BK,ZZ,B0,B1,B2
  READ1, B3,BS,H0,HX,HY,HZ
  READ1, HS,HT,HW,QQ,W,RF
  READ1, SC,YY,C,TS,SN,DB
  READ1, CE,SH,SD,TT,SK,T1
  READ1, RS,GC,GP,C1,CW,CP
  READ1, EL,CM,CQ,BH,BP,HH
  READ1, HF,SQ,PL,PE,DR,RK
  READ1, CC,WR,D1,W0,HD,DD
  READ1, H,B,BN,SB,TB,RE
  READ1, T3,PT,FE,RD,RT,T2
  READ1, RR,SNL,WF,CS,AS,FS
  READ1, TP,DF,CF,EC,AC,S
  GA=3.142*D1*CL
  AG=6.38*D1/(PX*GC*CC)
  GE=CC*GC
  IF(C1) 44,43,44
43  C1=(0.649*LOG(PE)+1.359)*((GC/GP)**0.352)
44  IF(CW)45,45,46
45  CW=0.707*EE*C1*DF/(EP*PN)
46  TG=6000000.0*EE/(CW*EC*RPM)

```

```
BG=TG/GA
  IF(CP)47,47,48
47 CP=(GC/GP)**0.41*PE*(LOG(GC/TP)*.0378+1.191)
48 FQ=TG*CP/PX
  IF(ZZ-3.0)49,50,51
49 SM=TT-BS
  GO TO 53
50 SM=TT-B2
  GO TO 53
51 IF(ZZ-4.0)50,52,49
52 SM=TT-BS*(0.554-0.888*H0/BS)
53 TE=TG/(QQ*SS*SM)
  BX=0.5*FQ/(HC*SS)
  IF(EL) 54,54,62
54 IF(RF) 55,55,61
55 IF(PX-2.0) 56,56,57
56 U=1.3
  GO TO 60
57 IF(PX-4.0) 58,58,59
58 U=1.5
  GO TO 60
59 U=1.7
60 EL=3.142*U*YY*(D1+HS)/QQ+0.5
  GO TO 62
61 EL=2.0*CE+(3.142*(0.5*HX+DB))+(YY*TS*TS/(SQRT(TS*TS-BS*BS)))
62 HM=CL+EL
  RY=SC*QQ*HM/(PN*AC*C*C)
  RX=RS*0.000001
```


RB=(T1+234.5)*0.00394*RX

RG=RX*RY

RP=RB*RY

AA=0.584+(SN*SN-1.0)*0.0625*(SD*CL/(SH*HM))**2.0

AB=(SH*SC*F*AC/(BS*RB*1000000.0))**2.0

ET=AA*AB*0.00335+1.0

EB=ET-0.00168*AB

IF(CM)63,63,64

63 AA=SIN(3.142*PE)

AB=SIN(1.571*PE)*4.0

CM=(3.142*PE+AA)/AB

64 A=PI*SC*CF/(C*TS)

PRINT3,SS,CC,HC,GA,TS,AG,TT,GE,FS,C1,DF,CW,CF,CP,EC,EL,AC,CM

PUNCH1,VA,EE,EP,PN,F,PX

PUNCH1,RPM,PI,PF,CK,POL,D1

PUNCH1,DU,CL,SS,HC,SF,QN

PUNCH1,WL,BK,ZZ,B0,B1,B2

PUNCH1,B3,BS,HO,HX,HY,HZ

PUNCH1,HS,HT,HW,QQ,W,GE

PUNCH1,SC,YY,C,TS,BG,TG

PUNCH1,FQ,TE,BX,TT,HM,SM

PUNCH1,RG,GC,RP,C1,CW,CP

PUNCH1,EL,CM,CQ,BH,BP,HH

PUNCH1,HF,SQ,PL,PE,DR,RK

PUNCH1,CC,WR,D1,W0,HD,DD

PUNCH1,H,B,BN,SB,TB,RE

PUNCH1,T3,PT,FE,RD,RT,T2

PUNCH1,RR,SNL,WF,CS,AS,ET

PUNCH1,TP,DF,CF,EB,AC,S

PUNCH1,AG,A

PAUSE

END

```
1 FORMAT(F12.5,F12.5,F12.5,F12.5,F12.5,F12.5)
3 FORMAT(9X F12.5,2X F12.5)
  READ1, VA,EE,EP,PN,F,PX
  READ1, RPM,PI,PF,CK,POL,D1
  READ1, DU,CL,SS,HC,SF,QN
  READ1, WL,BK,ZZ,BO,B1,B2
  READ1, B3,BS,HO,HX,HY,HZ
  READ1, HS,HT,HW,QQ,W,GE
  READ1, SC,YY,C,TS,BG,TG
  READ1, FQ,TE,BX,TT,HM,SM
  READ1, RG,GC,RP,C1,CW,CP
  READ1, EL,CM,CQ,BH,BP,HH
  READ1, HF,SQ,PL,PE,DR,RK
  READ1, CC,WR,D1,W0,HD,DD
  READ1, H,B,BN,SB,TB,RE
  READ1, T3,PT,FE,RD,RT,T2
  READ1, RR,SNL,WF,CS,AS,ET
  READ1, TP,DF,CF,EB,AC,S
  READ1, AG,A
  IF(CQ)69,69,70
69 AA=1.571*PE
  AB=3.1416*PE
  CQ=(0.5*COS(AA)+AB-SIN(AB))/(4.0*SIN(AA))
70 XR=.0707*A*DF/(C1*BG)
  IF(PN-2.0)71,71,72
71 FF=YY/(PN*QN)
  GO TO 75
72 IF(ZZ-5.0) 74,73,74
```

```

73 FF=1.0
   GO TO 75
74 FF=0.25*(3.0*YY/(PN*QN)+1.0)
75 CX=FF/(CF*CF*DF*DF)
   Z=CX*20.0/(PN*QN)
   BT=3.142*DI/QQ-B0
   ZA=BT*BT/(16.0*TS*GC)
   ZB=0.35*BT/TS
   ZC=H0/B0
   ZD=HX*0.333/BS
   ZE=HY/BS
   IF(ZZ-2.0) 76,77,78
76 PC=Z*(ZE+ZD+ZA+ZB)
   GO TO 82
77 PC=Z*(ZC+(2.0*HT/(B0+BS))+(HW/BS)+ZD+ZA+ZB)
   GO TO 82
78 IF(ZZ-4.0) 79,80,81
79 PC=Z*(ZC+(2.0*HT/(B0+B1))+(2.0*HW/(B1+B2))+(HX*0.333/B2)+ZA+ZB)
   GO TO 82
80 PC=Z*(ZC+0.62)
   GO TO 82
81 PC=Z*(ZE+ZD+(0.5*GC/TS)+(0.25*TS/GC)+0.6)
82 EK=EL/(10.0**(0.103*YY*TS+0.402))
   IF(DI-8.0) 83,83,84
83 EK=SQRT(EK)
84 ZF=.612*LOG(10.0*CS)
   EW=6.28*EK*ZF*(TP**(0.62-(0.228*LOG(ZF))))/(CL*DF*DF)
   IF(PN-3.0)85,86,86
85 ZC=0.1*DI*SIN(3.0*YY/(PN*QN))*1.57/(PX*GE*CF)

```

```

GO TO 87
86 ZC=0.0
87 XL=(PC+EW+ZC)*XR
   XD=XR*AG*C1*CM
   XQ=XR*CQ*AG
   WC=0.321*SC*QQ*AC*HM
   ZA=3.1416*(DI+HS)/QQ
   IF(ZZ-3.0) 88,89,88
88 TM=ZA-BS
   GO TO 90
89 TM=ZA-(B1+(1.0-0.5/(1.0-(HO+HT)/HS))*(B3-B1))
90 PRINT3,S,CQ,HM,A,RG,XR,RP,XL,ET,XD,EB,XQ
   PUNCH1,VA,EE,EP,PN,F,PX
   PUNCH1,RPM,PI,PF,CK,POL,DI
   PUNCH1,DU,CL,SS,HC,PC,QN
   PUNCH1,WL,BK,ZZ,BO,XD,XQ
   PUNCH1,XR,BS,XL,HX,HY,HZ
   PUNCH1,HS,WC,AC,QQ,W,GE
   PUNCH1,SC,YY,C,TS,BG,TG
   PUNCH1,FQ,TE,BX,TT,EW,AG
   PUNCH1,RG,GC,RP,C1,TP,CP
   PUNCH1,DF,CM,CF,BH,BP,HH
   PUNCH1,HF,SQ,PL,EB,DR,RK
   PUNCH1,CC,WR,D1,WO,HD,DD
   PUNCH1,H,B,BN,SB,TB,RE
   PUNCH1,T3,PT,FE,RD,RT,T2
   PUNCH1,RR,SNL,WF,CS,AS,ET
   PUNCH1,TM
   PAUSE

```

1 FORMAT(F12.5,F12.5,F12.5,F12.5,F12.5,F12.5)

3 FORMAT(9X F12.5,2X F12.5)

READ1, VA,EE,EP,PN,F,PX

READ1, RPM,PI,PF,CK,POL,DI

READ1, DU,CL,SS,HC,PC,QN

READ1, WL,BK,ZZ,BO,XD,XQ

READ1, XR,BS,XL,HX,HY,HZ

READ1, HS,WC,AC,QQ,W,GE

READ1, SC,YY,C,TS,BG,TG

READ1, FQ,TE,BX,TT,EW,AG

READ1, RG,GC,RP,C1,TP,CP

READ1, DF,CM,CF,BH,BP,HH

READ1, HF,SQ,PL,EB,DR,RK

READ1, CC,WR,D1,WO,HD,DD

READ1, H,B,BN,SB,TB,RE

READ1, T3,PT,FE,RD,RT,T2

READ1, RR,SNL,WF,CS,AS,ET

READ1, TM

WI=(TM*QQ*SS*HS+(DU-HC)*3.142*HC*SS)*0.283

AN=0.0

100 AN=AN+0.005

AL=COS(AN)

IF(PF-AL) 100,100,101

101 VR=0.262*DR*RPM

AP=BP*SQ*RK

SL=HF/((DR-2.0*HH-0.5*HF)*3.142/PX-BP)

ES=((PL-CL)*2.0+HF+0.25*BP)/CL

$$TL = (HH + GC - TP / 18.0) * 2.0 / (TP - BH)$$

$$FH = BG * GE / 0.00319$$

$$ZG = PT * PX * FE * 0.000001 / AS$$

$$FK = RR * ZG$$

$$FR = (T2 + 234.5) * FK * 0.00394$$

$$RC = 0.321 * PT * PX * FE * AS$$

$$RL = (1.5 * TL + SL) * 4.25 + 6.38 * ES$$

$$XF = (1.0 - C1 / ((1.273 * RL / AG + 2.0 * CP) * CM)) * XD$$

$$SI = (1.571 * CP * AG + RL) * PT * PT * PX * SQ * 0.00000001$$

$$IF (DD) 103, 103, 102$$

102 ZG=0.62

GO TO 104

103 ZG=0.333*H/B

104 BD=(HD/WO+ZG+0.5)*6.38

$$BE = (BH - (BN - 1.0) * TB) * 2.127 / GE$$

$$P1 = (BD + BE) * RL * \cos((BN - 1.0) * TB * 1.572 / TP) / (BD + BE + RL)$$

$$X1 = XR * P1$$

$$P2 = (HD / WO + ZG + 0.5 + GC / TB) * 20.0 * TB / TP$$

$$X2 = XR * P2$$

$$XA = XL + XD$$

$$XB = XL + XQ$$

$$XU = XL + XF$$

$$XS = 0.88 * XU$$

$$IF (BN) 105, 105, 106$$

105 XX=XS

XY=XB

GO TO 107

106 XX=XL+X1

XY=XL+X2

107 XN=(XX+XY)*0.5

TC=SI/FR

RA=PN*PI*PI*RP*0.001/VA

TA=XN/(628.4*F*RA)

T5=XS*TC/XA

IF (F-60.0) 108, 108, 109

108 T4=0.035

GO TO 110

109 T4=0.005

110 IF (WF) 111, 111, 112

111 WF=DR**2.5*(RPM**1.5)*PL*0.00000252

112 WQ=(DU-HC)*1.42*HC*SS*(BX/BK)**2.0*WL

WT=(TT-BS)*QQ*SS*HS*0.453*(TE/BK)**2.0*WL

PRINT3, PC, XA, EW, XB, WC, XF, WI, SI, TP, X1, AP, X2, ES, XU, TL, XS, SL, XX, AS, X

PRINT3, FK, XN

PUNCH1, VA, EE, EP, PN, F, PX

PUNCH1, RPM, PI, PF, CK, POL, DI

PUNCH1, DU, CL, SS, HC, PC, QN

PUNCH1, WL, BK, ZZ, BO, XD, XQ

PUNCH1, XR, BS, TL, HX, HY, HZ

PUNCH1, HS, ES, AC, QQ, W, GE

PUNCH1, SC, YY, C, TS, BG, TG

PUNCH1, FQ, TE, BX, TT, EW, AG

PUNCH1, RG, GC, RP, C1, AP, P2

PUNCH1, DF, SL, CF, FH, BP, HH

PUNCH1, HF, SQ, PL, EB, DR, RK

PUNCH1, CC, WR, D1, WO, TC, DD

PUNCH1,H,B,BN,SB,TB,RE

PUNCH1,T3,PT,VR,RD,RT,WT

PUNCH1,WQ,SNL,WF,CS,AS,ET

PUNCH1,FK,FR,XA,XB,T5,T4

PUNCH1,AN,AL,RC,TA,HD

PAUSE

END

```

1  FORMAT(F12.5,F12.5,F12.5,F12.5,F12.5,F12.5)
3  FORMAT(9X F12.5,2X F12.5)
   READ1, VA,EE,EP,PN,F,PX
   READ1, RPM,PI,PF,CK,POL,DI
   READ1, DU,CL,SS,HC,PC,QN
   READ1, WL,BK,ZZ,BO,XD,XQ
   READ1, XR,BS,TL,HX,HY,HZ
   READ1, HS,ES,AC,QQ,W,GE
   READ1, SC,YY,C,TS,BG,TG
   READ1, FQ,TE,BX,TT,EW,AG
   READ1, RG,GC,RP,C1,AP,P2
   READ1, DF,SL,CF,FH,BP,HH
   READ1, HF,SQ,PL,EB,DR,RK
   READ1, CC,WR,D1,WO,TC,DD
   READ1, H,B,BN,SB,TB,RE
   READ1, T3,PT,VR,RD,RT,WT
   READ1, WQ,SNL,WF,CS,AS,ET
   READ1, FK,FR,XA,XB,T5,T4
   READ1, AN,AL,RC,TA,HD
   GT=BS/GC
   IF(GT-3.75) 113,114,114
113 AA=10.0**0.178/((GT-1.0)**0.334)
   GO TO 115
114 AA=10.0**0.11/((GT-1.0)**0.174)
115 GF=AA*PI*SC/(C*FH)
   IF(SC-1.0)120,121,122
120 A5=0.0

```

GO TO 129

121 $AX=1.0$
 $AY=1.0$
GO TO 125

122 $AX=3.0*YY/(PN*QN)-2.0$
 $IF(CS-0.667) 123, 124, 124$

123 $AY=1.5*YY/(PN*QN)-0.25$
GO TO 125

124 $AY=.75*YY/(PN*QN)+0.25$

125 $A3=AX*P2/AY$
 $A4=0.07*AX*AG/(CF*CF)$
 $IF(AX) 120, 120, 126$

126 $IF(BN) 127, 127, 128$

127 $A5=A4$
GO TO 129

128 $A5=(A4+A3)/(A3*A4)$

129 $IF(W) 130, 130, 131$

130 $X0=0.0$
GO TO 132

131 $AA=(3.0*HZ+HX)*1.667/(PN*QN*CF*CF*DF*DF*BS)$
 $X0=((PC+A5)*AX/AY+AA+0.2*EW)*XR$

132 $D2=BG**2.5*0.000061$
 $D3=(0.0167*QQ*RPM)**1.65*0.000015147$
 $IF(TS-0.9) 133, 133, 134$

133 $D4=TS**1.285*0.81$
GO TO 137

134 $IF(TS-2.0) 135, 135, 136$

135 $D4=TS**1.145*0.79$

GO TO 137

136 $D4 = TS^{**}0.79^{*}0.92$

137 $D7 = B0/GC$

IF(D7-1.7) 138, 138, 139

138 $D5 = D7^{**}2.31^{*}0.3$

GO TO 144

139 IF(D7-3.0) 140, 140, 141

140 $D5 = D7^{**}2.0^{*}0.35$

GO TO 144

141 IF(D7-5.0) 142, 142, 143

142 $D5 = D7^{**}1.4^{*}0.625$

GO TO 144

143 $D5 = D7^{**}0.965^{*}1.38$

144 $D6 = 10.0^{**}(0.932^{*}C1 - 1.606)$

$BA = 3.142^{*}D1^{*}CL$

$WN = D1^{*}D2^{*}D3^{*}D4^{*}D5^{*}D6^{*}BA$

$UY = (SL + ES + TL)^{*}SQ^{*}0.00638$

$AA = W0/(GC^{*}CC)$

IF(AA-0.65) 145, 145, 146

145 $VT = \text{LOG}(10.0^{*}AA)^{*}(-0.242) + 0.59$

GO TO 147

146 $VT = 0.327 - (AA^{*}0.266)$

147 $UZ = (DU - HC)^{*}0.7850/PX$

$EZ = (ET + EB)^{*}0.5 - 1.0$

$AA = PN^{*}PI^{*}PI$

$PU = AA^{*}RG$

$PV = AA^{*}RP$

$VV = EE^{*}PI^{*}PF^{*}1.732$

FSC=XA*FH*0.01

PRINT3,FR,XO,RC,TG,WR,FQ,VR,BG,TC,TE,TA,BX

PUNCH1,VA,EE,EP,PN,F,PX

PUNCH1,RPM,PI,PF,CK,POL,TB

PUNCH1,BO,GC,HH,HF,SQ,DR

PUNCH1,SB,RE,T3,PT,T5,T4

PUNCH1,WO,DD,H,BN,GF,VT

PUNCH1,SNL,TS,CC,BG,FK,AP

PUNCH1,FQ,TE,BX,FR,XD,FH

PUNCH1,WQ,WT,AN,AL,XA,WF

PUNCH1,AS,HS,B,GE,BP,XB

PUNCH1,WN,UY,UZ,EZ,PU,VV

PUNCH1,FSC,PV,HD

PAUSE

END

```
DIMENSION FY(5),PA(5),ED(5),GX(5),GZ(5),GL(5),FD(5),FX(5),FB(5)
DIMENSION FI(5),EF(5),CD(5),Q(4),R(58)
1 FORMAT(F12.5,F12.5,F12.5,F12.5,F12.5,F12.5)
3 FORMAT(9X F12.5,2X F12.5)
4 FORMAT (F11.3,8X F11.3,F11.3,F11.3,F11.3)
  READ1, VA,EE,EP,PN,F,PX
  READ1, RPM,PI,PF,CK,POL,TB
  READ1, BO,GC,HH,HF,SQ,DR
  READ1, SB,RE,T3,PT,T5,T4
  READ1, WO,DD,H,BN,GF,VT
  READ1, SNL,TS,CC,BG,FK,AP
  READ1, FQ,TE,BX,FR,XD,FH
  READ1, WQ,WT,AN,AL,XA,WF
  READ1, AS,HS,B,GE,BP,XB
  READ1, WN,UY,UZ,EZ,PU,VV
  READ1, FSC,PV,HD
  READ1, R(1),R(2),R(3),R(4),R(5),R(6)
  READ1, R(7),R(8),R(9),R(10),R(11),R(12)
  READ1, R(13),R(14),R(15),R(16),R(17),R(18)
  READ1, R(19),R(20),R(21),R(22),R(23),R(24)
  READ1, R(25),R(26),R(27),R(28),R(29)
  READ1, R(30),R(31),R(32),R(33),R(34),R(35)
  READ1, R(36),R(37),R(38),R(39),R(40),R(41)
  READ1, R(42),R(43),R(44),R(45),R(46),R(47)
  READ1, R(48),R(49),R(50),R(51),R(52),R(53)
  READ1, R(54),R(55),R(56),R(57),R(58)
GO TO 199
```

```
200 VQ=0.0
202 RM=R(L)
    L=L+1
    RN=R(L)
    VL=VQ+5.0
    IF (VL-BF) 203,203,204
203 VQ=VL
    GO TO 202
204 Q(J)=(RN-RM)*(BF-VQ)/5.0+RM
    GO TO (208,209,210,214),J
199 L=1
    J=1
    BF=BX
    GO TO 200
208 AT=UZ*Q(J)
    L=1
    J=2
    BF=TE
    GO TO 200
209 FT=Q(J)*HS
    SA=FT+AT
    UX=(SA+FH)*UY
    TF=FQ+UX
    PD=TF/AP
    J=3
    L=30
    BF=PD
    GO TO 200
210 FA=(HF+HH)*Q(J)
```

```

FN=SA+FA+FH
SCR=FN/FSC
PRINT3,T5,FT,T4,AT,FSC,FH
221 FORMAT(9X F12.5/)
PRINT221,SCR
YL=0.000001
FW=FK
M=1
211 Y=100.0/YL
FY(M)=ATAN((BX/Y+SIN(AN))/AL)
PA(M)=FY(M)-AN
ED(M)=XA*SIN(FY(M))/Y+COS(PA(M))
GX(M)=(ED(M)-(0.93*XD*SIN(FY(M))/Y))*FQ
IF(PF-0.95)213,213,212
212 GX(M)=GX(M)*CK
213 GZ(M)=((1.0+COS(AN))*FT+AT+(FH*ED(M)))*UX/(FH+SA)
GL(M)=GX(M)+GZ(M)
FD(M)=GL(M)/AP
J=4
L=30
BF=FD(M)
GO TO 200
214 FX(M)=(HF+HH)*Q(J)
FB(M)=(1.0+COS(PF))*FT+AT+FX(M)+ED(M)*FH
FI(M)=FB(M)/PT
EF(M)=FI(M)*FW
CD(M)=FI(M)/AS
M=M+1
IF(M-3) 215,216,217

```


215 YL=1.0

FW=FR

GO TO 211

216 YL=1.5

GO TO 211

217 IF (M-5) 218,219,220

218 YL=2.0

GO TO 211

219 YL=POL

GO TO 211

220 PRINT4, GZ(1),GZ(2),GZ(3),GZ(4),GZ(5)

PRINT4, GL(1),GL(2),GL(3),GL(4),GL(5)

PRINT4, FD(1),FD(2),FD(3),FD(4),FD(5)

PRINT4, FX(1),FX(2),FX(3),FX(4),FX(5)

PRINT4, FB(1),FB(2),FB(3),FB(4),FB(5)

PRINT4, FI(1),FI(2),FI(3),FI(4),FI(5)

PRINT4, CD(1),CD(2),CD(3),CD(4),CD(5)

PRINT4, EF(1),EF(2),EF(3),EF(4),EF(5)

PUNCH1, FI(1),FI(2),FI(3),FI(4),FI(5)

PUNCH1, EP,PN,F,PX,WQ,WT

PUNCH1, BO,GC,HH,HF,POL,TB

PUNCH1, SB,RE,T3,HS,FK,FR

PUNCH1, WO,DD,H,BN,GF,VT

PUNCH1, SNL,TS,CC,BG,AP,B

PUNCH1, FQ,TE,BX,FH,XA,WF

PUNCH1, WN,UY,UZ,EZ,PU,VV

PUNCH1, PV,HD

PAUSE

END

```
DIMENSION PR(5),FI(5),PS(5),G(5),DL(5),PP(5),EX(5),ST(5),VA(5)
DIMENSION P(5),E(5),PM(5),SP(5)
1  FORMAT(F12.5,F12.5,F12.5,F12.5,F12.5,F12.5)
4  FORMAT (F11.3,8X F11.3,F11.3,F11.3,F11.3)
  READ1, FI(1),FI(2),FI(3),FI(4),FI(5)
  READ1, EP,PN,F,PX,WQ,WT
  READ1, BO,GC,HH,HF,POL,TB
  READ1, SB,RE,T3,HS,FK,FR
  READ1, WO,DD,H,BN,GF,VT
  READ1, SNL,TS,CC,BG,AP,B
  READ1, FQ,TE,BX,FH,XA,WF
  READ1, WN,UY,UZ,EZ,PU,VV
  READ1, PV,HD
  FS1=2.0*GC*PN*F
  FS2=2.0*FS1
  M=0
150 IF(M-1) 151,152,178
151 RM=RE*0.000001
  GO TO 153
152 RM=RE*(T3+234.5)*0.00000000396
153 AA=(FS1/RM)**0.5*DD*0.32
  AB=(FS2/RM)**0.5*DD*0.32
  IF(AA-2.5) 160,160,161
160 V1=1.0-0.15*AA+0.3*AA*AA
  GO TO 162
161 V1=AA
162 IF(AB-2.5) 163,163,164
```

163 $V2=1.0-0.15*AB+0.3*AB*AB$
GO TO 165

164 $V2=AB$

165 IF(H-B) 167,166,167

166 $VC=0.75/V1$
GO TO 169

167 IF(DD) 166,168,166

168 $VC=H/(3.0*B*V1)$

169 $VS=HD/WO+VT+VC$
 $VG=TB/(CC*GC)$
 $Q1=1.0-(1.0/(((B0*0.5/GC)**2.0+1.0)**0.5))$
 $QZ=B0/TS$
 $Q2=1.05*SIN(QZ*2.844)$
IF(QZ-0.37) 170,170,171

170 $Q3=0.46$
GO TO 172

171 $Q3=0.23*SIN(10.46*QZ-2.1)+0.23$

172 $Q4=SIN(6.283*TB/TS-1.571)+1.0$
 $Q5=SIN(12.566*TB/TS-1.571)+1.0$
IF(DD) 174,174,173

173 $AB=0.785*DD*DD$
GO TO 175

174 $AB=H*B$

175 $W2=PX*BN*SB*RM*1.246/AB$
 $W3=(Q2/(2.0*VS+(VG/Q4)))*2.0*V1$
 $W5=(Q3/(2.0*VS+(VG/Q5)))*2.0*V2$
 $WD=(TS*BG*Q1*CC)*2.0*W2*(W3+W5)$
 $M=M+1$

```
      IF(M-1) 176, 176, 177
176  WU=WD
177  GO TO 150
178  UA=0.0
      M=1
179  IF(M-1) 181, 181, 182
181  PW=PU
      FW=FK
      WW=WU
      GO TO 183
182  PW=PV
      FW=FR
      WW=WD
183  PR(M)=F I (M)*F I (M)*FW
      PS(M)=PW*UA*UA
      G(M)=(GF*UA)**2.0+1.0
      DL(M)=G(M)*WW
      PP(M)=G(M)*WN
      EX(M)=EZ*PS(M)
      ST(M)=(2.0*(0.0027*XA*UA)**1.8+1.0)*WT
      SP(M)=PP(M)+DL(M)+PR(M)+PS(M)+EX(M)+ST(M)+WF+WQ
      VA(M)=VV*UA
      P(M)=SP(M)+VA(M)
      PM(M)=(SP(M)/P(M))*100.0
      E(M)=100.0-PM(M)
      M=1+M
      IF(M-3) 184, 185, 186
```

```
184 UA=1.0
      GO TO 179
185 UA=1.5
      GO TO 183
186 IF(M-5) 187, 188, 189
187 UA=2.0
      GO TO 183
188 UA=POL
      GO TO 183
189 PRINT4, PR(1),PR(2),PR(3),PR(4),PR(5)
      PRINT4, WF,WF,WF,WF,WF
      PRINT4, ST(1),ST(2),ST(3),ST(4),ST(5)
      PRINT4, WQ,WQ,WQ,WQ,WQ
      PRINT4, PP(1),PP(2),PP(3),PP(4),PP(5)
      PRINT4, DL(1),DL(2),DL(3),DL(4),DL(5)
      PRINT4, PS(1),PS(2),PS(3),PS(4),PS(5)
      PRINT4, EX(1),EX(2),EX(3),EX(4),EX(5)
      PRINT4, SP(1),SP(2),SP(3),SP(4),SP(5)
      PRINT4, VA(1),VA(2),VA(3),VA(4),VA(5)
      PRINT4, P(1),P(2),P(3),P(4),P(5)
      PRINT4, PM(1),PM(2),PM(3),PM(4),PM(5)
      PRINT4, E(1),E(2),E(3),E(4),E(5)
      IF(SNL) 191, 191, 190
190 PUNCH1, FH, TE, BX, UZ, UY, FQ
      PUNCH1, AP, HF, HH, HS, EP
191 PAUSE
      END
```

```
DIMENSION Q(3),R(58)
1 FORMAT(F12.5,F12.5,F12.5,F12.5,F12.5,F12.5)
  READ1, FH,TE,BX,UZ,UY,FQ
  READ1, AP,HF,HH,HS,EP
  READ1, R(1),R(2),R(3),R(4),R(5),R(6)
  READ1, R(7),R(8),R(9),R(10),R(11),R(12)
  READ1, R(13),R(14),R(15),R(16),R(17),R(18)
  READ1, R(19),R(20),R(21),R(22),R(23),R(24)
  READ1, R(25),R(26),R(27),R(28),R(29)
  READ1, R(30),R(31),R(32),R(33),R(34),R(35)
  READ1, R(36),R(37),R(38),R(39),R(40),R(41)
  READ1, R(42),R(43),R(44),R(45),R(46),R(47)
  READ1, R(48),R(49),R(50),R(51),R(52),R(53)
  READ1, R(54),R(55),R(56),R(57),R(58)
  GO TO 234
228 IF(BF-140.0)230,230,229
229 IF(J-2)239,241,243
230 VQ=0.0
231 RM=R(L)
    L=L+1
    VL=VQ+5.0
    RN=R(L)
    IF(VL-BF)232,232,233
232 VQ=VL
    GO TO 231
233 Q(J)=(RN-RM)*(BF-VQ)/5.0+RM
    GO TO (236,237,238),J
```

234 UB=0.7

235 UB=UB+0.1

V=1.732*EP*UB

FG=FH*UB

TD=TE*UB

BC=BX*UB

J=1

L=1

BF=BC

GO TO 228

236 AT=UZ*Q(J)

L=1

J=2

BF=TD

GO TO 228

237 FT=Q(J)*HS

SA=FT+AT

UX=(FG+SA)*UY

TF=FQ*UB+UX

PD=TF/AP

J=3

L=30

BF=PD

GO TO 228

238 FA=(HF+HH)*Q(J)

FN=SA+FA

246 FORMAT(F12.5,F12.5,F12.5,F12.5,F12.5,F12.5//)

PRINT1,V,FG,TD,FT,BC,AT

PRINT 246, SA, UX, TF, PD, FA, FN

IF (UB-1.6) 235, 245, 245

239 PRINT 240

240 FORMAT(23H CORE DENSITY SATURATED)

GO TO 245

241 PRINT 242

242 FORMAT(24H TOOTH DENSITY SATURATED)

GO TO 245

243 PRINT 244

244 FORMAT(23H POLE DENSITY SATURATED)

245 PAUSE

END


TWO COIL LUNDELL
(BECKY-ROBINSON TYPE)

TWO COIL LUNDELL

(BECKY-ROBINSON TYPE)



60 KVA
TWO COIL LUNDELL
(BECKY-ROBINSON TYPE)
ROTOR



LUNDELL GENERATOR SALIENT POLE SYNCHRONOUS DESIGN SHEET

131

| STATOR | ROTOR | |
|------------------------------------|---|--|
| Punching I.D. _____ | Single Gap _____ ga _____ | |
| Punching O.D. _____ | Rotor Diameter _____ | |
| Core Length _____ | Peripheral Speed _____ | |
| DBS x 2 _____ | Pole Pitch _____ α _____ | |
| Slots _____ | Pole Area _____ | |
| Size Slots _____ | P_1 _____ P_5 _____ | |
| Carter Coeff. _____ | P_2 _____ P_6 _____ | |
| Type Wdg. _____ | P_3 _____ P_7 _____ | |
| Throw _____ | P_4 _____ | |
| Skew & Dist. Fact. _____ | Grade Of Iron _____ | |
| Chord Fact. _____ | No. Damper Bars _____ | |
| Cond. Per Slot _____ | Bar Size _____ | |
| Total Eff. Cond. _____ | Bar Pitch _____ h_o _____ b_o _____ | |
| Cond. Size _____ | Turns Per Pole _____ | |
| Cond. Area _____ | Cond. Size _____ | |
| Current Density _____ | Cond. Area _____ | |
| Wdg. Const. _____ C1 _____ | Mean Turn _____ | |
| Total Flux _____ | Res. At _____ ° | |
| Gap Area _____ | Wt. Of Copper _____ | |
| Gap Density _____ | Wt. Of Iron _____ | |
| Pole Const. _____ | % Load _____ | |
| Flux Per Pole _____ | Amps. _____ | |
| Tooth Pitch _____ | Volts _____ | |
| Tooth Density _____ | Amps/In. ² _____ | |
| Core Density _____ | Field Leak. React. _____ | |
| Grade Of Iron _____ | Field Self Induct. _____ | |
| 1/2 Mean Turn _____ | Damp. Leak. XDd _____ XDq _____ | |
| Res. Per Ph. At _____ ° | | |
| Eddy Fact. Top _____ | REACT.-TIME CONST. | |
| Eddy Fact. Bottom _____ | Synch. Xd _____ Xq _____ | |
| Demag. Fact. Cm _____ Cq _____ | Unsat. Trans. _____ | |
| Amp. Cond. Per In. _____ | Sat. Trans. _____ | |
| React. Factor _____ | Subtrans. Xd _____ Xq _____ | |
| Cond. Perm. _____ | Neg. Sequence _____ | |
| End Perm. _____ | Zero Sequence _____ | |
| Leakage React. _____ | Open Circ. Time Con. _____ | |
| Air Gap Perm. _____ | Arm. Time Con. _____ | |
| React. Of Arm. Xad _____ Xaq _____ | Trans. Time Con. _____ | |
| Wt. Of Copper _____ | Subtrans. Time Con. _____ | |
| Wt. Of Iron _____ | | |

| SATURATION | | | | |
|-------------------------|--|--|--|--|
| Air Gap A.T. _____ | | | | |
| Stator A.T. _____ | | | | |
| Pole A.T. _____ | | | | |
| No Load A.T. _____ | | | | |
| Rated Load A.T. _____ | | | | |
| Overload A.T. _____ | | | | |
| Short Circ. A.T. _____ | | | | |
| Short Circ. Ratio _____ | | | | |

| LOSSES-EFFICIENCY | | | | |
|-------------------------------------|--|--|--|--|
| % Load _____ | | | | |
| F & W _____ | | | | |
| Sta. Teeth _____ | | | | |
| Sta. Core _____ | | | | |
| Pole Face _____ | | | | |
| Damper _____ | | | | |
| Sta. I ² R _____ | | | | |
| Eddy _____ | | | | |
| Rot. I ² R _____ | | | | |
| Σ Losses _____ | | | | |
| Rating _____ | | | | |
| Rtg.+Loss _____ | | | | |
| % Loss _____ | | | | |
| % Eff. _____ | | | | |
| Stator Watts/In. ² _____ | | | | |
| Rotor Watts/In. ² _____ | | | | |

E.W.O. _____ Model No. _____ Type Cooling _____

_____ KVA _____ % PF _____ Volts _____ Amps. _____ Ph. _____ Cycles _____ RPM _____

Designed By _____ Date _____

STATOR

PUNCHING I. D. --(d) The inside diameter of the stator punchings.

PUNCHING O. D. --(D) The outside diameter of the stator punchings.

CORE LENGTH--(ℓ) The overall length of the stator iron. Also record on this line the solid core length (ℓ_s). The solid length is the overall length times the stacking factor (K_i). The stacking factor allows for the coating on the punchings, the burrs due to slotting, and the deviations in flatness. Approximate values of K_i are given in the table below.

**THICKNESS OF
LAMINATIONS
(INCHES)**

GAGE

K_i

| | | |
|------|----|------|
| .014 | 29 | 0.92 |
| .018 | 26 | 0.93 |
| .025 | 24 | 0.95 |
| .028 | 23 | 0.97 |
| .063 | -- | 0.98 |
| .125 | -- | 0.99 |

If ventilating ducts are used their length must be subtracted from the overall length also.

DEPTH BELOW SLOTS x 2--($2h_c$) The depth of the stator core below the slots times 2.

$$2h_c = D - (d + 2h_g)$$

Due to mechanical strength reasons h_c should never be less than 70% of h_g .

SLOTS--(Q) The number of stator slots. Write Q as a product of poles (p) times phases (m) times slots per phase per pole (q). Thus $pmq = Q$. In general fractions of q close to $1/3$ and $2/3$ should be avoided, because these fractions are inclined toward producing force poles that cause excessive noise and vibration. In three phase machines fractions of q with thirds or any multiple of three in the denominator should be avoided because with these values a balanced winding cannot be obtained.

SIZE SLOTS--(b_s and h_s) The width of the stator slot (b_s) and the depth of the stator slot (h_s).

CARTER COEFFICIENT--(K_s) The Carter coefficient for the stator slots.

$$K_s = \frac{\tau_s(5g+b_s)}{\tau_s(5g+b_s)-b_s^2} \quad (\text{for open slots})$$

$$K_s = \frac{\tau_s(4.44g+.75b_o)}{\tau_s(4.44g+.75b_o)-b_o^2} \quad (\text{for partially closed slots})$$

TYPE WINDING-- Record whether star or delta (Y or Δ), and whether series or parallel.

THROW--(y) The coil span in slots. Record the percent span (y/mq) and designate the slots in which the coil is placed ($1 + y$).

SKEW AND DISTRIBUTION FACTORS--(K_{sk} and K_d) The skew factor (K_{sk}) is the ratio of the voltage induced in the coils to the voltage that could be induced if there was no skew.

OR

$$K_{sk} = \frac{\sin \frac{\tau_{sk} \pi}{2\tau_p}}{\frac{\tau_{sk} \pi}{2\tau_p}}$$

The distribution factor (K_d) is the ratio of the voltage induced in the coils to the voltage that would be induced if the winding was concentrated in a single slot

$$K_d = \frac{\sin(q\alpha_{s/2})}{q \sin\alpha_{s/2}} \quad (\text{for integral slot machines})$$

$$K_d = \frac{\sin(N\alpha_{m/2})}{N \sin\alpha_{m/2}} \quad (\text{for fractional slot machines})$$

See table 2 for a compilation of distribution factors for the various harmonics. See "Grouping of Fractional Slot Windings" and "Distribution Factor" sections of the APPENDIX for an explanation of K_d for fractional slot machines.

CHORD FACTOR--(K_p) The ratio of the voltage induced in the coil to the voltage that would be induced in a full pitched coil.

$$K_p = \sin\left(\frac{Y}{mq} \times 90^\circ\right)$$

See Table 1 for a compilation of the pitch factors for the various harmonics.

CONDUCTORS PER SLOT--(n_s) The actual number of conductors per slot.

For random wound slots use a space factor of 80% to 85% when determining the permissible number.

TOTAL EFFECTIVE CONDUCTORS--(n_e) The actual number of effective series conductors in the stator winding taking into account the chord and skew factors but not allowing for the distribution factor.

$$n_e = \frac{Q_n K_p K_{sk}}{C}$$

CONDUCTOR SIZE-- Record the number of strands making up each conductor and their bare and insulated sizes. Indicate also the type of strand insulation.

CONDUCTOR AREA--(a_c) The actual area of the conductor taking into account the corner radius on square and rectangular wire. See the following table for typical values of corner radii.

$$a_c = (\text{width of cond.}) \times (\text{thickness of cond.}) - .858r_c^2$$

| Corner Radii | | | |
|--------------|--------------|--------------|--------------|
| Thickness | Width | | |
| | .751 & Up | .187 - .750 | Up to .188 |
| .689 & up | 3/16 | 3/16 | -- |
| .688 - .439 | 1/8 | 3/32 | -- |
| .438 - .226 | 3/32 | 1/16 | -- |
| .225 - .166 | 1/16 | 3/64 | 3/64 |
| .165 - .126 | 1/16 | 1/32 | 1/32 |
| .125 - .073 | Rounded edge | 1/32 | 1/64 |
| .072 - .051 | Rounded edge | Rounded edge | 1/64 |
| .050 & under | Rounded edge | Rounded edge | Rounded edge |

| Corner | $.858r_c^2$ |
|--------|-------------|
| 1/64 | .00021 |
| 1/32 | .00084 |
| 3/64 | .00189 |
| 1/16 | .00335 |
| 3/32 | .00754 |
| 1/8 | .0134 |
| 3/16 | .0302 |

Square wire .072 and under has a radius of .012. A rounded edge is produced by rolling round wire to the specified size.

CURRENT DENSITY--(s) The amperes per square inch of conductor.

$$s = \frac{I_{ph}}{Ca_c}$$

WINDING CONSTANT--(C_w) The ratio of the RMS line voltage for a full pitched winding to that which would be introduced in all the conductors in series if the density were uniform and equal to the maximum value.

$$C_w = \frac{EC_1 K_d}{\sqrt{2} E_{phm}}$$

Assuming $K_d = .955$, $C_w = .225 C_1$ for three phase delta machines and $C_w = .390 C_1$ for three phase star ones. C_1 is the ratio of the maximum fundamental of the field form to the actual maximum of the field form. For pole heads with more than one radius the field form is determined from a flux plot of the air gap flux at no load, neglecting saturation, and C_1 is then obtained by Fourier analysis. For pole heads with only one radius, C_1 is obtained from curve #4. The graphical flux plotting method of determining C_1 is explained in the section titled "Derivations."

TOTAL FLUX--(ϕ_T) The total flux that would exist in the gap if the density was uniform and equal to the maximum gap density.

$$\phi_T = \frac{6000 E 10^6}{C_{w n_e} \text{ RPM}}$$

GAP AREA-- The area of the gap surface at the stator bore = $\pi d \ell$

GAP DENSITY--(B_g) The maximum flux density in the air gap.

$$B_g = \frac{\phi_T}{\pi d \ell}$$

POLE CONSTANT--(C_p) The ratio of the average to the maximum value of the field form. For pole heads with more than one radius C_p is calculated from the same field form that was used to determine C_1 , and this method is described in the second part of the manual. For pole heads with only one radius C_p is obtained from curve #4. Note the correction factor at the top of the curve.

FLUX PER POLE--(ϕ_p) The total flux per pole.

$$\phi_p = \frac{\phi_T C_p}{p}$$

TOOTH PITCH--(τ_s and $\tau_{s \frac{1}{3}}$) The stator slot pitch on the inside stator bore, and the stator slot pitch at a distance a third of the way up the tooth.

$$\tau_s = \frac{\pi d}{Q} \qquad \tau_{s 1/3} = \frac{\pi(d + \frac{2}{3} h_s)}{Q}$$

TOOTH DENSITY--(B_t) The flux density in the stator tooth at 1/3 of the distance from the minimum section.

$$B_t = \frac{\phi_T}{Q \ell_s b_{t 1/3}} \quad \text{where } b_{t 1/3} = \tau_{s 1/3} - b_s$$

CORE DENSITY--(B_c) The flux density in the stator core, without adding the stator to rotor leakage flux.

$$B_c = \frac{\phi_p}{2h_c \ell_s}$$

GRADE OF IRON-- Alloy identification and lamination thickness of stator iron.

1/2 MEAN TURN--(ℓ_t) The average length of one conductor.

$$\ell_t = \ell + L_E$$

where L_E = the end extension length

For random wound coils

$$L_E = .5 + \frac{K_t \pi y(d+h_s)}{Q}$$

where K_t = constant depending on the number of poles

K_t = 1.3 for 2 poles; 1.5 for 4 poles; and 1.7 for 6 poles and up


For formed coils

$$L_E = 2\ell_{e2} + \pi\left(\frac{h_1}{2} + d_b\right) + y h_{te}$$

where d_b = diameter of bender pin

h_{te} = is obtained from the diagram as shown

ℓ_{e2} = straight part of the coil extension beyond the core



RESISTANCE PER PHASE AT $_____\circ$ --(R_{ph}) The resistance per phase calculated at the expected coil temperature.

$$R_{ph} = \frac{n_s Q \ell_t R_{1000}}{12000 C_m^2} \times \frac{235 + X^\circ C}{260} = \rho \frac{n_s Q \ell_t}{m a_c C^2}$$

where ρ = resistivity at $X^\circ C = .91 \times 10^{-6} 100^\circ C$

R_{1000} = resistance per 1000 ft. of conductor at $25^\circ C$

$X^\circ C$ = expected coil temperature in $^\circ C$

EDDY FACTOR TOP-- The eddy factor of the top coil. Calculate this value at the expected operating temperature of the machine.

$$EF_{Top} = 1 + \left[.584 + \left(\frac{N_{st}^2 - 1}{16} \right) \left(\frac{h'_{st} \ell}{h_{st} \ell_t} \right)^2 \right] \frac{3.35}{1000} \left[\frac{h_{st}^n n_s f a_c}{b_s \rho'} \right]^2$$

where $\rho' = \rho \times 10^6$

N_{st} = number of strands per conductor in depth

h'_{st} = distance between centerline of strands in depth

h_{st} = height of uninsulated strand

EDDY FACTOR BOTTOM-- The eddy factor of the bottom coil at the expected operating temperature of the machine. Use same equation as E. F. top except use .0833 in place of .584.

DEMAGNETIZING FACTOR--(C_M and C_q) The ratio of the field ampere turns to the maximum sine wave stator ampere turns required to force

the same fundamental flux across the gap. The demagnetizing factor in the direct axis is

$$C_M = \frac{\alpha \pi + \sin \alpha \pi}{4 \sin \frac{\alpha \pi}{2}}$$

and the cross magnetizing factor in the quadrature axis is

$$C_q = \frac{1/2 \cos \frac{\alpha \pi}{2} + \alpha \pi - \sin \alpha \pi}{4 \sin \frac{\alpha \pi}{2}}$$

The above factors can be read directly from curve #9 and calculation by the above formulas is thus unnecessary.

AMPERE CONDUCTORS PER INCH--(A) The effective ampere conductors per inch of stator periphery. This factor indicates the "specific loading" of the machine. Its value will increase with the rating and size of the machine and also will increase with the number of poles. It will decrease with increases in voltage or frequency. A is generally higher in single phase machines than in polyphase ones.

$$A = \frac{I_{ph} n_s K_p}{C_t s}$$

REACTANCE FACTOR--(X) The reactance factor is the quantity by which the specific permeance must be multiplied to give percent reactance. It is the percent reactance for unit specific permeance, or the percent of normal voltage induced by a fundamental flux per pole per inch numerically equal to the fundamental armature ampere turns at rated current. Specific permeance is defined as the average flux per pole per inch of core length produced by unit ampere turns per pole.

$$X = \frac{100AK_d}{\sqrt{2} C_1 B_g}$$

CONDUCTOR PERMEANCE--(λ_i) The specific permeance for the portion of the stator current that is embedded in the iron. This permeance depends upon the configuration of the slot.

(a) For open slots.

$$\lambda_i = C_X \frac{20}{mq} \left[\frac{h_2}{b_s} + \frac{h_1}{3b_s} + \frac{b_t^2}{16t_s g} + \frac{.35b_t}{t_s} \right] \quad b_t = \text{tooth width at gap}$$

(b) For partially closed slots with constant slot width.

$$\lambda_i = C_X \frac{20}{mq} \left[\frac{h_o}{b_o} + \frac{2h_t}{b_o + b_s} + \frac{h_w}{b_s} + \frac{h_1}{3b_s} + \frac{b_t^2}{16t_s g} + \frac{.35b_t}{t_s} \right]$$

(c) For partially closed slots with constant tooth width.

$$\lambda_i = C_X \frac{20}{mq} \left[\frac{h_o}{b_o} + \frac{2h_t}{b_o + b_1} + \frac{2h_w}{b_1 + b_2} + \frac{h_1}{3b_2} + \frac{b_t^2}{16t_s g} + \frac{.35b_t}{t_s} \right]$$

(d) For round slots.

$$\lambda_i = C_X \frac{20}{mq} \left[.62 + \frac{h_o}{b_o} \right]$$

(e) For open slots with a winding of one conductor per slot.

$$\lambda_i = C_X \frac{20}{mq} \left[\frac{h_2}{b_s} + \frac{h_1}{3b_s} + .6 + \frac{g}{2t_s} + \frac{t_s}{4g} \right] \quad \left(C_X = \frac{1}{K_p^2 K_d^2} \right)$$

($K_X = 1$)

In all of the above formulas C_X is a reduction factor that is dependent upon the pitch and distribution of the winding.

$$C_X = \frac{K_X}{K_p^2 K_d^2} \quad \text{where } K_X = \frac{1}{4} \left(\frac{3y}{mq} + 1 \right) \text{ for 3 phase}$$

$$K_X = \frac{y}{mq} \text{ for 2 phase}$$

Values of C_X versus percent pitch for three phase windings are plotted on Graph #1. These values assume a distribution factor of .955. See Graph #1.

END WINDING PERMEANCE--(λ_E) The specific permeance for the end extension portion of the stator winding.

$$\lambda_E = \frac{6.28}{\ell K_d^2} \left[\frac{\phi_E L_E}{2n} \right] K_E$$

(Obtain the value of $\phi_E L_E$ from Graph #1

$$K_E = \frac{\text{Calculated value of } L_E}{\text{Value of } L_E \text{ from Graph \#1}} \quad (\text{for machines of } d > 8'')$$

$$K_E = \sqrt{\frac{\text{Calculated value of } L_E}{\text{Value of } L_E \text{ from Graph \#1}}} \quad (\text{for machines of } d < 8'')$$

LEAKAGE REACTANCE--(X_ℓ) The leakage reactance of the stator for steady state conditions

$$X_\ell = X(\lambda_i + \lambda_E)$$

In the case of two phase machines a component due to belt leakage must be included in the stator leakage reactance. This component is due to the harmonics caused by the concentration of the MMF into a small number of phase belts per pole and is negligible for three phase machines.

$$\lambda_B = \frac{.1d}{pg_e} \left[\frac{\sin \frac{3y}{mq} \times 90^\circ}{K_p} \right]$$

$$X_\ell = X(\lambda_i + \lambda_E + \lambda_B) \quad \text{where } \lambda_B = 0 \text{ for 3 phase machines.}$$

AIR GAP PERMEANCE--(λ_a) The specific permeance of the air gap.

$$\lambda_a = \frac{6.38d}{pg_e}$$

REACTANCE OF ARMATURE REACTION--(X_{ad} and X_{aq}) The "fictitious reactance" due to armature reaction. In the direct axis

$$X_{ad} = X \lambda_a C_l C_M$$

and in the quadrature axis

$$X_{aq} = X C_q \lambda_a$$

WEIGHT OF COPPER-- The weight in lbs. of the stator copper.

$$\# = .321 n_s Q a_c \ell_t$$

WEIGHT OF IRON-- The weight in lbs. of the stator iron.

$$\# = .238 \left[b_{tm} Q \ell_s h_s + \pi (D - h_c) h_c \ell_s \right]$$


ROTOR

SINGLE GAP--(g) The single air gap. Also record the effective air gap (g_e) inch

$$g_e = K_s g$$

AUXILIARY GAP, OUTER--(g_2) inches


g_2 = Obtain length from design layout




AUXILIARY GAP, INNER--(g_3) inches

g_3 = Obtain length from design layout

STEPPED GAP (g_2)



TAPERED GAP (g_3)



ROTOR DIAMETER--(d_r) The outside diameter of the rotor.

$$d_r = d - 2g$$

PERIPHERAL SPEED--(V_r) The velocity of the rotor surface in feet per minute.

$$V_r = \frac{\pi d_r \text{ RPM}}{12}$$

POLE PITCH--(t_p) The pole pitch measured at the inside diameter of the stator.

$$t_p = \frac{\pi d}{p}$$

Also record the ratio of the pole arc to the pole pitch (α).

$$\alpha = \frac{b_h}{t_p}$$


b_h = Average pole head width under stator stack

For pole configuration below

$$\alpha = \frac{\alpha_e + \alpha_m}{2}$$

α_m = Per unit pole embrace (pole middle)

α_e = Per unit pole embrace (pole end)




NORTH POLE AREA--(a_{NP}) The effective cross sectional area of the pole.

$$a_{NP} = b_{NP} \ell_p K_i$$

Values of K_i are obtained from chart in Stator Section.

For solid iron $K_i = 1.0$



SOUTH POLE AREA--(a_{SP}) The effective cross sectional area of the south pole at the entry edge of the stator.

$$a_{SP} = b_{SP} t_{SP}$$


GRADE OF IRON--Alloy of rotor iron and lamination thickness if laminations are used.

URNS PER COIL--(N_C) The number of field turns per coil.


CONDUCTOR SIZE--The bare and insulated sizes of the field conductors. Also indicate the type of insulation.

CONDUCTOR AREA--(a_{cr}) The actual area of the conductor taking into account the corner radius. See stator area of conductor for typical corner radii values.


The flux circuit of the two-coil Lundell generator looks like this.




The rotor flux circuit is:



VIEW OF BOTH NORTH-POLE AND SOUTH-POLE FLUX CIRCUITS
SHOWING THE MMF DROPS IN THE TWO-COIL LUNDELL BRUSH-
LESS AC GENERATOR



And for the entire machine, the flux circuit looks like this.



Flux Circuit for 2-Coil Lundell A-C Generator

NOTE: The machine could be represented by showing two identical flux circuits in the south pole, from and including F_{SP} to and including F_{y4} . Instead the calculations are adjusted to fit the single circuit.

The leakage permeances in the flux circuit are:

POLE HEAD END LEAKAGE

$$P_1 = \frac{\mu \text{Area}}{\ell} = \frac{3.19 (\gamma_P t_{SP}) (P)}{\ell_1}$$

POLE HEAD SIDE LEAKAGE (P_2)

$$P_2 = \frac{\mu \text{Area}}{\ell} = \frac{3.19 (\ell_{NP} + \ell_1) t_{SP} (P)}{\ell_2}$$

POLE BODY END LEAKAGE (P_3)

$$P_3 = \frac{\mu \text{Area}}{\ell} = \frac{3.19 \ell_P (h_P - t_{SP}) P}{(d_r - d_{os}) \frac{\pi}{8} - t_{SP}}$$

POLE BODY SIDE LEAKAGE

$$P_4 = \frac{\mu \text{Area}}{\ell} = \frac{3.19 \left[\left(\frac{d_r - d_{os}}{2} \right) - t_{SP} \right] (\ell_P + \ell_1) P}{\left(\frac{d_r}{2} - t_{SP} \right) \sin \frac{2\pi}{P} \left[1 - \frac{\alpha}{4} \right] - \frac{b_{NP}}{2}}$$

For six poles and up.

$$P_4 = \frac{3.19 \left[\frac{d_r}{2} - t_{SP} \right] (\ell_P + \ell_1) P}{\frac{d_r - d_{os}}{2} - t_{SP}}$$

For four pole generators only.

COIL LEAKAGE PERMEANCE TO A NORTH POLE (P_5)

$$P_5 = \frac{\mu \text{Area}}{\ell} = \frac{3.19 b_P (\ell_6)^{\frac{2}{3}} (2P)}{\ell_c}$$

Obtain ℓ_c from layout.

P_5 = Total leakage permeance for path 5 on both ends of the rotor

COIL LEAKAGE PERMEANCE TO A SOUTH POLE (P_6)

$$P_6 = \frac{\mu \text{Area}}{\ell} = \frac{3.19 \ell_c \alpha (d_r - 2t_{SP}) \frac{\pi}{P} (P)}{\ell_6}$$

= Total leakage permeance for path 6 on both ends of the rotor

$$\ell_6 = \left(\frac{d_r - d_{os}}{2} \right) - t_{SP}$$

STATOR CORE TO ROTOR SKIRT, flux leakage permeance path (P_7)

$$P_7 = \frac{\mu \text{Area}}{\ell}$$

$$\text{Area} = \pi (d_r + h_c) \frac{h_c + \ell_{SK}}{2} \text{ in}^2$$

The leakage is from 1/2 the stator end surface on each side of the stator, making the total leakage surface calculated above.

However - 1/2 of the leakage flux is useful and generates voltage in the stator conductors. So for tooth density, pole density and air-gap flux calculations the leakage flux area is

$$\begin{aligned}\text{Area} &= \frac{1}{2} \pi (d_r + h_c) \frac{h_c + \ell_{SK}}{2} \\ &= \frac{\pi}{4} (d_r + h_c) (h_c + \ell_{SK})\end{aligned}$$



$$\text{Length} = \pi \frac{h_c}{2} \text{ inches}$$


h_c = stator height from bore to back-iron surface, inches

$$\begin{aligned}P_7 &= \frac{3.19 \frac{\pi}{4} (d_r + h_c) (h_c + \ell_{SK})}{\pi \frac{h_c}{2}} \\ &= \frac{3.19 (d_r + h_c) (h_c + \ell_{SK})}{2h_c}\end{aligned}$$

NON-MAGNETIC MATERIAL


MAGNETIC STEEL







$$l_3 = \left(\frac{d_r - d_{os}}{4} \frac{\pi}{2} \right) - t_{SP} = (d_r - d_{os}) \frac{\pi}{8} - t_{SP}$$

$$P_3 = \frac{3.19 \ell_P (h_P - t_{SP}) P}{\ell_3}$$




$$P_4 = \frac{3.19 \left[\frac{d_r}{2} - t_{SP} \right] (l_P + l_1) P}{\frac{d_r}{2} - t_{SP} \sin \frac{2\pi}{P} \left[1 - \frac{\alpha}{4} \right] - \frac{b}{2} \frac{NP}{2}}$$






TWELVE (12) POLE ALTERNATOR


$$l_4 = \left(\frac{d_r}{2} - t_{SP} \right) \sin \frac{2\pi}{P} \left[1 - \frac{\alpha}{4} \right] - \frac{b_{NP}}{2}$$






FOUR (4) POLE ALTERNATOR




EIGHT (8) POLE ALTERNATOR








FLUX LEAKAGE ACROSS FIELD COILS



$$P_6 = \frac{3.19 l_c \alpha (d_r - 2t_{SP}) \frac{\pi}{P} (P)}{l_6}$$

$$= \frac{3.19 l_c \alpha (d_r - 2t_{SP}) \pi}{l_6}$$

Leakage Fluxes ϕ_5 and ϕ_6
(Leakage across the field coil ϕ_6 ,
and through the field coil ϕ_5)



d_{os} = diameter of outer shaft

A_{y2} = area of yoke at smallest section

$$A_{y2} = d_{os} t_{y2}$$

The leakage flux ϕ_5 and ϕ_6 add to the flux in the yoke member y_2 but of the two leakage fluxes, only ϕ_5 adds to the flux crossing air gap g_3 .

NO LOAD SATURATION

1.05 ϕ_T = Estimated total flux including flux leakage from stator to rotor skirt - path 7.

$\frac{1.05 \phi_T}{A_g}$ = Estimated air gap density at no load.

$\frac{1.05 \phi_T}{A_T}$ = Estimated tooth density at no load.

$\frac{1.05 \phi_P}{2A_C}$ = Estimated core density

MMF drop through main air-gap = F_g

$$F_g = \frac{B_g \text{ from above est.}}{3.19} (\ell_g)$$

MMF drop through teeth at tooth density est. above = F_T

MMF drop through core at core density est. above

Total MMF drop across flux leakage path from stator core to rotor skirt (Path 7) = $F_g + F_T + F_C$.

The drop across the south pole is negligible at no load and not likely to be large at any load. For this reason it is ignored.

Leakage flux through leakage path seven. Leakage from stator back-iron to rotor skirt = ϕ_7

$$\phi_7 = \text{MMF}_7 (P_7) = (F_g + F_T + F_C) P_7$$

Compare ϕ_7 with estimated value

$$\text{Estimated } \phi_7 = \phi_P (.05) P$$

$$\text{If } \frac{\phi_7 - \phi_P (.05) P}{\phi_7} = \pm .10 \text{ or less, proceed. If greater than } .10$$

repeat calculations using

$$\frac{\phi_7 + P\phi_P}{P\phi_P} \frac{(\phi_T)}{A_g} = B_g$$

$$\frac{(\phi_7 + P\phi_P)}{P\phi_P} \frac{\phi_T}{A_T} = B_T$$

Obtain new ϕ_7

Calculate leakage fluxes 1, 2, 3, 4

Pole to pole leakage fluxes are

$$\phi_1, \phi_2, \phi_3, \phi_4$$

$$\phi_{1,2,3,4} = (2F_g + 2F_T + F_C) (P_1 + P_2 + P_3 + P_4)$$

$$B_{NP} = \frac{\phi_P + \frac{\phi_{1-4} + \phi_7}{P}}{A_{NP}} = \text{north-pole flux density}$$

$$B_{SP} = \frac{\phi_P + \frac{\phi_{1-4} + \phi_7}{P}}{2A_{SP}} = \text{south-pole (tube) flux density}$$

$$F_{NP} = \text{MMF drop corresponding to } B_{NP}$$

F_{SP} = MMF drop corresponding to B_{SP}

Flux density in auxiliary air-gap = B_{g2}

$$B_{g2} = \frac{\phi_P + P + \phi_{1-4} + \phi_7}{2A_{g2}}$$

MMF drop across auxiliary air-gap = F_{g2}


$$F_{g2} = \frac{B_{g2}}{3.19}$$

$$A_{y4} = \frac{d_{y4}^2}{4} = \text{Area Shaft (in}^2\text{)}$$

Flux density in shaft = B_{y4}

$$B_{y4} = \frac{\phi_P + P + \phi_{1-4} + \phi_7}{A_{y4}}$$

$MMF_{y4} = F_{y4} = H \ell_{y4}$ where H is the AT/in. at B_{y4} for shaft steel.



Flux density in 2nd auxiliary air gap = B_{g3}

$$B_{g3} = \frac{\phi_P \times P + \phi_{1-4} + \phi_7}{2A_{g3}}$$

MMF drop across 2nd auxiliary air-gap = F_{g3}

$$F_{g3} = \frac{B_{g3}}{3.19} \ell_{g3}$$

Leakage flux from north pole (spider pole) through the field coil = ϕ_5

$$\phi_5 \text{ (first calculation)} = \left[F_{g2} + F_{SP} + (2F_g) + 2F_T + F_C + F_{NP} \right] P_5$$

Calculate new MMF drop in NP

$$B_{NP} = \frac{\phi_P + \frac{\phi_{1-4} + \phi_7 + \phi_5}{P}}{A_{NP}}$$

$$MMF_{NP} = (H_{at} B_{NP}) H_P$$

$$\text{New } B_{g3} = \frac{\phi_P \times P + \phi_{1-4} + \phi_7 + \phi_5}{A_{g3}}$$

$$\text{New } F_{g3} = \frac{B_{g3}}{3.19} \ell_{g3}$$

Leakage flux across field coils from inner yoke to south-pole tube = ϕ_6

$$\phi_6 = \left[F_{SP} + 2F_g + 2F_T + F_C + F_{NP} + F_{g1} + F_{g3} \right] P_6$$

Add ϕ_6 to flux in yoke and tube.

Calculate flux density in the tube at the inboard edge of the auxiliary air gap g_2 to be sure that the tube is not saturating at that point.

$$\text{Final } B_{g2} = \frac{(\phi_P \times P) + \phi_{1-4} + \phi_7 + \phi_6}{A_{g2}}$$

$$\text{Final } F_{g2} = \frac{\text{Final } B_{g2} \ell_{g2}}{3.19}$$

$$F_{y2} = \frac{\phi_P \times P + \phi_{1-4} + \phi_7 + \phi_6 + \phi_5}{2A_{y2}}$$

$$A_{y2} = \pi d_{os} t_{y2} = \text{Smallest section of the yoke as shown in figure}$$

Total ampere turns drop at no load is

$$F_{NL} = 2F_g + F_T + F_C + F_{NP} + F_{SP} + F_{g2} + F_{y2} + F_{y3} + F_{g3} + F_{y4}$$

REACTANCES AND TIME CONSTANTS

X_{ad} = The fictitious reactance due to armature reaction in the direct axis.

$$X_{ad} = \frac{.9 n_e I_{ph} \ell_m t_d}{P (2F_g + F_{g2} + F_{g3})} \times 100$$

X_{aq} = The fictitious reactance due to armature reaction in the quadrature axis.

$$X_{aq} = \frac{C_q X_{ad}}{C_m 1} \times 100$$

SYNCHRONOUS REACTANCE--(X_d and X_q) The steady state short circuit reactance. In the direct axis

$$X_d = X_\ell + X_{ad}$$

and in the quadrature axis

$$X_q = X_\ell + X_{aq}$$



When current is suddenly applied to a generator stator (a step load) there is no flux linkage with the field winding during the first instant, and during that first instant all flux due to the armature mmf is forced through the field coil leakage paths.



The inductance of the field coil leakage paths in the direct axis is L_d' and the reactance is

$$X_d' = 2\pi f L_d'$$

Since X_d' includes stator leakage reactance, X_d' can be written as

$$X_{du}' = X_F' + X_\ell = \text{The unsaturated transient reactance.}$$





X'_d is usually considered to be about 88% to 90% of X'_{du} and the lower value is called the saturated transient reactance. It is the value found by testing at rated voltage.

THE EFFECTIVE FIELD LEAKAGE REACTANCE (X'_F). The reactance which added to the stator leakage reactance gives the transient reactance X'_{du} .

When unit fundamental armature ampere turns are suddenly applied on the direct axis, an initial field current (I_f) will be induced. The value of this initial field current will be just enough to make the net flux inter-linking the field because of the field current and the armature current zero. The field ampere turns will equal the armature ampere turns.

$$X'_F = X \frac{P}{\ell} \left[\frac{\frac{C_1^2}{C_P} P_g^2}{2 \pi P_e \left(\frac{g_e'}{g_e} \right)^2} \right] \%$$

$$X'_{du} = X'_F + X_\ell$$

$$g_e' = g_e \left(\frac{2F_g + F_{g2} + F_{g3}}{2F_g} \right)$$

where F_g , F_{g2} , F_{g3} are calculated at rated load.

F_g = Ampere turns drop across single main air gap (g_e)

F_{g2} = Ampere turns drop across the outer auxiliary gap (g_2)

F_{g3} = Ampere turns drop across the inner auxiliary gap (g_3)

$$P_e = \frac{\phi_{g2} @ NL}{I_f N_c @ NL}$$

UNSATURATED TRANSIENT REACTANCE -- (X'_{du}) The transient reactance due to the field winding assuming unsaturated conditions.

$$X'_{du} = X_l + X_F$$


SATURATED TRANSIENT REACTANCE -- (X'_d) The transient reactance due to the field winding assuming normally saturated conditions.

$$X'_d = .88 X'_{du}$$

NUMBER OF DAMPER BARS -- (n_b) The number of damper bars per pole.

BAR SIZE -- The size of the damper bars.

BAR PITCH -- (t_b) The damper bar pitch. This is the distance between the centerlines of adjacent damper bars. Also indicate the height of the slot opening above the damper bar (h_{bo}) and the width of this opening (b_{bo}).



DAMPER LEAKAGE REACTANCE -- (X_{Dd} and X_{Dq}) The leakage reactance of the damper winding. In the direct axis the dimensions corresponding to the end bar next to the pole tip are used.


For rectangular square damper bars

$$\lambda_b = 6.38 \left(\frac{h_{bo}}{b_{bo}} + \frac{h_{b1}}{3b_{b1}} + .5 \right)$$

$$\lambda_{pt} = 6.38 \left[\frac{b_n - t_b (n_b - 1)}{3g_e} \right]$$

$$\lambda_{Dd} \left[\cos \left\{ \frac{(n_b - 1) t_b \pi}{2t_p} \right\} \right] \frac{(\lambda_b + \lambda_{pt}) \lambda_F}{\lambda_b + \lambda_{bt} + \lambda_F}$$

$$X_{Dd} = X \lambda_{Dd}$$



In the quadrature axis the dimensions corresponding to the bar in the center of the pole is used.

For rectangular square bars

$$\lambda_{Dq} = \frac{20t_b}{t_r} \left[\frac{h_{bo}}{b_{bo}} + \frac{h_{b1}}{3b_{b1}} + .5 + \frac{g}{t_b} \right]$$

$$X_{Dq} = X \lambda_{Dq}$$

For round damper bars use the constant 0.62 in place of $h_{b1}/3b_{b1}$ in the above formulas.

SUBTRANSIENT REACTANCE -- (X_d'' and X_q'') The subtransient reactance due to the damper winding. In the direct axis

$$X_d'' = X_\ell + X_{Dd}$$

and in the quadrature axis

$$X_q'' = X_\ell + X_{Dq}$$

~~If the machine does not have a damper winding~~

$$X_d'' = X_d'$$

$$X_q'' = X_q'$$

NEGATIVE SEQUENCE REACTANCE -- (X_2) The reactance presented to negative sequence currents in the stator of the generator.

When negative sequence currents are applied to the stator winding they produce a backward rotating mmf traveling at synchronous speed with respect to the stator and at twice synchronous speed with respect to the rotor.

Currents of twice rated frequency are induced in the pole head winding or in the solid pole head, keeping the flux linkages of the pole circuits at almost zero value. The flux due to the armature current is forced into the damper or pole head winding leakage paths. These paths are the same as for the subtransient reactances.

L_2 = Armature flux linkages per ampere when negative sequence currents are flowing. This includes the stator leakage inductance also.

$$X_2 = \frac{X_d'' + X_q''}{2}$$

or the average between the quadrature and direct axis subtransient reactances. It is approximately equal to X_d'' or to $X_{Dd}'' + X_\ell$

where

$$X_{Dd}'' = \text{Direct axis damper leakage}$$

NEGATIVE SEQUENCE REACTANCE -- (X_2) The reactance presented to the flux field which rotates at synchronous speed in a direction opposite to that of the rotor.

$$X_2 = \frac{X_m \left[4\zeta + 4\zeta^2 + n^2 \right]}{n^2 + 4(1 + \zeta)^2} + X_l$$

where $\zeta = \frac{X_D}{X_m}$

$$X_m = \frac{X_{ad}}{C_1 C_m} \left(\frac{2F_g + F_{g2} + F_{g3}}{F_{NL}} \right)$$

$$X_D = X \left[\frac{20}{n_b} \left(.62 + \frac{h_{bo}}{b_{bo}} \right) \right] + \frac{5X_m}{6n_b^2} \quad \text{For round slots}$$

$$X_D = X \left[\frac{20}{n_b} \left(\frac{h_{b1}}{3b_{b1}} + \frac{h_{bo}}{b_{bo}} \right) \right] + \frac{5X_m}{6n_b^2} \quad \text{For rectangular slots}$$

$$n = \frac{R_D}{X_m}$$

R_D = Damper resistance

APPROXIMATE CALCULATION OF NEGATIVE SEQUENCE IMPEDANCE

$R_2 + j X_2 = \tau_2$ = Negative sequence impedance - %

$$R_2 = \frac{2R_D}{n^2 + 4(1 + \zeta)^2} + R_s$$

$$X_2 = \frac{X_m [4\xi + 4\xi^2 + n^2]}{n^2 + 4(1 + \xi)^2} + X_\ell$$

R_D = damper resistance

$$R_D = \frac{100 X_P (9 \times 10^6)}{f \ell} \left[\frac{\ell_b}{n_b a_b P} + \frac{.637 d_{dr}}{a_{dr} P^2} \right] \%$$

P = poles

ρ = resistivity of bar and end ring materials ($.692 \times 10^{-6}$ for copper at 77 F)

f = frequency

ℓ = stack length

ℓ_b = active bar length

a_b = bar cross section (in.²)

d_{dr} = mean diameter of damper end ring

a_{dr} = cross section of damper end ring

$n = R_D / X_m$

$$X_m = \frac{X_{ad}}{C_1 C_m} \left(\frac{2F_g + F_{g2} + F_{g3}}{F_{NL}} \right)$$

$\xi = X_D / X_m$

$$X_D = X \left[\frac{20}{n_b} \left(.62 + \frac{h_{bo}}{b_{bo}} \right) \right] + \frac{5X_m}{6n_b^2} \quad \text{For round slots}$$

$$X_D = X \left[\frac{20}{n_b} \left(\frac{h_{b1}}{3b_{b1}} + \frac{h_{bo}}{b_{bo}} \right) \right] + \frac{5X_m}{6n_b^2} \quad \text{For rectangular slots}$$

R_s = stator winding resistance - %

X_l = stator leakage reactance - %

ZERO SEQUENCE REACTANCE -- (X_o) The reactance drop across any one phase (star connected) for unit current in each of the phases. The machine must be star connected for otherwise no zero sequence current can flow and the term then has no significance.

$$X_o = X \left[\frac{K_{Xo}}{K_X} (\lambda_i + \lambda_{Bo}) + \frac{20(h_1 + 2h_3)}{12mqK_p^2 K_d^2 K_s^2} + .2 \lambda_E \right]$$

$$\lambda_{Bo} = \frac{K_{Xo}}{K_X} \lambda_{Dq}$$

$$\lambda_{BWo} = \frac{K_{Xo}}{K_p^2} (.07 \lambda_a)$$

for machines with damper windings

$$\lambda_{Bo} = \frac{\lambda'_{Bo} + \lambda_{BWo}}{(\lambda'_{Bo}) (\lambda_{BWo})}$$

and for machines without damper windings

$$\lambda_{Bo} = \lambda_{BWo}$$

and

$$K_{Xo} = \frac{3y}{mq} - 2$$

$$K_X = \left(\frac{3y}{4mq} + \frac{1}{4} \right) \text{ for pitches of } 66\frac{2}{3}\% \text{ to } 100\%$$

$$K_X = \left(\frac{3y}{2mq} - \frac{1}{4} \right) \text{ for pitches of } 33\frac{1}{3}\% \text{ to } 66\frac{2}{3}\%$$

for a one conductor per slot winding

$$K_{X0} = K_X = 1$$

OPEN CIRCUIT TIME CONSTANT -- (T'_{do}) The time constant of the field winding with the stator open circuited and with negligible external resistance and inductance in the field circuit.

$$T'_{do} = \frac{L_F}{R_F} \text{ second}$$

TRANSIENT TIME CONSTANT -- (T'_d) The time constant of the transient reactance component of the alternating wave.

$$T'_d = \frac{X'_d}{X_d} T'_{do}$$

ARMATURE TIME CONSTANT -- (T_a) The time constant of the DC component.

$$T_a = \frac{X_2}{(2) (100 \text{ fr}_a)} \text{ seconds}$$

$$r_a = \frac{\text{Stator } I^2 R \text{ (KW)}}{\text{Rated KVA}}$$

SUBTRANSIENT TIME CONSTANT -- (T''_d) The time constant of the sub-transient component of the alternating wave. This value has been determined empirically from tests on large machines and

$$T''_d = .035 \text{ second at 60 cycles.}$$

$$T''_d = .005 \text{ second at 400 cycles.}$$

LOAD SATURATION - FULL LOAD

$$E_{NL} = E_{ph} + IR$$

$$\psi = \tan^{-1} \left[\frac{\sin \theta + X_q}{\cos \theta} \right]$$

= Angle between output current and ℓ_d (see figure)

$$\theta = \text{Power factor angle} = \cos^{-1} [\text{P. F.}]$$

$\epsilon = \psi - \theta$ = angle between terminal volts and ℓ_d (see figure)

$$e_d = \cos \epsilon + X_d \sin \psi$$

= Voltage that would be generated at no load and no saturation - the air-gap voltage behind the synchronous reactance.

$$F_{gL1} = e_d F_{gNL}$$

= Air-gap ampere turns under load if there were no stator leakage flux from the core to the rotor skirt.

F_{gNL} = Air-gap ampere turns at no load without the stator leakage flux from the core to the rotor skirt.

$$F_{TL1} = F_{TNL} (1 + \text{P. F.})$$

= First approximation of the teeth ampere turn drop at full load.

$F_{CL} = F_{CNL}$ approximately because the core to rotor leakage flux does not increase the core density. The stator tooth to tooth leakage flux approximately off-sets the theoretical increase in core flux under load.

$$\phi_{7-1} = P_7 [F_{gL1} + F_{TL1} + F_C]$$

= First approximation of the leakage flux from the stator back-iron to the rotor skirt.

$$F_{gL} = F_{gL1} + \frac{\phi_{7-1}}{3.19} g'$$

= Total air-gap ampere turns at full load.

$$\phi_{TL1} = \phi_{NL} + \frac{\phi_{7-1}}{C_P}$$

= Theoretical total flux at full load. First approximation

$$B_{TL} = \frac{\phi_{TL}}{A_T}$$

= Tooth density at full load above the north pole.

$$F_{TL} = \ell_T H_{BTL} (1 + P.F.)$$

H_{BTL} = Ampere turns drop/inch corresponding to a tooth density of B_{TL}

$$\phi_{7L} = P_7 [F_{gL1} + F_{TL} + F_C]$$

$$\phi_{TL} = \phi_{NL} + \frac{\phi_7}{C_P}$$

= Theoretical total flux at F. L. second approximation.

$$\phi_{1,2,3,4} = (P_1 + P_2 + P_3 + P_4) (2F_{gL} + 2F_{TL} + F_C)$$

= Leakage flux from pole to pole in the rotor.

$$\phi_{PL} = \phi_{PNL} \left[\ell_d - .0093 X_{ad} \sin \psi \right]$$

$$\phi_{PL} = 1.10 \phi_{PNL} \text{ for } \cos \theta = >.90$$

$$\phi_{PNL} = \text{Flux/pole Calc at NL voltage} = V + IR$$

$$\phi_{SP-FL} = \frac{\phi_{PL}}{2} + \frac{\phi_{1234}}{2P}$$

= Flux in south pole

A_{SP} = Area of south pole entry section. Section at edge of stator stack.

$$B_{SP-FL} = \frac{\phi_{SP-FL}}{A_{SP}}$$

= Flux density in S. P. at full load

$$F_{SP-FL} = H_{SP-FL} \ell_P$$

= Ampere turns drop through S. P. at FL

$$\phi_{NP-FL} = \phi_{PL} + \frac{\phi_7}{P} + \frac{\phi_{1234}}{P}$$

= Flux in north pole without leakage flux ϕ_5

$$A_{NP} = \text{Area of north pole (in.}^2\text{) at base}$$

$$B_{NP-FL-1} = \frac{\phi_{NP-FL}}{A_{NP}}$$

= First approximation of north pole flux density at full load

$$F_{NP-FL-1} = H_{NP-FL} P$$

= Ampere turns drop in north pole - first approximation

P_6 = Leakage permeance across field coil from rotor shaft outer diameter to the inner surface of the rotor skirt

$$\phi_6 = P_6 [F_{SP-FL} + F_{NP-FL} + 2F_g + 2F_T + F_C]$$

= Leakage flow across field coil

$$A_{SK} = \pi (d_r - t_{SK}) t_{SK} \text{ in}^2$$

= Area of skirt at entry edge of auxiliary air-gap g_2

$$\phi_{SK-FL} = (\phi_{SP-FL}) \frac{P}{2} + \phi_7 + \frac{\phi_6}{2}$$

$$B_{SK-FL} = \frac{\phi_{SK-FL}}{A_{SK}}$$

= Flux density in the rotor skirt at full load

$$F_{SK-FL} = H_{SK-FL} l_{SK}$$

This should be an insignificant ampere turn drop.

The calculation of B_{SK-FL} is in the program for a check on a possible bottle-neck

P_5 = Permeance of leakage flux path from north pole through the field coil to the yoke y_2

$$B_{g2-FL} = \frac{\phi_{SK-FL}}{A_{g2}} \quad \left\{ \begin{array}{l} \text{Flux density in auxiliary air gap} \\ \text{at full load} \end{array} \right.$$

$$F_{g2-FL} = \frac{(B_{g2-FL})}{3.19} l_g$$

= Ampere turn drop across auxiliary air gap at full load

$$\phi_5 = P_5 [F_{NP-FL} + 2F_{g-FL} + 2F_{T-FL} + F_C + F_{SP-FL} + F_{g2-FL}]$$

= Leakage flux through field coil from north pole to yoke y_2

$$\phi_{y2-FL} = \phi_{SK-FL} + \frac{\phi_5}{2}$$

$$B_{y2-FL} = \frac{\phi_{y2-FL}}{A_{y2}}$$

Where A_{y2} is smallest cross-section (at base of yoke section)

$$F_{y2-FL} = \frac{H_{y2-FL} l_{y2}}{3}$$

= Ampere turn drop in the yoke section y_2 . This MMF value should be insignificant and the calculation is here to call attention to a possible saturation point.


If the yoke section is made straight, of uniform thickness, all of the ampere turn drop will be in the lower one-half of the yoke.

$$B_{y3-FL} = \frac{\phi_{y2-FL} \frac{S_t - t_{y2}}{S_t}}{A_v}$$

= Flux density in the stationary yoke section y_3 at the entry to the auxiliary air-gap g_3

$$F_{y3-FL} = H_{y3-FL} (S_t - t_{y2})$$

H_{y3-FL} = Ampere turns drop/inch for material at flux density B_{y3-FL}



$$B_{g3-FL} = \frac{\phi_{y2-FL}}{A_{g2}}$$

$$F_{g3-FL} = \frac{B_{g3-FL}}{3.19} (g_3)$$

= Ampere turns drop across auxiliary air-gap g_3 at full load

$$B_{y4-FL} = \frac{(\phi_{y2-FL})}{A_{y4}}$$

= Flux density in shaft at entry to north poles

$$B_{NP-FL} = \frac{2 (\phi_{y2-FL})}{A_{NP}}$$

= Flux density in north pole at base

$$F_{NP-FL} = \frac{H_{NP-FL} h_P}{2}$$

$$F_{FL} = \left[2F_g + 2F_T + F_C + F_{SP} + F_{NP} + F_{SK} + F_{g2} + F_{y2} + F_{y3} \right. \\ \left. + F_{g3} + F_{g4} \right]$$

LOAD SATURATION AT .5, 1.5, 2.0 PER-UNIT LOAD

$$E_{NL} = E_{ph} + IR \text{ (P. U. load)}$$

$$\psi = \tan^{-1} \left[\frac{\sin \theta + X_q \text{ (P. U. load)}}{\cos \theta} \right]$$

$$\ell_d = \cos \epsilon + X_d \text{ (P. U. load)} \sin \psi$$

$$\frac{\phi_{PL}}{\phi_{PNL}} = \left[\ell_d - .93 X_{ad} \text{ (P. U. load)} \sin \psi \right]$$

$$\frac{\phi_{PL}}{\phi_{PNL}} = 1.10 \text{ if } \cos \theta > .90$$

$\frac{\phi_{PL}}{\phi_{PNL}}$ is the increase in pole flux required because of distortion of the wave form and resultant decrease in C_1

ϕ_{PNL} is value calculated at NL voltage = $V + IR$

STATOR TOOTH LOSS -- (W_{TNL} , W_{TFL} , W_{TOL}) The no load loss (W_{TNL}) consists of eddy current and hysteresis losses in the iron. For a given frequency the no load tooth loss will vary as the square of the flux density.

$$W_{TNL} = .453 (t_{s1/3} - b_s) Q \ell_s h_s K_Q \text{ watts}$$

$$K_Q = \left(\frac{B_t}{77.4} \right)^2 \times K$$

K = Watts/lb loss at 77.4 kl/in² density. Take from U.S.S. Steel Manual

The stator tooth loss under load (W_{TFL} & W_{TOL}) is increased because of the parasitic fluxes caused by the ripple due to the rotor damper bar slot openings.

$$W_{TFL} = \left[2 (.27 X_d)^{1.8} + 1 \right] W_{TNL}; (X_d \text{ in per unit})$$

For W_{TOL} use X_d corresponding to the overload condition.

STATOR CORE LOSSES -- (W_C) The stator core losses are due to eddy currents and hysteresis and do not change under load conditions. For a given frequency the core loss will vary as the square of the flux density.

$$W_C = 1.42 (D - h_c) h_c \ell_s K_Q$$

K_Q = Watts per pound loss from U. S. S. Electrical Steel Sheets Manual at a density of B_C .

POLE FACE LOSSES -- (W_{PNL} , W_{PFL} , W_{POL}) The pole surface losses are due to the slot ripple caused by the stator slots. They depend upon the width of the stator slot opening, the air gap, and the stator slot ripple frequency. The no load pole face loss (W_{PNL}) is calculated from Graph #2. $K_1 = 7.0$ for solid pole faces. Graph #2 is plotted on the basis of open slots and thus B_s on the curve equals b_o for partially closed ones. The pole face loss under load (W_{PFL} , W_{POL}) is calculated as

$$W_{PFL} = \left[\left(\frac{K_{sc} I_{ph} n_s}{c F_g} \right)^2 + 1 \right] W_{PNL}$$

K_{sc} is obtained from Graph #3.

For W_{POL} use I_{ph} corresponding to the overload phase current.

DAMPER -- (W_{DNL} , W_{DFL} , W_{DOL}) The loss produced by the slot ripple in the damper winding. At no load this loss is calculated from curves #7 and #8. The damper loss under load (W_{DFL} , and W_{DOL}) for polyphase machines is calculated as

$$W_{DFL} = \left[\left(\frac{K_{sc} I_{ph} n_s}{c F_g} \right)^2 + 1 \right] W_{DNL}$$

K_{sc} is obtained from Graph #3.

For W_{DOL} use I_{ph} corresponding to the overload phase current.

STATOR I^2R -- The copper loss based on the DC resistance of the winding. Calculate for the maximum expected operating temperature.

$$I^2R = m I_{ph}^2 R_{ph}$$

EDDY -- The stator I^2R loss due to skin effect.

$$\text{Eddy Loss} = \left[\left(\frac{\text{Eddy Factor Top} + \text{Eddy Factor Bottom}}{2} \right) - 1 \right] \text{Stator } I^2R$$

ROTOR I^2R -- The copper loss in the field winding.

$$I^2R = I_f^2 R_f$$

SUM OF THE LOSSES -- The total losses at the various loads.

RATING -- The kilowatt rating of the generator.

RATING + LOSS -- The sum of the total losses and the KW rating.

PERCENT LOSS -- The total loss divided by the rating plus total loss.

PERCENT EFFICIENCY -- (100% - % loss).

STATOR WATTS/SQ. IN. -- The stator watts loss per sq. in. of stator periphery.

$$\text{Watts/in}^2 = \frac{\text{Stator (Tooth Loss + Core Loss + } I^2 R \text{ + Eddy Loss)}}{\pi D \ell}$$

ROTOR WATTS/SQ. IN. -- The rotor watts loss per sq. in. of rotor periphery.

$$\text{Watts/in}^2 = \frac{\text{Pole Face Loss + Damper Loss + Rotor } I^2 R}{\pi d_r \ell_p}$$

POLE-FACE LOSSES IN SOLID POLE GENERATORS

IN BRIEF

Pole-face losses in solid rotor generators can limit the rotational speed, the output, or both. The following article discusses the calculation of, and the design limits imposed by the pole face losses.

GENERAL STATEMENT

Paradoxically, the solid rotor machine is proposed for high speeds and high air-gap flux densities when it cannot operate at speeds or loadings comparable to those of the laminated pole generators, without the penalty of high losses in the solid pole faces.

A solid-pole Lundell generator that operates over a speed range of two to one may require de-rating at the maximum speed because of pole-face losses. This de-rating is required because of the pole face losses under load - not the no load losses.

When the wide speed range generator operates at its maximum speed, the gap density is reduced and the reduction of losses due to the reduced flux density is greater than the loss increase due to the increase in tooth ripple frequency. The result at no load is a reduction in pole face losses. At full load though, the same stator current flows and the armature mmf is the same as it was at the lower speed.

Because of the doubled slot frequency, the pole face load losses at the top speed will be of the order of 3 times as great as at the $1/2$ speed condition. The actual increase in pole face losses under load depends upon the slot opening, air gap length, ampere loading, and gap density.

SOURCE OF THE FORMULAE

T. Spooner and I. F. Kinnard "Surface Iron Losses with Reference to Laminated

Materials" Trans. AIEE, Vol. 43, 1924, pp 262-281.

The above reference points out that the following factors influence pole face losses:

1. Air gap induction B_g
2. Field form C .
3. Ratio of slot width to single air gap $\frac{b_s}{g}$
4. Tooth frequency f_t
- *5. Tooth pitch τ_s or slot pitch
6. Resistivity of material (ρ)
7. Thickness of individual laminations t
8. Hysteresis Coefficient γ
9. Insulation between laminations
10. Effect of punching

* We use different symbol than Spooner and Kinnard

In the equation -

Pole face losses = $W_S = K_1 K_2 K_3 K_4 K_5 K_6$ (Bore area), the hysteresis coefficient is not used, the interlamination resistance is assumed high, no burrs are assumed to be shorting the laminations and the effect of work-hardening is assumed to be removed by annealing.

In the paper, Spooner and Kinnard summarize that as a rough approximation, surface losses vary as:


$$(Bg)^2, (f_t)^{1.5}, \frac{b_s}{g}^{1 \text{ to } 2}, (\tau_s)^1$$

In the text of the paper, higher exponents are used and the constant K_1 is adjusted to give the required accuracy. The exponents used in the curves given in the design manuals of this report are about 30% higher than the rough approximation given by Spooner and Kinnard, and account for interlaminated currents caused by imperfect insulation.

193

DRAWN BY

READ LEFT SCALE
READ RIGHT SCALE



SOLID-POLE P. F. LOSSES

For this study, tests were made on solid-pole generators using 4130 pole steel. Tests correlated within 5% of calculated losses when the constant $K_1 = 7.0$ was used. Load losses in the pole face are calculated just as for laminated poles.

Note: If the rotor is not relieved at the leading and trailing edges of the pole, the losses will be higher than those calculated with $K_1 = 7.0$. Such a condition might exist when 316 steel or Inconel X is welded between poles and the weldment is cylindrical. In such cases, the armature reaction flux causes high losses in the interpolar area. This discussion and calculation assumes that best conditions exist.

NO-LOAD POLE FACE LOSSES

The pole face losses are a function of the stator bore area, and when the stator tooth pitch is constant, the losses are a function of the rotor diameter. They are also functions of the gap density and under load they are functions of the stator loading. Since the RPM determines the tooth ripple frequency, the P. F. losses are a function of the RPM.

The flux density and speed of a specific, solid pole generator, are limited by the amount of heat that can be dissipated from the surface of the poles so without considering the output of the generator, the effect of slot pitch and air gap density on pole face losses can be observed, while the generator operates at no-load.

With a specified air gap density and specified slot pitch, the pole face losses can be made high enough to cause the machine to fail and this can happen without load being applied. It can happen to a laminated pole or to a solid pole generator.

The no load pole face losses in a solid pole generator are of the order of six (6) times as great, for the same stator design, as those in the pole faces of a

laminated rotor. For this reason only the design limits for the solid pole generators are investigated here.

No load pole face losses are $= \text{fn} (Bg, \frac{b_s}{g}, f_t, \tau_s, C_1)$ where

Bg = air gap density, Kilolines/in²

b_s = slot opening, inches

g = air gap length, inches

f_t = tooth ripple, cycles/sec

τ_s = tooth pitch on stator, inches

C_1 = fundamental of field form (a ratio)

For most of the following discussion, the following values are assumed fixed:

$$\frac{b_s}{g} = 2.0$$

$$\tau_s = .3''$$

$$C_1 = 1.0$$

Since $\tau_s = .3$, now the number of teeth is a function of d .

$$\text{No. Teeth} = \frac{\pi d}{.3}$$

$$f_t = \frac{\pi d}{.3} \cdot \frac{\text{RPM}}{60}$$

PFL at NL = $K_1 K_2 K_3 K_4 K_5 K_6$ (Bore Area)

$$K_1 = 7.0$$

$$K_2 = \text{fn} (B_g) = .8 \text{ for } 45 \text{ Kilolines/in}^2 \text{ gap density}$$

$$K_3 = \text{fn } (f_T) 1.65 = \text{fn } \left[\frac{7d}{.3} \frac{(\text{RPM})}{60} \right]^{1.65}$$

$$K_4 = \text{fn } (\tau_s) = .175$$

$$K_5 = \text{fn } \left(\frac{b}{g} \right) = 1.45$$

$$K_6 = \text{fn } (C_1) = .22$$

$$\text{PFL at NL} = (7.0) .8 (K_3) (.175) 1.45 (.22) (\text{Bore Area})$$

$$= .313 K_3 (\text{Area}) \text{ for Bg} = 45 \text{ Kilolines/in}^2$$


$$= .235 K_3 (\text{Area}) \text{ for Bg} = 40 \text{ Kilolines/in}^2$$

$$= .11 K_3 (\text{Area}) \text{ for Bg} = 30 \text{ Kilolines/in}^2$$

$$= .039 K_3 (\text{Area}) \text{ for Bg} = 20 \text{ Kilolines/in}^2$$

| Rotor Dia. In. | RPM | No-Load Pole Face Loss in Watt/in ² $\tau_s = .3$ | | | |
|----------------------|--------|--|---------|---------|---------|
| | | Bg = 45 | Bg = 40 | Bg = 30 | Bg = 20 |
| 4 | 2,000 | .72 | .54 | .25 | .09 |
| " | 4,000 | 2.28 | 1.7 | .8 | .284 |
| " | 8,000 | 7.2 | 5.4 | 2.5 | .9 |
| " | 12,000 | 14.1 | 10.6 | 4.9 | 1.76 |
| " | 24,000 | 44 | 33 | 15.4 | 5.5 |
| " | 48,000 | 128 | 96 | 45 | 16 |
| 6 | 2,000 | 1.4 | 1.05 | .49 | .17 |
| " | 4,000 | 4.4 | 3.3 | 1.54 | .55 |
| " | 8,000 | 14 | 10.5 | 4.9 | 1.75 |
| " | 12,000 | 27 | 20.2 | 9.5 | 3.37 |
| " | 24,000 | 86 | 64.5 | 30 | 10.7 |
| " | 48,000 | 272 | 204 | 95 | 34 |


POLEFACE LOSSES IN A SOLID POLEFACE AT
 NO LOAD AS A FUNCTION OF SPEED WHEN
 THE GAP DENSITY $B_g = 45 \text{ KL/IN}^2$
 $b_g = 20$ SLOT PITCH $\tau_s = .30$



CURVE


POLE FACE LOSSES IN A SOLID POLE FACE
AT NO LOAD AS A FUNCTION OF SPEED AND
AIR GAP DENSITY FOR A 4.0 DIA. ROTOR.

$$\frac{b_s}{g} = 2.0 \quad \text{SLOT PITCH} = \tau_s = .30$$



CURVE

POLEFACE LOSSES IN A SOLID POLEFACE AT NO LOAD ¹⁹⁹
 AS A FUNCTION OF SPEED AND AIR-GAP DENSITY
 FOR A 6.0" DIA. ROTOR. $b_g = 2.0$ SLOT PITCH, $\gamma_s = .30$



DISSIPATING THE POLE FACE LOSSES

If the pole face losses are to be dissipated to gas similar to air or if the machine is force ventilated with air, the best coefficient that could be expected is 0.10 watts/in^2 of surface/ $^{\circ}\text{C}$ rise above the air. See curve from Luke and curve from A.D. Moore.

If 25 watts/in^2 is to be dissipated from the rotor surface, the temperature rise of the rotor surface in this case will be $\frac{25}{.10} = 250^{\circ}\text{C}$ above the cooling air or gas. Similarly, if 50 watts/in^2 must be dissipated, then the temperature rise of the rotor will be 500°C above the cooling air.

If room temperature cooling air can be used in sufficient quantity, 40 watts/in^2 might possibly be dissipated from the generator rotor surface. If a heat transfer coefficient of $.10 \text{ w/in}^2/^{\circ}\text{C}$ can be obtained, the rotor temperature will be approximately 800°F or 425°C .


A cooling coefficient more likely to be obtained is $.08 \text{ watts/in}^2/^{\circ}\text{C}$ and this value has been used on curve to show probable rotor temperatures associated with various no-load pole face loss levels.

EFFECT OF REDUCING GAP DENSITY

If a high-speed generator is designed and the PF losses are too great at say $45 \text{ kilolines/in}^2$ air gap density, reducing the flux density will reduce the pole-face, no-load losses by the ratio of gap densities raised to the power 2.5. The factor for gap density is K_2 .

| Bg | K_2 |
|----|-------|
| 20 | .10 |
| 25 | .18 |
| 30 | .28 |
| 40 | .6 |
| 45 | .8 |

SURFACE HEAT DISSIPATION FROM
A GENERATOR ROTOR.




AVERAGE AIR VELOCITY THROUGH
MACHINE IN THOUSANDS OF FEET
PER MINUTE.

FROM LUKE: HEATING OF RAILWAY
MOTORS. AIEE TRANS 1922 VOL 41
PP 163-173.

CURVE

WATTS DISSIPATED FROM THE ROTOR OF AN ELECTRICAL MACHINE WHEN FORCED-AIR COOLING IS USED.

FROM A.D. MOORE: FUNDAMENTALS OF ELECTRICAL DESIGN. MCGRAW HILL 1927 PAGE 134.




AVERAGE COOLING AIR VELOCITY THROUGH THE MACHINE AIR-GAP - THOUSANDS OF FEET PER MINUTE.

CURVE

NO LOAD POLE FACE LOSSES FOR A SOLID-ROTOR
GENERATOR HAVING 6.0 DIA. ROTOR AND A TOOTH
PITCH OF .3"

203

$$bs/g = 2.0$$



CURVE

EFFECT OF VARYING SLOT PITCH

When the slot pitch is varied, the pole face loss varies as the slot ripple frequency variation raised to the 1.65 power and varies as the tooth pitch variation raised to the 1.26 power. The no-load pole-face loss will decrease as the tooth or slot pitch is increased.

The net change in the loss as the slot pitch increases is approximately (ratio of slots)^{1.65} (ratio of slot pitches)^{1.26}.

In the tabulation for diameter = 4.0", $B_g = 40 \text{ Kl/in}^2$, $s = .3''$, RPM = 12000, the NLPFL = 10.6 watts/in^2 of stator bore.

If the slot pitch is increased to .6", the NLPFL will be reduced to 8.1 watts/ in^2 of stator bore area.

EFFECT OF SLOT OPENING

Completely closing the slots can have only limited effect in reducing pole face losses since the bridge closing the slot must saturate before the machine can operate. The saturated bridge represents an effective opening in the slot and the ratio $\frac{b_s}{g}$ is some definite value. In considering the effect of closing the slot with a bridge, a smaller effective opening can be assumed such as $\frac{b_s}{g} = 1.0$. The pole face loss at no load varies approximately as the ratio

$$\left(\frac{\frac{b_{s2}}{g}}{\frac{b_{s1}}{g}} \right)^{1.3} = \left(\frac{b_{s2}}{b_{s1}} \right)^{1.3}$$

So, by reducing the slot opening to 1/2 its original width, the no-load losses can be reduced to about 1/2.4 of the initial no-load value. This applies to the no load losses only and the pole-face losses under load may be much higher because of the reduced slot opening. Load losses in the pole-face are a function of the stator loading and of the slot opening to air gap ratio (b_s/g). This can be expressed as a function of b_s/g and a function of $(X_{ad})^2$.

LOAD LOSSES IN THE POLE FACE

Under load, the pole face losses are increased. This increase is due to the armature mmf wave and resulting flux wave which has a saw tooth shape.

The higher the current loading in the stator, the more pronounced the saw tooth shape of the flux wave becomes when the machine is fully loaded. This effect is a function of the ratio -

$$\left[\frac{\text{series conductors/slot} \times I_{ph} K_{sc}}{\text{no load air gap ampere turns}} \right]^2 \quad (\text{NLPFL})$$

where K_{sc} is a modifying factor describing the effect of $\frac{b}{g}$. The smaller the opening, the sharper the step or saw-tooth in the armature reaction flux wave.

E.I. Pollard treated the pole face load losses in his paper "Load Losses in Salient Pole Synchronous Machines", AIEE Trans., Vol. 54, 1935, pp 1332-1340. His work shows that if the slot opening to air gap ratio is made too small, the result may be an increase in total pole face losses. See curve

In the rotor sizes 4.0" dia. to 8.0" dia., an air gap length of .030" is reasonable to assume. If the following values are assumed:

ampere loading = 900 ampere wires per inch of stator bore periphery,
 $bs/g = 2.0$, $B_g = 40 \text{ Kl/in}^2$, then the air gap ampere turns are about 400 and from curve


$$\begin{aligned} \text{PF load losses} &= \left[\frac{K_{sc} I_{ph} N_s}{\text{AGAT}} \right]^2 \quad \text{NLPFL} \\ &= \left[\frac{1.4 (270)}{400} \right]^2 \quad \text{NLPFL} \end{aligned}$$

PF Load Losses = .91 x no load PF losses

where N_s = conductors/slot

$$I_{ph} N_s = 900 \times .3 = \text{ampere wire loading} \times \text{slot pitch}$$

LOAD LOSSES IN THE POLE FACE
 FROM E.I. POLLARD: LOAD LOSSES IN
 SALIENT POLE SYNCHRONOUS MACHINES,
 AIEE TRANS. VOL. 54 1935 PP 1332 1340.




CURVE

SOLID POLE FACE

207

POLE FACE LOSSES AT NO LOAD AND AT FULL
LOAD FOR 4.0" DIA. ROTOR AT VARIOUS GAP
DENSITIES. $A=900$ $D_s/g=2.0$ $\gamma_s=.3$



SOLID POLE FACE


208

POLE FACE LOSSES AT NO LOAD AND AT FULL LOAD
FOR 6.0" DIA. ROTOR AT VARIOUS GAP DENSITIES.

$\Delta = 900$

$b_s/g = 2.0$


$\gamma_s = 3$



CURVE

POLEFACE LOSSES AT NO LOAD AND AT FULL LOAD²⁰⁹
FOR 8.0" DIA. ROTOR AT VARIOUS GAP DENSITIES


GAP DENSITIES: $A=900$, $b_s/g=2.0$, $\gamma_s=.30$



SOLID POLE FACE


210

POLE FACE LOSSES AT NO LOAD AND AT FULL
LOAD FOR 12.0" DIA. ROTOR AT VARIOUS GAP
DENSITIES, $A=900$ $b/g=2.0$ $\gamma_s=.30$




CURVE

POLEFACE LOSSES AT NO LOAD AND AT FULL LOAD
FOR ROTORS OF VARIOUS DIAMETERS $B_g = 30 \text{ KL/IN}^2$
 $A = 900 \text{ AW/IN}$ SLOT PITCH = .4 $b_s/g = 20$



CURVE


ROTOR DIA. VS ROTOR SPEED FOR SOLID POLE FACE ALTERNATORS
 LIMITED TO 20 WATTS / IN² POLE FACE LOSSES BASED ON STATOR
 BORE AREA $B_g = 30 \text{ KL} / \text{IN}^2$ $C_1 = 2.0$ $C_2 = 1.0$



ROTOR DIAMETER, INCHES

CURVE

ROTOR DIA. VS ROTOR SPEED FOR SOLID POLE FACE ALTERNATORS LIMITED TO 20 WATTS PER SQ. INCH BASED ON THE STATOR BORE AREA. A COMPARISON OF LOSSES WHEN ONLY THE SLOT PITCH IS CHANGED. NOTE THAT WHEN THE SLOT PITCH IS INCREASED THE NO-LOAD LOSSES ARE REDUCED BUT UNDER LOAD THE TOTAL PF LOSSES INCREASE.



ROTOR DIAMETER, INCHES

CURVE

AGAT = 400 = ampere turns drop across main air gap

K_{sc} = loss factor from curve

The pole-face load losses are added to the no-load pole-face losses.

When the air gap density is decreased, the ampere turns drop across the air gap decreased in direct proportion and the pole-face load losses increase as the square of the change in gap density. For example, the factor just calculated above for a 40 Kl/in² gap density was .91 (NLPFL). When the gap density in the same machine is reduced to 30 Kl/in² but the ampere loading is maintained at 900 AW/in², the loss eqn. becomes -

$$PFL = \left[\frac{1.42 (270)}{300} \right]^2 \quad NLPFL = 1.63 \text{ (NLPFL)}$$

$$\text{or } PFL = \left(\frac{4}{3} \right)^2 (.91) \text{ NLPFL} = 1.63 \text{ (NLPFL)}$$

We have already discussed how the reduction of the air gap flux density reduces the pole face no load loss per square inch of stator bore area by

$$\left(\frac{B_{g2}}{B_{g1}} \right)^{2.5} \text{ and in the case of a reduction from } 40 \text{ Kl/in}^2 \text{ to } 30 \text{ Kl/in}^2 \text{ the reduction in NLPFL is } \left(\frac{3}{4} \right)^{2.5} = .488.$$

The full load PFL increased by $\left(\frac{4}{3} \right)^2$ or 1.78 so the total load loss was reduced from 1.0 to 1.78 (.488) = .87 a reduction of 13%.

SLOTING THE ROTOR TO REDUCE THE POLE-FACE LOSSES

Figure 1 shows graphically what happens when a solid pole-face is slotted to reduce pole face losses, when the slot approximates 50% of the pole surface.

Assuming that the air gap flux density is unity, the initial pole face density at its surface was also unity.

When the rotor was slotted to the extent that 50% of the surface was removed, the density in 1/2 the remaining surface or 1/4 of the initial surface became 1.74 times the initial value or 1.74 per unit. The surface density in the remaining 1/4 of the initial surface increased to 2 times the surface density or 2.0 per unit. The average increase in total pole face losses based upon the increase in gap density at the surface of the pole is 2.4 times. However, the increased air gap density in the region of the pole surface reduces the effect of the slot ripple and tends to reduce the load losses. These effects can nearly enough offset the effect of grooving to make the pole face losses about the same with or without grooving.


Experiments made in support of this study showed insignificant results when the rotor was grooved approximately with .020-.03 wide grooves, and only 50% of the initial surface was left.


Figure shows the results obtainable when the rotor grooving is about 10 to 12 % of the surface area. This amount of grooving does not change the rotor surface flux density a significant amount. To realize a satisfactory reduction in pole face losses, the lands formed by the grooving should be thin; .020" width is a good maximum for 400 cps generators.

To satisfy the requirement for lamination-thickness lands, and only 12% loss of surface, the grooves should be only about .0025" wide and the requirement for such an extremely narrow slot imposes a difficult manufacturing problem. Some methods that can be used to cut the narrow grooves are: diamond sawing with narrow saw or wire, electric-discharge machining with small diameter wire used as electrodes, and electron-beam machining.

DISTRIBUTION OF SURFACE FLUX
DENSITIES WHEN A ROTOR POLE HEAD
HAS 50% OF ITS SURFACE GROOVED

GAP DENSITY = 50 KL/IN^2





WITH $.025''$ LANDS AND $.005''$ SLOTTING,
 THE POLE SURFACE DENSITY IS 109%
 THAT OF A SMOOTH POLE FACE

USING SYNCHRONOUS GENERATORS AS MOTORS

INTRODUCTION

When an electric power generator is driven from a turbine in a nuclear reactor energy conversion loop, the motoring characteristics of the generator are an important consideration in the system design.

All of the nuclear reactors that are to be used in Space (The SNAP Systems) are to be started after they are in orbit or after they are outside the earth's atmosphere. This is planned to reduce the danger of atmosphere contamination in case of a launch failure. To start the reactor, or to make it go critical, the controls operate to allow the fuel assembly emission to increase and, at the same time, the coolant or working fluid is circulated to prevent the fuel assembly from overheating.

In a Brayton Cycle Conversion system, the power output turbine can be used to circulate the coolant gas or working fluid through the fuel assembly until the gas is heated and the cycle is self-sustaining.

An alternate start-up method for Brayton Cycle systems uses the release of bottled gas to introduce the working fluid into the piping and, at the same time, force the gas through the reactor where the gas is heated. In this way, the cycle is started and it becomes self sustaining. This second method must work perfectly and the reactor must heat up the first time because there is no second try.

In contrast, the turbine used as a pump can circulate the gas and allow the reactor to heat up slowly if necessary. Using the generator as a motor allows margin in the start up procedure. The margin increases the reliability of the system.

INTRODUCTION - Continued

In Rankine Cycle systems that use two liquids, one pump may be on the generator shaft or both pumps may be on the generator shaft. In either case, the generator must be operated as a motor to circulate the working fluids and prevent the fuel assembly from overheating during the start-up period.

An alternate start-up method for Rankine Cycle systems can use pumps that by-pass the turbine-generator shaft-driven pumps. This complicates the system and tends to reduce the reliability.

In either Brayton Cycle systems or Rankine Cycle systems, the motoring characteristics of the generator are of great interest.

USING SYNCHRONOUS GENERATORS AS MOTORS

IN BRIEF

Synchronous generators can be started as induction motors and operated as synchronous motors. The following discussion explains motor operation of the two types of synchronous generators; wound-pole and solid-rotor.

DISCUSSION

General


The rotating electrical generator converts mechanical energy to electrical energy. Electric motors convert electrical energy to mechanical energy. There is no basic difference in the two classes of machines as one machine can be designed to operate reversibly - as a motor or as a generator.

If the synchronous generator is used as a motor, it can operate either as a synchronous motor or as an induction motor. An induction generator can be motored only as an induction motor. The two modes of electrical motor operation are, then, synchronous and induction.

When the synchronous generator operates as a synchronous motor, it can be brought into synchronism by starting it as an induction motor until its speed is near synchronism and then applying field current to the d-c fields to accelerate the rotor to synchronous speed. It can also be started in synchronism by slowly varying the voltage and frequency from a low voltage level and low frequency to the rated values. This latter method is called a full synchronous start and throughout this kind of start, the synchronous motor can produce rated torque at rated current. Since the full synchronous start requires special supply equipment, it is not often used.

A salient-pole wound-field synchronous generator can be, and usually is, made with a pole face winding that is essentially an induction motor cage winding. This winding is called an amortisseur or damper winding. Its primary purpose

SPEED-TORQUE CHARACTERISTIC OF A
WOUND-POLE, SALIENT-POLE, SYNCHRONOUS,
GENERATOR HAVING A COPPER CAGE
WINDING. FIELD WINDINGS ARE SHORTED.
NO SKEW IN STATOR OR ROTOR



GENERATOR IS 30 KVA, .75 PF, 400 CPS,
6,000 RPM. P.U. BASE IS 22.5 KW.

in a generator is to damp out rotor oscillations and negative sequence flux waves. The same cage winding is well suited for induction motor operation and can sometimes be made as a double cage winding for higher starting torque combined with low slip.

The synchronous motor with the damper winding (or squirrel cage pole face winding) can have about the same speed-torque characteristics as an induction motor. The important difference is that the cage winding is much smaller than it would be if the motor were a normal induction motor, and the operating cycle must be short because of the small cage bars. Large synchronous motors are frequently limited to two successive starts after which a cooling period of about 30 minutes must be allowed before another start is attempted. This is in contrast to the continuous full-load operation of a normal induction motor.

Speed-Torque Characteristic of Salient-Pole Machine

The speed-torque characteristics of a 30 KVA salient-pole, synchronous generator operating as an induction motor is shown in Curve 1. This generator shows cusps in the speed torque curve that can be removed by skewing the stator one slot pitch.

Per-Unit Base

The speed-torque curves in this discussion are plotted on a per-unit scale with the generator nameplate kilowatt rating used as the 1.0 P. U. base. The 30 KVA, .75 PF machine tested has a KW rating of 22.4 KW.

$$1.0 \text{ P. U. torque is then } T = \frac{(84300) (22.5)}{6000} = 316 \text{ in. lb.}$$

$$\text{Torque in inch pounds} = \frac{84300 (\text{Kilowatts})}{\text{RPM}}$$

Such a base is meaningful. A machine designed for low power-factor loads has lower reactances than a machine designed for the same output at a high power factor. The per unit torque of a low reactance motor is higher than that of a high reactance motor.

Induction Motor Characteristics

The starting and speed-torque characteristics of an induction motor can be varied over a wide range by changing the resistance of the rotor winding. Wound-rotor induction motors are made with insulated polyphase rotor windings. These windings connect to slip rings on the shaft and variable external resistance can be added to the rotor windings. By varying these resistances, the maximum torque point on the speed-torque curve can be varied from zero speed to around 98% speed. Synchronous motors have been made with insulated, wound, pole face windings connected through slip rings to external starting resistances. Such motors are special and seldom used.

When the rotor resistance of an induction motor is changed, the speed torque characteristics curve does not change in shape. The maximum torque point and all other points shift to a new slip point. The change is proportional to the change in resistance. If the resistance of the rotor is doubled, all of the points of the speed-torque curve shift to new slip values twice that of the original. Curve 2 illustrates this change.


The characteristic curve shown for rotor resistance $R = 1$ is approximately that of a normal low-slip motor. The characteristic curve shown for $R = 4$ is for a high slip motor and could represent a torque motor.

A motor designed to give high torque against a load driving it in the reverse direction might have the characteristic shown for $R = 8$.

If a synchronous motor having a cage winding is to start under load and synchronize, it may be required to have high starting torque and low slip. A low slip motor will produce its maximum torque at 95% to 98% of synchronous speed.

To pull into synchronism, a synchronous motor must be operating at 95% speed or more when the field current is applied. The torque resulting from the attraction between the moving stator flux wave and the flux from the wound

TORQUE - SLIP CURVES OF AN INDUCTION MOTOR SHOWING THE EFFECT OF VARYING THE RESISTANCE OF THE ROTOR WINDING.



rotor pole must be sufficient to accelerate the rotor from the 95% speed to synchronous speed in one (1) revolution. If the slip is too great, (the speed too low) at the time field current is applied in an attempt to synchronize, the rotor will slip poles, the speed will decrease and the starting attempt must be discontinued before the rotor overheats. To have high starting torque, the damper or cage winding should have high resistance and the maximum speed as an induction motor may be well below 95% of synchronous speed, so that the machine cannot be synchronized. To obtain the combination of high starting torque and low slip, a double cage winding can be used in larger machines. The high slip frequency at standstill and the high reactance of the combination cage winding forces the rotor current into the top winding which has high resistance. At lower slip frequencies, the rotor current flows in the bottom cage winding also and the winding then has low resistance. This double cage winding was invented and first used by Dolivo Dobrowolsky in 1889.

Solid-Rotor Machines

If a synchronous machine has a solid pole face, a damper circuit is difficult to install and its effect is not pronounced. The characteristics of a solid-pole, Lundell generator starting at no-load, rated voltage, are shown on Curve 3.


The starting characteristics of the solid rotor are shown with and without a copper cage winding. Both rotors pulled into synchronism quickly (i.e., without hesitation or any evidence of marginal operation) without field excitation. The test curves show that the copper cage does increase torque near synchronism.


The solid rotor synchronous motor is usually impossible to synchronize under load and some designs cannot be relied upon to synchronize at no load unless special steps are taken. Such special steps may be operating at a frequency higher than rated during the start so that the terminal speed of the rotor is above rated synchronous speed, then reducing the frequency of the supply current faster than the rotor speed can drop. The rotor will then easily synchronize with the supply.

SPEED-TORQUE CHARACTERISTIC OF A TWO-COIL LUNDELL GENERATOR WITH SOLID POLE FACES.

TWO ROTORS WERE TESTED -- ONE WITH COPPER CAGE AND ONE WITHOUT.

GENERATOR RATING 30 KVA, .75 PF, 400 CPS, 8000 RPM.





Comparison of speed torque characteristics to be expected from conventional salient-pole generators with damper windings and solid-pole Lundell generators without damper windings ($X_d = 160\%$ approx.).

Another procedure that can sometimes be resorted to is to use a small induction motor having a higher synchronous speed and mounted on the same shaft as the large machine. The small machine will assist the large machine enough to drive it up to synchronous speed. Starting motors are sometimes used on large synchronous condensers where normal starting currents in the large machine would cause a severe voltage dip on the utility distribution system.

Some of the brushless generators have rotors that can easily be laminated and some do not. If the rotor speed is not too great, the homopolar inductor generator can have laminated rotors and also cage windings. The Lundell generators are difficult to make with laminated rotor poles. The heteropolar inductor cannot have a cage winding at all and we do not know how to use it as a motor. The cascade machine has its cage winding on the rotor for motor operation and on the d-c poles for generator operation.

Of the synchronous generators, the solid rotor machines can operate longest as induction motors. The losses in the solid rotor are not concentrated in small bars but are distributed well over the entire rotor surface. The heat transfer is fast and the entire rotor stores the heat. The laminated rotor with a small cage winding has its losses concentrated in the bars and heat transfer from the bars to the steel laminations is poor.

Continuous Operation

When some significant load is to be carried by a synchronous machine for any appreciable time such as 20 HP motor load on a 20 KVA generator, the machine must be in synchronism - both to carry the load and to survive for more than a few minutes (of the order of 5 minutes).

If the load and speed are both reduced enough, the generator can operate continuously as an induction motor because the rotor has some continuous load capability as an induction motor.

Rotating Rectifier Machine

The wound-pole synchronous generators with rotating rectifiers on or in the shaft have a special starting problem that usually prevents their being considered for motor duty.


When a wound-pole synchronous machine is started as a motor, the fields are shorted through a starting resistance that can be zero or some finite value. If the fields are open, the induced voltage in the field is dangerous to the field insulation. Curve 4 shows the field voltage of a 30 KVA, 6000 rpm wound-pole synchronous generator during a motor start. The fields were open circuited during one start and shorted through a 15 ohm resistor during another start. The resulting curves demonstrate that the maximum current induced was 12-1/2 amperes and that the induced voltage on open circuit was 1800 volts RMS at standstill and 300 volts RMS at 90% speed.

When rectifiers are used in the excitation supply circuit, they block on one half cycle so that the resistance presented by them is, for practical purposes, infinite. Since obtainable rectifiers cannot withstand 2000 (+) volts or even 650 (+) volts in the reverse direction, the fields must still be shorted during the start cycle and then energized to pull the machine into synchronism.

To short the fields during the start, three methods that have been tried are:

1. Short the fields by using slip rings, brushes, and a relay. Open the relay at end of induction motor start.
2. Use a centrifugal switch that shorts the fields at standstill and opens them at 90% or more or synchronous speed.
3. Use controlled diodes with the rectifier bridge and apply them in such a way that they short the motor field automatically during the start cycle.

Stationary coil, brushless machines do not have a comparable starting problem.



THE PHYSICAL DIMENSIONS OF LUNDELL-TYPE GENERATORS

IN BRIEF

For a given Lundell generator type having a given rotor diameter there is an optimum stator length and if the stator is made longer than the optimum length, the output of the machine will decrease.

The useful flux of any Lundell generator must pass through the rotor shaft. The flux-carrying capability of the shaft limits the maximum output obtainable from any given rotor diameter.


DISCUSSION

There are two arbitrary types of Lundell radial-gap generators. One type has a coil and magnetic shaft between the two sets of poles and the flux circuit is completed through the shaft into one set of poles, into the stator and out again into the other set of poles and back into the shaft section between the pole carrying flux plates. This is the type of generator used for automotive service and an adaptation of this type has a parasitic air-gap allowing it to be brushless. This general type of Lundell generator cannot practically have a shaft cross section of more than 20% of the stator bore cross section area, because of the area taken up by the poles themselves and the exciting coils.

The Lundell generators that have their flux circuits completed outboard of the pole structures can have larger magnetic sections bringing the pole flux into the pole pieces. Two of these generators are the two-coil Becky-Robinson machine and the German Lundell which completes its flux circuit in a yoke outside of the stator.

TWO-COIL LUNDELL (BECKY-ROBINSON)

In the Becky-Robinson Lundell generator, the combined shaft and rotor skirt area that can be allowed for carrying flux in or out of the rotor is approximately



FLUX CIRCUIT OF A TWO-COIL LUNDELL
OR BECKY-ROBINSON GENERATOR

30% of the total cross section area of the stator bore. This value can be considered a maximum because of the area that must be left for excitation coils.

$$\text{At } B_g = 40 \text{ Kl/in.}^2$$

and Leakage flux = 40% of total rotor flux

$$\text{Pole embrace} = .5 \text{ and } C_p = .5$$

The total shaft flux entering the rotor from the two ends combined is equal to the flux in the shaft on one end plus the flux in the skirt on one end.

$$\text{Shaft flux at } 100 \text{ kl/in}^2 \text{ density} = \frac{.3 \pi d^2}{4} (100)$$

$$\text{Total useful flux reaching stator} = \frac{.3 \pi d^2}{4} (100) \cdot 6$$

$$\text{Hypothetical total air gap flux at } 40 \text{ Kl/in}^2 \text{ gap density} = \pi d l (40)$$

$$\begin{aligned} \text{Hypothetical total air gap flux} &= \frac{.3 \pi d^2}{4} \cdot \frac{60.0}{C_p} \\ &= \frac{.3 \pi d^2 60}{4 (.5)} = 9 \pi d^2 \end{aligned}$$

$$\pi d l (40) = 9 \pi (d)^2$$

$$l = \frac{9}{40} d = .225d$$

On this basis, the KVA output of a two-coil Lundell generator of the Becky-Robinson type =

$$\text{KVA} = \frac{B_g d^2 1 (\text{RPM}) A}{90 \times 10^7} = \frac{40 (.225d^3) \text{RPM } A}{90 \times 10^7}$$

If $A = 900$ is accepted as a maximum load on the stator -

$$\text{KVA} = \frac{40 (.225d^3) \text{RPM}}{10^6} = \frac{9d^3 \text{RPM}}{10^6}$$

OUTPUT VS ROTOR DIAMETER FOR A TWO-COIL
LUNDELL GENERATOR OF BECKY-ROBINSON TYPE

$$KVA = \frac{B_g d^2 \ell (RPM) A}{90 (10^7)}$$

$$= 9 d^3 RPM (10^{-6})$$

WHERE


$$\ell = .225 d$$

$$B_g = 40 \text{ K/LIN}^2$$

$$A = 900 \text{ A WIRES}$$

KVA OUTPUT

KVA OUTPUT AT 10,000 RPM



U. S. Patent No. 2,796,542

ROTOR DIAMETER (INCHES)


282/10

$$\text{and, } d = \sqrt[3]{\frac{\text{KVA } (10^6)}{9 \text{ (RPM)}}}$$

| d | d ³ | $\frac{9 d^3 \text{ RPM}}{10^6}$ | KVA at 10, 000 RPM |
|----|-----------------|----------------------------------|--------------------|
| 3 | 27 | $207 \frac{\text{RPM}}{10^6}$ | 2.07 |
| 4 | 64 | $576 \frac{\text{RPM}}{10^6}$ | 5.76 |
| 5 | 125 | $1125 \frac{\text{RPM}}{10^6}$ | 11.25 |
| 6 | 216 | $1944 \frac{\text{RPM}}{10^6}$ | 19.44 |
| 7 | 343 | $3087 \frac{\text{RPM}}{10^6}$ | 30.87 |
| 8 | 512 | $4608 \frac{\text{RPM}}{10^6}$ | 46.08 |
| 9 | 729 | $6561 \frac{\text{N}}{10^6}$ | 65.61 |
| 10 | 10 ³ | $9000 \frac{\text{N}}{10^6}$ | 90 |

OUTSIDE-COIL LUNDELL

The Lundell generator having the coil or coils in the housing or yoke can be made with slightly larger pole areas than those of the two coil Becky-Robinson Lundells. In some cases, the total pole base area could be .4 of the bore cross-section area or $.4 \frac{\pi d^2}{4}$ (100) at 100 kl/in² density in the iron. If the leakage can be held to .4 of the flux entering the pole, the useful flux crossing



FLUX CIRCUIT OF AN OUTSIDE-COIL
LUNDELL GENERATOR

the air gap will be =

$$\phi_p \text{ across gap} = .4 \frac{\pi d^2}{4} (.6) (100) = 6 \pi d^2$$

$$\text{The hypothetical total flux in the air gap} = \phi_T = \frac{\phi_p}{C_p} = \frac{6 \pi d^2}{.5} = 12 \pi d^2$$

$$\phi_T \text{ also} = \pi d l (40) \text{ for } 40 \text{ Kl/in}^2 \text{ gap density.}$$

$$\pi d l (40) = 12 \pi d^2$$


$$l = \frac{12 d^2 \pi}{\pi d (40)} = \frac{12 d}{40} = .3 d$$

$$\text{KVA} = \frac{B_g A d^2 l \text{ RPM}}{90 \times 10^7}$$

If the ampere loading is 900 ampere wires/inch and speed is 10,000 rpm

$$\text{KVA} = \frac{40 (900) .3 d^3 (10^4)}{90 \times 10^7} = .12 d^3$$

| d | .12d ³ | = KVA at 10,000 RPM |
|---|-------------------|---------------------|
| 3 | 3.24 | 3.24 |
| 4 | 7.68 | 7.68 |
| 5 | 15 | 15 |
| 6 | 25.9 | 25.9 |
| 7 | 41.2 | 41.2 |
| 8 | 61.4 | 61.4 |



AXIAL AIR GAP LUNDELL GENERATORS

Axial air gap synchronous generators have definite design limits that allow the prediction of generator output from stator O.D. and RPM.

Discussion

When the axial air gap machine is worked to definite limits of current loading and air gap density, simply specifying the speed and the KVA output determines the diameter of the stator.

To determine the size of a specific type of generator at different speeds and ratings, a stator current loading limit and an air gap density limit should be assumed. For the determination of the size of the axial gap generators, an ampere loading of 900 ampere-conductors per inch of circumference of the stator has been used. This circumference is at the average diameter $\therefore \frac{OD + ID}{2}$. The gap density has been fixed at 40 Kl/in^2 . This density is the actual maximum of the flux wave under each pole. The equations used assume a sine wave of flux, or that the maximum fundamental of the pole flux wave is equal to the actual maximum of the flux wave. For concentric poles (square flux waves), this occurs at a pole embrace of 55%.

40 Kl/in^2 gap density and 900 amp-conductors per inch are set as the design limits.

The following discussion explains the derivation of the output equation used to determine generator sizes.

The output of a three phase generator is $\text{KVA} = \frac{I_{LL} E_{LL} \sqrt{3}}{10^3}$

The voltage is defined by -

$$E_{LL} = \frac{\phi_T (\text{RPM}) C_w N_e}{60 \times 10^5}$$

See derivation elsewhere in report.

Where ϕ_T = Hypothetical total flux in air gap in Kilolines,

$$C_w = \frac{E_{LL}}{M E_{ph}} \cdot \frac{C_1 K_d}{\sqrt{2}} = .39 C_1$$

m = No. of phases

C_1 = Ratio $\frac{\text{maximum fundamental}}{\text{actual maximum}}$ of the flux wave = 1.0 for sine wave

Ne = Total effective conductors in the machine

The basic voltage equation is substituted in the output equation.

$$KVA = E_{LL} I_L \frac{\sqrt{3}}{10^3} = \frac{\phi_T \text{ RPM } C_w \text{ Ne } I \sqrt{3}}{60 \times 10^5 \times 10^3}$$

$$\phi_T = B_{\text{Gap}} A_{\text{Gap}} \text{ and}$$

$$I = \frac{A \pi D}{\text{Ne}} \text{ where}$$

A = Ampere wire/inch loading of stator based on the average diameter of stator

$$KVA = \frac{B_g (\pi D \ell_c) \text{ RPM } (.39 C_1) \text{ Ne } \sqrt{3} A \pi D}{60 \times 10^8 \text{ Ne}}$$



$$KVA = \frac{B_g 9.85 D^2 \ell_c \text{ RPM } .39 C_1 A \sqrt{3}}{60 \times 10^8}$$

$$KVA = \frac{B_g D^2 \ell_c \text{ RPM } A}{90 \times 10^7} \text{ Basic eqn.}$$

For axial air gap machines

D = average diameter of stator

$$= \frac{OD + ID}{2}$$



For radial air gap machines

D = rotor diameter.

To allow a general treatment of the axial air gap machine, the typical design will be considered to have the following characteristics:

$$\text{Stator OD} = \frac{3}{2} \text{ stator ID}$$

$$\text{Gap density} = B_g = 40 \text{ Kl/in}^2$$

$$\text{Ampere loading} = A = 900 \frac{\text{Amp. Cond.}}{\text{in.}}$$

$$C_1 = \text{Field form factor} = 1.0 \text{ (assume sine wave)}$$

Then,

$$\text{KVA} = \frac{B_g D_{\text{avg}}^2 \ell_c \text{ RPM } A}{90 \times 10^7}$$

$$D_{\text{avg}} = \frac{\text{OD} + \frac{2}{3} \text{OD}}{2} = \frac{5}{6} \text{OD}$$

$$\ell_c = \frac{1}{6} \text{OD}$$

and,

$$\text{KVA} = 40 \frac{25}{36} (\text{OD})^2 \frac{1}{6} (\text{OD}) \frac{\text{RPM (900)}}{90 \times 10^7}$$

$$\text{KVA} = \frac{4.63 (\text{OD})^3 \text{ RPM}}{10^6}$$

$$\text{Area of stator} = .437 (\text{OD})^2$$

$$\text{Total flux} = 40 (\text{Area of stator}) = 17.5 (\text{OD})^2 \text{ Kl.}$$

$$\phi_P = \text{approx. } \frac{\phi_T}{\text{Poles}} \times .56$$

$$\phi_{\text{shaft}} = \text{approx. } \phi_T \times .27$$

When the ID of the stator is fixed at $\frac{2}{3}$ OD, the diameter which divides the stator into two equal areas is .85 OD. The average diameter is $\frac{5}{6}$ OD or .835 OD -- a 1.75% difference. This difference will be ignored and the average diameter, $\frac{5}{6}$ OD will be used as the design diameter for all calculations.

For axial air gap generators

$$\text{KVA} = \frac{4.63}{10^6} (\text{OD})^3 \text{ RPM}$$

| OD | (OD) ³ | $\times \frac{4.63}{10^6}$ | $\times 6000$ | 12000 |
|----|-------------------|----------------------------|---------------|-------|
| 3 | 27 | .125 (10 ⁻³) | .75 | 1.5 |
| 4 | 64 | .296 (10 ⁻³) | 1.77 | 3.54 |
| 5 | 125 | .58 (10 ⁻³) | 3.48 | 6.96 |
| 6 | 216 | 1.00 (10 ⁻³) | 6.00 | 12.0 |
| 7 | 343 | 1.59 (10 ⁻³) | 9.55 | 19.1 |
| 8 | 512 | 2.37 (10 ⁻³) | 14.2 | 28.4 |
| 9 | 730 | 3.38 (10 ⁻³) | 20.3 | 40.6 |
| 10 | 10 ³ | 4.63 (10 ⁻³) | 27.7 | 55.4 |
| 11 | 1330 | 6.16 (10 ⁻³) | 37.0 | 74.0 |
| 12 | 1728 | 8.0 (10 ⁻³) | 48.0 | 96.0 |
| 13 | 2197 | 10.15 (10 ⁻³) | 61.0 | 122.0 |
| 14 | 2744 | 12.7 (10 ⁻³) | 76.3 | 152.6 |

KVA for RPM Shown

| OD | 6000 | 8000 | 10, 000 | 12, 000 | 15, 000 | 20, 000 | 24, 000 |
|----|------|-------|---------|---------|---------|---------|---------|
| 3 | .75 | 1.0 | 1.25 | 1.5 | 1.88 | 2.5 | 3.0 |
| 4 | 1.77 | 2.36 | 2.95 | 3.54 | 4.42 | 5.9 | 7.08 |
| 5 | 3.48 | 4.63 | 5.8 | 6.96 | 8.7 | 11.6 | 13.92 |
| 6 | 6.00 | 8.0 | 10.0 | 12.0 | 15.0 | 20.0 | 24.0 |
| 7 | 9.55 | 12.7 | 15.9 | 19.1 | 23.9 | 31.8 | 38.2 |
| 8 | 14.2 | 18.9 | 23.6 | 28.4 | 35.5 | 47.2 | 56.8 |
| 9 | 20.3 | 27.1 | 33.8 | 40.6 | 50.7 | 67.6 | 81.2 |
| 10 | 27.7 | 36.9 | 46.2 | 55.4 | 69.2 | 92.4 | 110.8 |
| 11 | 37.0 | 49.3 | 61.7 | 74.0 | 92.5 | 123.4 | 148.0 |
| 12 | 48.0 | 64.0 | 80.0 | 96.0 | 120.0 | 160.0 | 192.0 |
| 13 | 61.0 | 81.3 | 102.0 | 122.0 | 153.0 | 204.0 | 244.0 |
| 14 | 76.3 | 101.5 | 127.0 | 152.6 | 191.0 | 254.0 | 305.2 |

ESTIMATING THE COIL WEIGHT AND I^2R LOSS

Based on 80% ratio of $\frac{\text{Field Copper Area}}{\text{Total Coil Area}}$ for field coils and a current density of 5000 amps/in², 4000 ampere turns would require one square inch of coil cross section.

Assume a square copper coil in all cases then using the coil inner diameter; d_c :

$$WT = \left[d_c + \frac{AT}{4000} \times \frac{AT}{4000} \right] . 321 \text{ lbs.} \quad (1)$$

Where d_c = coil inner dia, inches

Here the weight of coil hangers and insl. is estimated at 20% of the total.

$$\frac{I^2 R \text{ Loss}}{\text{Lb. Cu.}} = \left(\frac{\text{Amps}}{\text{In.}^2} \right)^2 \frac{\rho}{\#/\text{in}^3} = 25 \frac{(10^6)}{.321} \rho (.8)$$

Where ρ = Coil resistivity in microhm inches

at 400°F and 5000 amps/in² in CU, use Wt. obtained in equation (1) x .8

$$I^2 R \text{ Loss} = \frac{25 (1.17)}{.321} \cdot 8 \text{ (WT Coil)} = 73 \text{ (WT.) Watts} \quad (2)$$

@ 400°F (240°C)

ROTOR STRESSES

The speed and rating obtainable from a generator are functions of allowable rotor stresses.

The brushless generator rotors can be made into composite cylinders and preliminary stress treatment can be on the basis of a cylinder of homogeneous material.

Maximum stress in a homogeneous solid disk is -

$$\text{Max. } S_r = \text{MAX. } S_t = \frac{1}{8} \frac{\gamma \omega^2}{386.4} (3 + \nu) R^2$$

R = disk outside radius, inches ; ω = RAD/SEC

ν = Poisson's Ratio = .26 for steel (general approximation)

γ = density LB/in³ = .283 for steel ; N = REV/MIN

$$S = \frac{.283}{8} \frac{(2\pi)^2 N^2}{386.4 (3600)} (3.26) R^2 \quad ; S = \text{PSI}$$

$$= \frac{3.26}{10^6} N^2 R^2$$

A more realistic condition usually is represented by a cylinder with a hole in the center.

The maximum stress in a homogeneous circular disk or a cylinder with a small hole in the center is:

$$\text{Max } S_t = \frac{1}{4} \frac{\gamma W^2}{386.4} \left[(3 + \nu) R^2 + (1 - \nu) R_o^2 \right]$$

R = disk outside radius, inches

R_o = disk inside radius, inches


If R_o is small and insignificant

$$\text{Max } S_t = \frac{1}{4} \frac{\gamma W^2}{386.4} (3 + \nu) R^2 \quad \text{PSI}$$


This equation gives twice the stress calculated in a disk without a hole or -

$$S_t = \frac{6.52}{10^6} N^2 R^2$$

STRESS IN THE TUBULAR SECTION OF A TWO-COIL LUNDELL GENERATOR



STRESS IN CYLINDER HAVING A SMALL,
AXIAL, THROUGH HOLE



$$\text{MAX. } S_t = \frac{1}{4} \frac{8\omega^2}{386.4} [3.26 R^2]$$

$$S_t = 6.53 (\text{RPM})^2 R^2 10^{-6}$$

